



North Carolina Department of Natural and Cultural Resources
State Historic Preservation Office

Ramona M. Bartos, Administrator

Governor Roy Cooper
Secretary Susi H. Hamilton

Office of Archives and History
Deputy Secretary Kevin Cherry

September 24, 2018

John McDade, Cultural Resource Manager
Blue Ridge Parkway
199 Hemphill Knob Road
Asheville, NC 28803

john_mcdade@nps.gov

Re: Bluffs Coffee Shop, Doughton Park, Blue Ridge Parkway, Historic Structures Report, ER 18-1288

Dear Mr. McDade:

Thank you for the August 2018, submittal of the Bluffs Coffee Shop Historic Structure Report 95% draft by Joseph K. Opperman Architect, PA. The document is an outstanding accounting of the history and development of the building and will provide solid direction for upcoming repair and rehabilitation. We have the following comments about content and wording that we believe will document the existing historic status of the Bluffs Coffee Shop and Doughton Park complex and reconcile unclear or conflicting content. With these minor revisions, we believe the Parkway will be in good stead for ongoing planning, design, and rehabilitation at Bluffs.

Page 117 line 12 references a 2013 management plan that states that post-1955 structures “are not considered to contribute to the significance of the parkway...” Recent survey and evaluation in preparation for National Historic Landmark (NHL) designation has, in accordance with federal preservation regulation, updated the period of historic significance for the Parkway, rendering some post-1955 sites, structures, and buildings eligible for the National Register. We suggest including reference to the February 2016 Survey and Assessment report and NHL draft documents within section II.B of the report to fully account for all studies and reports that reference the Doughton complex. Also, for clarity’s sake, state in the management summary and any other relevant section that this building and complex are considered eligible and will be listed as contributing structures in the NHL district.

Page 121 line 20 references 2006 Cultural Landscapes Report recommendations related to Doughton Park. We recommend referencing this report along with other guiding policies and documents in Section II.B.

Page 30 line 1 refers to the composite shingle roof selected for the Coffee Shop as a “long-term roofing material,” while on page 123 line 26, it is identified as a “semi-long-term solution.” We have established in consultation with NPS staff that a compatible composite shingle will be sourced to replace failing concrete shingle on the Coffee Shop, and that NPS will seek to source more durable reproduction concrete shingle for other Doughton structures and other structures on the Parkway. We suggest reconciling and rewording these passages to remove doubt as to NPS’ intentions for the Coffee Shop roof. For example, it might be stated that the composite shingle roof is likely to be in place for the foreseeable future, and if resources allow, NPS will assess installation of a reproduction concrete shingle roof on the Coffee Shop.

The above comments are made pursuant to Section 106 of the National Historic Preservation Act and the Advisory Council on Historic Preservation's Regulations for Compliance with Section 106 codified at 36 CFR Part 800.

Thank you for your cooperation and consideration. If you have questions concerning the above comment, contact Renee Gledhill-Earley, environmental review coordinator, at 919-807-6579 or environmental.review@nccdr.gov. In all future communication concerning this project, please cite the above referenced tracking number.

Sincerely,



for Ramona M. Bartos

Received: 08/20/2018
State Historic Preservation Office



United States Department of the Interior



NATIONAL PARK SERVICE
Blue Ridge Parkway
199 Hemphill Knob Road
Asheville, North Carolina 28803

IN REPLY REFER

ER 18-1288

H30
PIN 80750

Due -- 9/12/18

Renee Gledhill-Earley
State Historic Preservation Office
4617 Mail Service Center
Raleigh, NC 27699-4617

H- ER letters
9/21/18
JSE

Subject: 95% Draft of the Bluffs Coffee Shop Historic Structure Report

Dear Ms. Gledhill-Earley,

The National Park Service (NPS) has contracted with Joseph K. Oppermann-Architect, P.A. (JKOA) to prepare a historic structure report (HSR) for the Bluffs Coffee Shop located on the Blue Ridge Parkway in Alleghany County, NC. Enclosed are digital and hardcopy versions of the 95% draft of the HSR. We invite your office to review and comment on the draft report. We are particularly interested in feedback regarding the proposed preservation approaches identified in the report.

Blue Ridge Parkway and NPS Southeast Regional Office staff reviewed the 75% draft of the report and are currently reviewing the 95% draft. Once approved, the NPS intends to use the document to guide rehabilitation of the structure. The NPS would also consider the document an approved treatment plan for streamlined review of eligible projects in accordance with the Programmatic Agreement.

Please send any comments on the report to me at john.mcdade@nps.gov.

Sincerely,

John McDade
Cultural Resources Manager

Attachments: CD, Hardcopy Report

Bluffs Coffee Shop

Doughton Park
Blue Ridge Parkway



HISTORIC STRUCTURE REPORT

95% DRAFT

August 2018

JKOA

JOSEPH K. OPPERMAN-ARCHITECT, P.A.

539 N. Trade Street Winston-Salem, NC 27101

Bluffs Coffee Shop

Doughton Park

Blue Ridge Parkway

Historic Structure Report

95% DRAFT

August 2018

for

Blue Ridge Parkway
Southeast Region, National Park Service

by

JKOA

JOSEPH K. OPPERMANN-ARCHITECT, P.A.

539 N. Trade Street Winston-Salem, NC 27101

www.jkoa.net | office@jkoa.net | (336)721-1711



Cultural Resources, Partnerships,
and Science Division
Southeast Region
National Park Service
100 Alabama St. SW
Atlanta, GA 30303
(404) 507-5847

The historic structure report presented here exists in two formats. A traditional, printed version is available for study at the park, at the Southeast Regional Office of the NPS (SERO), and at a variety of other repositories. For more widespread access, the historic structure report also exists in digital format through the IRMA Portal, Integrated Resource Management Applications, including the NPS Data Store, accessed at <https://irma.nps.gov/App/Reference/Welcome>, a website of the National Park Service.

DRAFT - August 2018
Historic Structure Report
Bluffs Coffee Shop
Doughton Park
Blue Ridge Parkway
(BLRI)

LCS#: Not Listed
BLRI Building No. 106

**Bluffs Coffee Shop
Doughton Park
Blue Ridge Parkway
Historic Structure Report 2018**

Approved by: _____
Superintendent, Blue Ridge Parkway Date

Recommended by: _____
Chief, Cultural Resources Partnerships & Science Division, Southeast Region Date

Recommended by: _____
Deputy Regional Director, Southeast Region Date

Approved by: _____
Regional Director, Southeast Region Date

Foreword

We are pleased to make available this historic structure report, part of our ongoing effort to provide comprehensive documentation for the historic structures and landscapes of National Park Service units in the Southeast Region. Many individuals and institutions contributed to the successful completion of this work. We would particularly like to thank the staff of Blue Ridge Parkway for their assistance throughout the process, especially Cultural Resources Manager John McDade, Highlands District Facility Manager Matt Henderson, Museum Curator Jackie Holt, and the park's Superintendent J.D. Lee. We hope that this study will prove valuable to park management in their treatment of Bluffs Coffee Shop, and to everyone in understanding and interpreting the Blue Ridge Parkway.

Dan Scheidt, Chief
Cultural Resource Partnership and Science
Southeast Regional Office
October 2018

Table of Contents

Project Team.....	iii
Management Summary	1
Administrative Data	7

Part I - Developmental History

A. Historical Background and Context.....	9
B. Chronology of Development and Use	15
Timeline	31
C. Physical Description.....	33
Construction Characteristics	38
Exterior Features.....	47
Common Interior Features	64
Interior Features Room-by-Room.....	66
Character Defining Features	107
Summary of Physical Conditions.....	109

Part II - Treatment and Use

A. Ultimate Treatment and Use.....	111
B. Requirements for Treatment and Use.....	113
C. Alternatives for Treatment and Use	119
D. Recommendations for Treatment and Use.....	121

Bibliography	125
---------------------------	------------

Appendix A

Original 1948 Construction Drawings

Appendix B

Documentation Drawings

- Site Plan
- Basement & Foundation Plan
- Main-Level Floor Plan
- Roof Plan
- Detail Drawings

Project Team

Joseph K. Oppermann–Architect, P.A. (JKOA)

Joseph K. Oppermann, FAIA, Historical Architect
Jeffrey P. Anderson, Associate AIA

National Park Service – North Major Acquisition Buying Office


Lara Wood, Contracting Officer

National Park Service – Blue Ridge Parkway (BLRI)

John McDade, Cultural Resources Manager
Matt Henderson, Distric Facility Manager, Highlands District



Red oval shows approximate location of Doughton Park within the context of the entire Blue Ridge Parkway, map courtesy of NPS.



Red oval shows location of Bluffs Coffee Shop within the larger Doughton Park recreation area, map courtesy of NPS.

Management Summary

1 This Historic Structure Report (HSR) documents
2 the development, use, and current condition of
3 Bluffs Coffee Shop at Doughton Park on the Blue
4 Ridge Parkway (BLRI). It examines options for
5 potential uses and treatments. The National Park
6 Service (NPS) will use this report to inform and
7 guide its stewardship of this historic building.

8 The report is divided into two major segments, Part
9 I: Developmental History, and Part II: Treatment
10 & Use. Part I is organized into three sections that
11 address the historical background in sequence, first
12 addressing the background and context, followed
13 by a chronology of development and use, and
14 finally a description and assessment of current
15 condition.

16 Part II: Treatment and Use is divided into four
17 sections which present the recommended “ultimate
18 treatments and uses” for the building, evaluates
19 alternatives, and reviews the requirements that
20 circumscribe them.

21 A bibliography precedes the appendices, which
22 contain the original 1948 architectural drawings,

23 as well as scaled documentation drawings of
24 the current floor, foundation, roof plan, and
25 characterizing historic details of Bluffs Coffee
26 Shop.

Historical Overview

27 Begun as part of the New Deal in 1935 and
28 completed in 1987, the Blue Ridge Parkway is a
29 recreational motorway spanning 469 miles from
30 Shenandoah National Park in Virginia to the
31 Great Smoky Mountains National Park in North
32 Carolina. The portion of the parkway containing
33 Doughton Park is Section 2C, one of the earliest
34 completed sections of the route.

35 Design parameters and context for the parkway
36 were developed by resident landscape architect
37 Stanley W. Abbott and Bureau of Public Roads
38 engineer William M. Austin. Together they worked
39 to create what has been called “a museum of
40 managed American Countryside”. The Parkway
41 seeks to present motorists with a wide variety of
42 relationships and engagement with nature.



Figure M1. Access road at MP 241 leading to site of future lodge, viewed from the median just south of Bluffs Coffee Shop site, October 1939. (BLRI Coll.)



Figure M2. Construction of stone walls and steps along parking area east of current coffee shop site, likely photographed in 1938. (BLRI Coll.)



Figure M3. Signpost for Bluffs concession area photographed in October, 1949. (BLRI Coll.)

1 Along with showcasing the natural beauty of
 2 Appalachia, the Parkway placed the development
 3 of recreation areas as a high priority since its
 4 initial planning phases. The Parkway's master
 5 plan, developed in 1934, names The Bluffs
 6 (now Doughton Park) as one of four proposed
 7 recreation areas. Others named included Natural
 8 Bridge, Peaks of Otter, and Pinnacles of Dan. These
 9 areas would offer a variety of amenities, including
 10 overnight lodging.
 11 Bluffs would be the first comprehensively-designed
 12 recreation area that would include all aspects
 13 of the planned model, including picnic areas,
 14 campground, service station, lodge, and coffee
 15 shop. Initial land acquisition and infrastructure

16 installation were completed prior to World War II,
 17 with some continuing during the War.
 18 Planning for concessions at Bluffs began in 1937,
 19 and included provisions for a service station,
 20 lodge, and coffee shop. Roadways, water supply,
 21 and parking areas were in place by the early
 22 1940s. Concessionaires initially took little interest
 23 in the project; however, as motorists on the
 24 Parkway increased exponentially after the war,
 25 the idea became much more lucrative, and initial
 26 conceptual design was underway by the mid 1940s.
 27 The architectural style employed at Bluffs Coffee
 28 Shop, service station, and later the lodge, combine
 29 the Parkway's early rustic style, including simple
 30 roof geometries, exposed framing, and natural
 31 stone, with modern, economical materials and
 32 methods. The resulting structures serve their
 33 modern purposes while maintaining a distinct,
 34 rustic character. In addition, they further the
 35 Parkway's directive of maintaining harmony
 36 between the built environment and the landscape.
 37 Bluffs' architectural approach was carried on to
 38 similar comprehensive concessions areas found
 39 at Peaks of Otter in Virginia, and Mount Pisgah in
 40 North Carolina, completed in the mid 1960s. The
 41 use of rustic materials and treatments were also
 42 adapted to the modernist design aesthetics used in
 43 Mission 66 projects on the Parkway.

Bluffs Coffee Shop

44 The coffee shop's design continued to develop
 45 throughout 1946 and 1947, with the input of
 46 Horace Peaslee, a consulting architect working
 47 on behalf of National Park Concessions, Inc.
 48 (NPC), the restaurant's initial concessionaire.
 49 The final design was completed by Charles E.
 50 Grossman, an NPS architect of the Roanoke office,
 51 as a prototypical example for the design of future
 52 Parkway concession areas. Construction took
 53 place during the fall of 1948, and the building was
 54 completed, along with the adjacent service station,
 55 in time for the 1949 tourist season.
 56 Despite attempts in the early 1980s to modernize
 57 the structure, both the interior and exterior of
 58 the coffee shop remain remarkably unchanged
 59 since its initial construction. Early photographs of
 60 the south, east, and west elevations, as well as the
 61 dining room, present the opportunity for direct

1 comparison with present-day conditions. These
 2 comparisons help to identify minor changes, many
 3 of which are undocumented, such as the reduction
 4 of the original serving counter.

5 Modifications over time are largely cosmetic in
 6 nature, and have done little to affect character-
 7 defining historical features. An emergency
 8 exit doorway was sensitively added to the east
 9 elevation in 1981 as part of life-safety renovations.
 10 The renovation also included installation of fire
 11 protection and life safety equipment, and a full
 12 replacement of the electrical system, with the
 13 exception of early dining room light fixtures.
 14 Sometime after 1981, the coverage of the hot
 15 water heating system was greatly reduced, with the
 16 majority of radiators being removed from non-
 17 public areas.

18 The original gift shop counter was slightly modified,
 19 sometime before 1997, and replaced entirely
 20 by the current casework around the year 2000.



Figure M4. Dining room of Bluffs Coffee Shop in 1952. (BLRI Coll.)



Figure M5. The dining room in 2018, note consistency with photo above (JKOA 2018)

21 Other minor changes included the re-tiling of the
 22 main-level bathrooms, and new terracotta tile
 23 flooring installed over the original terrazzo in the
 24 kitchen sometime between 1998 and 2005. In the
 25 year 2000, NPC was absorbed by Arizona-based
 26 hospitality company Forever Resorts, who assumed
 27 control of concessions at Bluffs and several other
 28 concessions on the Parkway.

29 In 2005, Bill Harrison became general manager
 30 of both Bluffs Lodge and the coffee shop. In
 31 2006, Bill oversaw the installation of a new
 32 walk-in cooler in the basement of the coffee shop,
 33 replacing the then-intact men’s locker room.
 34 A screening partition was added to the dining
 35 room at the far east end of the serving counter
 36 to conceal bus carts. Beginning in 2010, the
 37 original cement shingle roof was replaced in-kind.
 38 Completion of the project was delayed into the
 39 spring of 2011 due to durability issues with the
 40 shingles.

41 Forever Resorts declined to renew their
 42 contract with NPS after the 2010 season. The
 43 concessionaire claimed that the scale of operations
 44 at bluffs was difficult to market, and was no longer
 45 financially viable. Both the coffee shop and lodge
 46 did not operate during the 2011 season, and
 47 remain closed.

48 Unfortunately, the recently-installed cement
 49 shingle roof had failed by 2016, resulting in water
 50 infiltration and mold growth inside the building.
 51 Mold remediation efforts and hazardous material
 52 testing were carried out between September 2016
 53 and January 2017. Regrettably, the original dining
 54 room tables and chairs were discarded during
 55 this work. As part of this project, the gutters and
 56 downspouts on the south elevation were replaced
 57 in-kind, though retaining the original gutter
 58 hangers. Additionally, subsurface drains were
 59 largely replaced along the south exterior wall.
 60 Temporary 3-ply composition roofing was installed
 61 on the section of the roof above the main entrance,
 62 as well as along the ridge. Currently, installation of
 63 a composite shingle roof is planned as a mid-term
 64 solution while options are considered for restoring
 65 the roof to its original material.

66 In June 2017, the service station reopened as the
 67 Doughton Park Visitor’s Center and Park Store
 68 operated by Eastern National. This marks the first
 69 of the Bluffs concessions to be returned to active
 70 use.

Methodology

1 This HSR, which complies with NPS-28 guidelines, 48
2 offers a comprehensive, scholarly assessment of the 49
3 history, fabric, and current physical condition of 50
4 the building. 51
5 Our findings and recommendations for 52
6 preservation of the coffee shop rely on research of 53
7 primary and secondary sources, early photographs, 54
8 and maps, correlated with our physical 55
9 investigation of extant building fabric. 56
10 In accordance with the NPS provision for “limited” 57
11 historical research, we relied for the most part 58
12 on primary and secondary research conducted 59
13 in the Park archives, though additional primary 60
14 records were studied in online collections. 61
15 An interview was conducted with the former 62
16 manager of Bluffs Coffee Shop and Bluffs Lodge. 63
17 Building archaeology was critical in formulating 64
18 recommendations, and was combined with 65
19 extensive study of the original construction 66
20 drawings provided by the Park. 67
21 Our discussion of the background and context 68
22 was aided by the 2006 Cultural Landscape Report 69
23 for Doughton Park by The Jaeger Company, the 70
24 draft of the 2016 National Historic Landmark 71
25 Nomination for the Parkway prepared by NPS, as 72
26 well as correspondence and plans from the Park’s 73
27 archives. Digitized photographs from the Parkway 74
28 archive were accessed through the University of 75
29 North Carolina’s “Digital Blue Ridge Parkway” 76
30 online repository. 77
31 The firm of Joseph K. Oppermann–Architect, 78
32 P.A. (JKOA) prepared this HSR. The project team 79
33 included Joseph K. Oppermann, FAIA, historical 80
34 architect and principal-in-charge; and Jeffrey P. 81
35 Anderson, Associate AIA. This team researched, 82
36 investigated, and documented the building and 83
37 wrote this HSR. The interdisciplinary approach 84
38 broadens the understanding of the history and 85
39 conditions, aiding the development of appropriate 86
40 treatment recommendations. 87
41 An initial site visit to the coffee shop was 88
42 combined with the project kickoff meeting on 89
43 April 17, 2018. Building measurements were taken 90
44 with manual tape measures, carpenter’s ruler, 91
45 and laser distance meter. Measurements were 92
46 recorded on base field drawings traced from scans 93
47 of the original construction documents. General 94

photographic field-reference documentation was prepared using digital cameras. The resulting field drawings were used to create AutoCAD drawings of foundation, floor, roof, and site plans, as well as detailed documentation of select building features.

A two-day visit to the Blue Ridge Parkway archives took place from May 8-9, 2018. Park staff assisted with locating relevant information and providing assistance.

During a follow up visit on May 15, 2018, standard assessment methodology was used to survey the condition of each exterior feature and interior room, itemizing features and elements and photographing them in detail. Visual observation of surface conditions was used to assess the physical condition of building materials. In accordance with the NPS scope of work, no building system components were tested, and no invasive investigation methods were employed.

A third site visit was conducted on June 6, 2018 in order to gain access to previously locked spaces including the boiler room. Additional photographs and measurements were taken to record areas which had been obscured by plastic sheeting during previous visits.

Findings

75 The archival research and field investigations
76 brought a better understanding of both the
77 physical evolution of the building over time and its
78 current condition.

79 Bluffs Coffee Shop appears much as it did when it
80 was constructed in 1949. Early photographs offer
81 extensive documentation of the exterior shortly
82 after construction was completed. Character-
83 defining interior spaces such as the entryway and
84 dining room were photographed in the early 1950s,
85 and provide a near-comprehensive look at early
86 conditions. The original construction documents
87 provided by the NPS were found to be highly-
88 accurate in terms of dimensions and detailing,
89 and were used in conjunction with building
90 archaeology to assist in identifying early fabric. The
91 majority of early building fabric remains intact, and
92 most is in good or repairable condition.

93 The coffee shop is a critical component of the
94 concession area at Doughton Park, which retains

1 a remarkably-intact historic context, including
 2 original site features, sight lines, and circulation.
 3 In its current state, the building boasts many 43
 4 original character-defining features and has great 44
 5 potential for rehabilitation to once again serve its 45
 6 historic purpose. 46

47
 48
Summary of Significance 48

7 Bluffs Coffee Shop, in conjunction with the service 49
 8 station and Bluffs Lodge, represent a critical period 50
 9 in the development of recreation areas along the 51
 10 Blue Ridge Parkway. The buildings were designed 52
 11 as a prototype for future concession development, 53
 12 and are a highly-intact example of the modern- 54
 13 rustic hybrid architectural style which grew from 55
 14 the Parkway’s early rustic aesthetic and predated 56
 15 Mission 66-era modernist construction. 57

58
Recommended Treatments and 59
Uses 60
 61

16 Recommendations for treatment and use of Bluffs
 17 Coffee Shop echo the strategies outlined in the
 18 Parkway’s 2013 General Management Plan (GMP), 62
 19 its 2003 Long-Range Interpretive Plan (LRIP), and 63
 20 2016 Foundation Document, which updated the 64
 21 GMP. 65

22 *The Recommended Ultimate Treatment* 66
 23 *includes preservation of the exterior of the* 67
 24 *building and the major public interior spaces,* 68
 25 *the entrance foyer and dining room, according* 69
 26 *to its 1949 appearance, and rehabilitation of the* 70
 27 *interior ancillary spaces.* 71

28 *The Recommended Ultimate Use is a restaurant* 72
 29 *on the main level operated by a concessionaire* 73
 30 *with related ancillary uses, such as storage and* 74
 31 *office spaces, at the basement level.* 75

32 Recommended specific actions to support these 76
 33 treatments and uses include: 77

Recommendations for the Site 78

- 34 • Retain the early landscape elements 79
 35 surrounding the coffee shop complex as 80
 36 outlined in the 2006 CLR for Doughton park 81
 37 Use this document to guide site treatment. 82
- 38 • Evaluate deterioration of concrete retaining 83
 39 wall west of the coffee shop and plan for 84
 40 repair or replacement. The original stone of 85
 41 the upper portion should be retained and 85
 42 reused in the reconstruction. 86

Recommendations for Achieving Accessibility & Universal Design Standards

- The existing ramp leading to the east doorway provides a good solution for universal accessibility. The existing flagstone walkway in front of the building has curb cuts at its center, east, and west ends, making the ramp easily accessed from all parking areas. A new door jamb design without center post would provide a greater ease of access for wheelchairs.
- ADA compliant bathrooms should be designed within the footprint of the existing main level bathrooms, west of the main entrance. To accommodate the additional space required for accessibility, consider replacing the existing public bathroom designs with two, single-fixture bathrooms which would not require additional space for entry vestibules and could accommodate the turning radius of a wheelchair.

Recommendations for Historic Paints and Finishes

- Prepare an analysis of historic paints and finishes of the interior and exterior for the historic period. Include paint type and color, as well as varnishes. Interior analysis should focus on noted locations of early finishes identified in the dining room and entryway (Rooms 101A and 101B). The results of this analysis should inform the treatment of original trim, exposed structural members, and wood paneling in key public areas.

Recommendation for Exterior Siding

- Inspect underlying sheathing of areas with failed fasteners, particularly those on the east and west walls of the projecting south bay.
- Replace in-kind heavily-warped or split boards that represent a threat to the weathertightness of the building envelope.
- Monitor gaps in vertical plank board siding for insect entry through exposed sheathing boards.
- Maintain natural weathered appearance of exterior cladding as part of future repair or finishing campaigns.

Recommendations for Roofing:

- Continue planned semi-long-term solution of installing composite roofing to replace failing cement shingles and temporary 3-ply composition roofing.

1	• Plan for eventual replacement of composite	43	and replace with a more aesthetically-sensitive
2	roofing with combed cement shingle	44	solution. Rewire original recessed fixture boxes
3	matching the size and coloration of the	45	still present above most exterior doorways.
4	original cement roofing material.	46	
	Recommendations for Gutters and Downspouts	47	
5	• Install /reinstall gutters and downspouts	48	• Replace exterior lighting fixtures with an
6	on north elevation to effectively collect	49	appropriate design considering both the
7	rainwater runoff from all roof slopes,		rustic architectural styling as well as the era
8	including the rear porch.	50	in which the building was constructed.
	Recommendation for Protecting Historic	51	
	Windows	52	
9	• After conducting a comprehensive paint	53	• Replace existing asphalt tile floor in the
10	analysis, prepare and paint all elements	54	dining room and entryway, which in addition
11	of window sash and exterior casings. As	55	to be worn an incomplete, has tested positive
12	part of the preparation, remove exfoliating	56	for asbestos content. Care should be taken
13	surface rust on steel-sash windows and		to match the coloration, texture, pattern,
14	prime with a rust-inhibiting primer.	57	and dimension of the original flooring, all of
15	• Restore operation of windows in key areas,	58	which relate to the character of the space.
16	such as the dining room, by repairing or	59	
17	replacing in-kind missing or damaged	60	
18	awning sash operators.	61	
19	• Fabricate interior screen sash to allow window	62	
20	operation. Remaining screen sash hardware can	63	
21	serve as a model for replacements.	64	
22	• Consider fabricating interior thermal sash that	65	
23	could be installed during colder months and	66	
24	in the off-season to reduce drafts.	67	
	Recommendations for Exterior Doors		
25	• Restore functionality of locking mechanisms	68	
26	on all exterior doors. Original locksets should	69	
27	be retained, re-keyed, repaired, and reused.	70	
28	• Replace deteriorated two-panel paired	71	
29	screen doors on west elevation based on the	72	
30	design shown in original drawings.		
31	• Replace three non-original screen doors on	73	
32	the north elevation with doors and hardware	74	
33	modeled after extant early examples.	75	
34	• Replace deteriorated east doors and door	76	
35	frame with a design sized appropriately for the	77	
36	rough opening. Model the replacement doors	78	
37	according to existing original door designs.	79	
		80	
	Recommendations for Chimney		
38	• Clean the outside of the chimney with mild,		
39	non-ionic detergent to reduce excessive soiling	81	
40	and biocide to address biological growth.	82	
	Recommendations for Exterior Lighting		
41	• Remove existing surface-mounted electrical	83	
42	boxes, fixtures, and conduit on the exterior	84	
			Recommendations for Historic Flooring
			• Replace existing asphalt tile floor in the
			dining room and entryway, which in addition
			to be worn an incomplete, has tested positive
			for asbestos content. Care should be taken
			to match the coloration, texture, pattern,
			and dimension of the original flooring, all of
			which relate to the character of the space.
			Recommendations for Counter and Stools
			• Repair and reuse existing serving counter
			and use as a model to reconstruct missing
			sections, matching the original in appearance
			and materials.
			• Repair and reuse existing counter stools.
			Use existing stools as a model for fabricating
			missing stools. If any original stools cannot
			be repaired, retain in the Park's archive.
			• Restore original serving counter length
			and number of stools as shown in early
			photographs.
			Recommendations for Mechanical Systems
			• Install new heating and cooling systems to
			cover all major interior spaces. The designed
			system should have minimal visual impact
			on the character of the coffee shop's historic
			dining room and entryway, especially.
			Recommendations for Electrical System
			• Replace entirety of electrical system,
			including wiring, receptacles, switches and
			panels. Provide necessary service to support
			a commercial kitchen.
			• Clean, repair, and rewire existing original
			and early light fixtures in the dining room.
			Replace missing glass chimneys based on
			those in historic photographs.
			Recommendation for Plumbing System
			• Remove remnants of existing plumbing
			system and install new system.
			Fire Protection and Life Safety System
			• Remove remnants of existing fire protection
			system and install new system.

Administrative Data

Locational Data

Building Name: Bluffs Coffee Shop

Location: Milepost 241.1, Doughton Park, Laurel Springs
Blue Ridge Parkway, Highlands District

County: Alleghany County

State: North Carolina

Real Property Information

Acquisition Date: 1949 (Construction Completed)

Numbering Information

BLRI Structure No. : 106

LCS ID: Not Listed, DOE not completed

Size Information

Total Floor Area: 5,253 square feet ±

Roof Area: 3,000 square feet ±

Number of Stories: 2

Number of Rooms: 18

Number of Bathrooms: 4

Cultural Resource Data

National Register Status: Determined as eligible by 2016 NHL survey; however SHPO concurrence has not yet been sought.

Listed as contributing to proposed Blue Ridge Parkway Historic District.

Proposed Treatment

The Recommended Ultimate Treatment includes preservation of the exterior of the building and the major public interior spaces, the entrance foyer and dining room, according to its 1949 appearance, and rehabilitation of the interior ancillary spaces.

The Recommended Ultimate Use is a restaurant on the main level operated by a concessionaire with related ancillary uses, such as storage and office spaces, at the basement level.

Related NPS Studies

The Jaeger Company, *Cultural Landscape Report, Doughton Park and Sections 2A, B, and C, Blue Ridge Parkway*. Atlanta: National Park Service, 2006).

National Park Service. *Final General Management Plan /Environmental Impact Statement, Blue Ridge Parkway, Virginia and North Carolina*. Southeast Regional Office, 2013

National Park Service. *Long-term Interpretive Plan, Blue Ridge Parkway*. Blue Ridge Parkway Branch of Interpretation, Harpers Ferry Center Interpretive Planning, 2002.

National Park Service. *Foundation Document, Blue Ridge Parkway, North Carolina /Virginia*. Southeast Regional Office, 2016.

National Park Service. *Draft: National Historic Landmark Nomination, Blue Ridge Parkway Historic District*. Unpublished, 2016.

Quin, Richard and Christopher Marston. *Blue Ridge Parkway Historic American Engineering Record, HAER No. NC-42*. 1996-1997.

I.A Historical Background and Context

The Parkway

1 Blue Ridge Parkway is a unique linear park serving
2 as both a route and destination, showcasing the
3 natural beauty of the landscape and providing
4 man-made amenities for the traveler. Connecting
5 Shenandoah National Park in Virginia to the
6 Great Smoky Mountains National Park in North
7 Carolina, construction of the Parkway began under
8 the New Deal in 1935 and was completed in 1987.
9 The Parkway spans some 469 miles through the
10 Southern Appalachian Mountains, and stands
11 as a feat of landscape architecture, engineering,
12 recreation, and conservation.

13 Construction of the roadway was completed in
14 forty-five sections. Sections are identified by either
15 the number 1 for Virginia or 2 for North Carolina,

16 followed by a letter. The Bluffs, for example is part
17 of Section 2C and is among the first completed
18 sections of the Parkway (Figs. A1-A2).

Addressing the Landscape

19 Stanley W. Abbott was the resident landscape
20 architect for the development of the Parkway.
21 Abbott, in combination with Bureau of Public
22 Roads engineer William M. Austin, developed
23 design parameters to establish a context for the
24 Parkway as part of the landscape.¹ Abbott felt that
25 the Parkway should showcase the variety of the
26 landscapes throughout the two states, saying,

1. The Jaeger Company, *Cultural Landscape Report, Doughton Park and Sections 2A, B, and C, Blue Ridge Parkway* (Atlanta: National Park Service Southeast Regional Office, 2006), 2.



Figure A1. Undated photograph of the Parkway in Section 2C, near milepost 238. (BLRI Coll.)

1 The location of the road, therefore, in
2 combined woodlands, over rolling hill,
3 along small creeks, in the broader river
4 valley, as well as in varied relationship to
5 the mountains is desirable. . . Similarly,
6 it will be helpful to introduce historical
7 features and occasional pictures of the
8 native country life.²

9 The goal of Abbott's design for the Parkway
10 was to form "a museum of managed American
11 countryside."³ Part of that managed countryside
12 took the form of dedicated recreation areas along
13 the Parkway.

Developing Recreation at Bluffs

14 The area now known as Doughton Park was
15 one of the first recreation areas to be established
16 along Parkway.⁴ Called The Bluffs until 1950, the
17 Park was renamed for noted Parkway advocate
18 and North Carolina State Representative Robert
19 Doughton.⁵ The master plan for the parkway
20 developed in December 1934 names The Bluffs
21 among four original proposed recreation areas and
22 the only one in North Carolina. Listed in addition
23 to Bluffs were Natural Bridge, Peaks of Otter,

24 and Pinnacles of Dan, Virginia.⁶ Recreation areas
25 played a critical role in furthering the Parkway's
26 goal to be a scenic motorway designed for leisure.
27 Travelers would be invited to make frequent stops
28 by providing areas to rest, including overnight
29 lodging at each major recreation area.⁷

30 The appraisal and acquisition of an over 6,000 acre
31 site of The Bluffs was largely secured thanks to Sam
32 Weems, Project Manager for recreation areas and
33 later Superintendent of the Parkway, along with
34 his staff of landscape architects (*Fig. A3*).⁸ Initial
35 infrastructure was constructed by WPA and CCC
36 camps before World War II, and Conscientious
37 Objectors Camps during World War II. After the
38 war, labor was performed by force account or
39 under contract.⁹

40 By 1937, planning and provisions for concessions
41 including lodging, a restaurant, and service station
42 at Bluffs were already underway.¹⁰ A curving
43 road with stone gutter at mile post 241.1 was
44 constructed in 1938, and initially led to the parking
45 area for Wildcat Rocks Overlook (*Fig. A4*).¹¹ Later,
46 this road would also lead to Bluffs Lodge. The

2. Harley Jolley, *Painting with a Comet's Tail: The Touch of the Landscape Architect on the Blue Ridge Parkway* (Boone, NC: Appalachian Consortium Press, 1987), 12. (As cited in CLR, 17.)

3. Jaeger, *Cultural Landscape Report*, 17

4. *Ibid.*, 5.

5. *Ibid.*, 53.

6. *Ibid.*, 37.

7. *Ibid.*

8. *Ibid.*

9. *Ibid.*, 38.

10. *Ibid.*, 40.

11. *Ibid.*



Figure A2. View of Parkway under construction at milepost 240, October 1937. (BLRI Coll.)



Figure A3. Property map showing the Parkway and boundary of Bluffs Park. (BLRI Coll.)



Figure A4. Undated photo of completed access road to Wildcat Rocks Overlook. Photograph taken from the grass median between the Parkway and future coffee shop. (BLRI Coll.)

- 1 roadways for the campground at Bluffs were also
- 2 laid out around this time.¹²
- 3 By 1939, the water supply system for the recreation
- 4 development at Bluffs was in place, and consisted
- 5 of a water tank near Wildcat Rocks Overlook
- 6 connected to a pump house (Fig. A5).¹³
- 7 The roadway and parking lot portion of the
- 8 plan for the coffee shop and gas station was
- 9 implemented in 1938-1939 at milepost 241.1 (Figs
- 10 A6-A7).¹⁴ Along with the roadwork, rustic stone
- 11 retaining walls and stone steps at the edge of the
- 12 parking area were constructed leading to the
- 13 Woods Picnic Area on the slope below (Fig. A7).¹⁵
- 14 The water supply was extended to serve the new
- 15 comfort station at the picnic area between 1941
- 16 and 1942.¹⁶ As part of racial segregation planning,
- 17 this picnic area was designated for African
- 18 Americans, while the Meadow Picnic Area was
- 19 reserved for whites.¹⁷

12. *Ibid.*, 44.
 13. *Ibid.*, 41.
 14. *Ibid.*, 43.
 15. *Ibid.*, 44.
 16. *Ibid.*
 17. *Ibid.*



Figure A5. Water tank near Wildcat Rocks Overlook in October 1939. (BLRI Col.)



Figure A6. Work camp at future site of coffee shop and service station in 1941. Note roadway and stone curbs already in place. (BLRI Coll.)



Figure A7. Construction of stone retaining wall of parking area for the Woods Picnic Area, east of future coffee shop site, July 1938. (BLRI Coll.)

12 and other small structures associated with
 13 campgrounds and picnic areas. Structures of this
 14 style are characterized by their ability to adapt to
 15 their site conditions and context, as well as their
 16 use of stone, timber, and logs.

17 At Doughton, examples of pre-war rustic
 18 architecture can be found in the early trail
 19 shelter. The structure is set into a sloping grade,
 20 constructed of squared logs, and has a flagstone
 21 porch (Fig. A8). Rustic comfort stations were
 22 generally of frame construction and clad with
 23 board-and-batten siding. The comfort station at
 24 the Woods Picnic Area, northeast of the coffee
 25 shop, is a prime example of the rustic style used on
 26 this building type (Fig. A9). In addition to nearby
 27 structures, rustic elements such as stone retaining
 28 walls, stairs, picnic tables and water fountains
 29 characterize the immediate area around the coffee
 30 shop and service station.

1 By the early 1940s, the majority of the
 2 infrastructure required for the coffee shop and
 3 service station were in place; however, design
 4 would not begin until after World War II.

Rustic Pre-war Architecture

5 Developments on the Blue Ridge Parkway prior
 6 to World War II were typically of a rustic design.
 7 Three prime examples of the rustic style include
 8 the trail shelters at Rocky Knob, Cumberland
 9 Knob, and Doughton Park.¹⁸ The guiding
 10 principles of rustic architecture can be seen in
 11 the design of comfort stations, picnic shelters,

18. National Park Service, *Draft: National Historic Landmark
 Nomination, Blue Ridge Parkway Historic District*,
 (unpublished), 33-34.

An Adapted Style for the Post-War Parkway

31 The Park Service had little luck in finding
 32 interested companies to operate concessions
 33 before the war. Parkway planning had established
 34 an eventual goal that recreation areas would have
 35 facilities to provide food, gas, and in the case of
 36 larger complexes, lodging. Although this goal has
 37 yet to be realized even today, the ever-increasing
 38 motorists taking to the Parkway after the war
 39 did help to spur development. Thus, operating



Figure A8. Trail shelter at Doughton Park in the 1940s. Note that structure is partially-embeded in the slope, also note squared log construction and stone foundation walls. (BLRI Coll.)

1 concessions became a much more attractive
 2 proposition for concessionaires.¹⁹
 3 Bluffs was the first example of a comprehensive
 4 concession area including service station, coffee
 5 shop, and lodge.²⁰ The parkway initially engaged
 6 with an architecture firm to design the complex;
 7 however, as planning continued, it was decided
 8 that NPS architects would design the buildings to

19. Draft of National Historic Landmark Nomination, Blue Ridge Parkway Historic District (unpublished), 37, 38
 20. Ibid., 37.

9 serve as a model for concession developments on
 10 the Parkway.²¹

11 The final design for the coffee shop blends the
 12 character of the pre-war rustic style with modern
 13 construction methods and materials, including
 14 an economical concrete structure and steel-sash
 15 windows. Cement shingles combed to resemble
 16 wood shakes are used in the interest of economy
 17 in place of wood shakes.²² Still, influences of
 18 the pre-war period on the coffee shop design are
 19 obvious; the building is sunken into the slope of the
 20 site, uses exposed timber framing on the interior,
 21 and native stone and weathered cladding on the
 22 exterior. The hybrid design allows the building to
 23 serve its modern purpose while still addressing
 24 the original intent of buildings on the parkway, to
 25 engage and harmonize with the landscape.²³

26 Charles Grossman, NPS design architect for the
 27 coffee shop, noted the influence of rustic mountain
 28 themes in the design of the building, saying:

29 The exterior of the building reflects the
 30 architecture of the region in general
 31 proportions, roof slopes, and the materials
 32 used. The interior of the building we visualize as

21. Ibid., 37.
 22. Ibid., 38.
 23. Ibid.



Figure A9. Rustic comfort station at the Woods Picnic Area, northeast of the coffee shop site. Note board-and-batten siding and stone foundation walls. (BLRI Coll.)




Figure A10. View of Bluffs Coffee Shop from south of the parkway before 1953. (BLRI Coll.)

1 being first “functional” but it is recommended
 2 that local feeling be striven for in the coffee
 3 shop, the fountain room and most assuredly
 4 in the gift shop. This might be accomplished
 5 through the use of bead jointed chestnut
 6 boards on certain wall surfaces, together with
 7 characteristic soft grey and blue mountain
 8 colors on any plaster wall, and, of course, in
 9 the decorative fabrics of the mountain looms
 10 in hangings, table decorations, etc. Mountain
 11 handicrafts should supply furniture and casual
 12 items for decorative interest. In coffee room
 13 only it is contemplated to open the ceiling to
 14 the truss and roof framing, common practice in
 15 many native barns.²⁴

Legacy

16 The impact of the Bluffs model can be seen at
 17 similar comprehensive concession developments
 18 at Peaks of Otter in Virginia and Mount Pisgah
 19 in North Carolina, completed in 1964 and 1965,
 20 respectively. Structures in these complexes use
 21 similar techniques to blend large structures into the
 22 landscape and employ a hybrid rustic style.²⁵

23 Four other coffee shops and restaurants along the
 24 parkway include Whetstone Ridge, Otter Creek,
 25 Crabtree Falls, and Mabry Mill. Of these four, only
 26 Mabry Mill employs rustic styling, the remainder



Figure A11. Peaks of Otter Lodge embodies the same hybrid rustic style seen at Bluffs Coffee Shop and Bluffs Lodge. Photo taken October 1964. (BLRI Coll.)

27 exhibit a modernist aesthetic consistent with
 28 Mission 66-era construction.^{26, 27}

29 The concession buildings at Bluffs, including the
 30 coffee shop, lodge, and service station, remain as
 31 remarkably-intact examples of a critical period
 32 of development in both the experience and
 33 architectural character of the Blue Ridge Parkway.

26. Ibid.

27. Mission 66 was a ten-year program begun in 1955 with the goal of greatly expanding and modernizing visitor services as well as infrastructure by 1966. The program also served to commemorate the 50th anniversary of the establishment of NPS.

24. Jaeger, *Cultural Landscape Report*, 55.

25. Draft: *National Historic Landmark Nomination*, 38.

I.B Chronology of Development and Use



Figure B1. View of Bluffs Coffee Shop from the southeast in April 2018. (Photo by JKOA)

The Design Develops

1 Drawings outlining the design for the coffee shop
2 at Bluffs evolved throughout 1946 and 1947.
3 Design concepts for the coffee shop and service
4 station were initially prepared by the office of
5 Horace Peaslee, consultant architect under
6 contract with National Park Concessions, Inc.,
7 the coffee shop's initial concessionaire. A variety
8 of iterations were prepared during the summer
9 of 1946.²⁸ These concepts applied to an alternate
10 site at the east end of the parking area, considered

28. Sam P. Weems, "Superintendents Memorandum for the Regional Director", Region One, September 28, 1946., BLRI Archives Series 16, Box 89, Folder 41, 1-2.)

11 for its superior northern views (*Fig. B2*). Peaslee
12 preferred this site over the one outlined in the
13 project plan, which had been determined in the
14 initial planning period.²⁹ Peaslee felt that the
15 planned site offered little in the way of noteworthy
16 views from the dining room.³⁰ As part of the early
17 scheme, the dining room was to be a partially-
18 screened space with large outdoor dining terrace
19 (*Fig. B2*).³¹

29. Jaeger, *Cultural Landscape Report*, 40.

30. Horace Peaslee "Report to the National Park Service and National Park Concessions, Inc. on the Bluff Park Coffee Shop and Service Station", June 22, 1946, BLRI Archives Series 16, Box 89, Folder 35, 5)

31. *Ibid.*, 4.




Figure B2. Conceptual plan for Bluffs Coffee Shop on alternate site, August 1946. Existing picnic parking area visible to the west (left). The drawing is annotated with sight lines projecting north-northeast from the dining room and terrace. (BLRI Coll., PKY-BR BL-2066B, ETIC)




Figure B3. Preliminary drawings of Bluffs Coffee Shop and adjacent service station on final site, Revised March 1947. (BLRI Coll., PKY-BR BL-2047A, ETIC)



Figure B4. The coffee shop under construction in September 1948, looking northeast. Photograph by Construction photos by Superintendent Weems. (BLRI Coll.)



Figure B6. The coffee shop under construction in September 1948, looking west. The service station, appearing near completion is visible in the distance. (BLRI Coll.)



Figure B5. The coffee shop under construction in September 1948, looking east. (BLRI Coll.)

1 Although this early plan was championed for
 2 several months, the design was returned to the
 3 originally-planned site adjacent to the service
 4 station by early 1947.³² Issues of budget, combined
 5 with concerns about the alternate site's relation to
 6 the parkway likely helped to fuel this decision.³³
 7 Peaslee's involvement with the project was limited
 8 to the conceptual design phase, as it was decided
 9 that NPS architects would design the concession
 10 buildings at Bluffs to serve as an example for future
 11 developments.³⁴

12 A preliminary plan filed for review in January
 13 1947 bears striking similarity to the one eventually

32. Ralph W. Emerson, Regional Landscape Architect, Memorandum to the Superintendent, January 24, 1947, BLRI Archives Series 16, Box 90, Folder 45.

33. Various correspondence between NPS, NPC, and Peaslee regarding plan layouts at the proposed east site voice concerns regarding budget, as well as the building's relation to the Parkway. No information has been found that documents the exact date or circumstances surrounding the decision to return the design to the originally-planned site.

34. National Park Service, *Draft: National Historic Landmark Nomination*, 38.

14 built.³⁵ A revised version of this plan dated March
 15 1947 was prepared by Charles E. Grossman, an
 16 NPS architect in the Roanoke office (*Fig. B3*). Gone
 17 was the L-shaped plan and terrace, replaced with
 18 a rectangular plan with elongated dining room
 19 paralleling the parkway (*Fig. B3*).

20 Grossman continued to develop the scheme
 21 throughout late 1947. Equipment and storage
 22 layouts were provided by National Park
 23 Concessions, Inc. Much of the kitchen equipment
 24 made use of surplus obtained from Fort
 25 Washington³⁶, which was transferred to the Blue
 26 Ridge Parkway.³⁷

27 In February 1948, correspondence between the
 28 regional director and acting superintendent call
 29 for the coffee shop to operate between April 1 and
 30 December 1. The heating system and insulation
 31 were designed considering this operating
 32 schedule.³⁸ It was also noted that the employee
 33 quarters would likely house the service station
 34 attendant during the season.³⁹

35 The final construction drawings were approved on
 36 August 23, 1948; construction was underway by
 37 the following month (*Figs B4-B6*). Both the coffee

35. Ralph W. Emerson, "Regional Landscape Architect Memorandum to the Superintendent", January 24, 1947.

36. Fort Washington likely refers to Fort Washington Park in Maryland, an ex-military fort overlooking the Potomac River originally constructed in 1809 and transferred to the Department of the Interior after World War II. The Fort has been maintained as a park by the NPS since 1946. It is assumed that the surplus kitchen equipment in question was in storage there and was transferred to the Blue Ridge Parkway as the coffee shop neared completion.

37. H.S. Sanborn, "Memorandum to the Superintendent", December 7, 1947, BLRI Archives Series 16, Box 90, Folder 52.

38. J. Carlisle Crouch, "Acting Superintendent Memorandum for the Regional Director", Region 1, February 17, 1948, BLRI Archives Series 16, Box 90, Folder 53.

39. *Ibid.*



Figure B7. Photo dated 1949 showing Bluffs Coffee Shop from the southeast during its premiere season. Note cased exterior openings at the main entrance and diagonal downspouts. (BLRI Coll.)



Figure B8. Undated photo taken before September 1953 showing south and partial west elevations. Similar conditions suggest that this picture was taken at or near the same time as the photo above. Note lack of vent on west gable. Also note doors propped open within the exterior vestibule. (BLRI Coll.)



Figure B9. September 1953 photograph taken from the southwest. Attic vent, exterior screen doors, and redesigned downspouts are visible. (BLRI Coll.)

1 shop and service station opened during the 1949
2 season⁴⁰.

A Timeless Landmark

3 Today's view of Bluffs Coffee Shop from the
4 Parkway remains remarkably unchanged from
5 the one that greeted tourists in its 1949 premiere
6 season (*Figs. B1, B7*). The building's exterior and

40. *Superintendent's Annual Report to the Director, 1949, 2.*



Figure B10. Undated image showing detail of west elevation by 1953. The revised downspout design is visible at main entrance, as is the added vent. Original gate is seen open between the two buildings. Vehicle license plates read 1949 and 1950. (BLRI Coll.)

7 the surrounding site retain the vast majority of
8 original historic elements.

9 Several undated photographs capture the
10 building's original appearance. Photos taken in
11 1952 and 1953 provide comparisons to document
12 some of the earliest exterior modifications.

13 The first modification may have been the addition
14 of a louvered vent opening on the west gable end of
15 the main body (*Fig. B6*). The first dated photograph
16 showing the opening was taken in September 1953.

17 The 1949 photographs show diagonal downspouts
18 connecting the hanging wood gutters directly to
19 the underground drainage system (*Figs. B7-B8*).
20 By 1953, these downspouts had been changed to
21 a more typical elbow design shown in the original
22 drawings (*Figs. B10-B11*). The most logical reason
23 for this change, other than aesthetics, would be to
24 slow down rainwater runoff from the roof before it
25 enters the underground drainage system.

26 The final of the early exterior changes is the
27 addition of paired one-screened-light-over-one-
28 panel doors in the two outer openings of the
29 main entrance. These doors are not shown in
30 the original drawings. In 1949 photographs, it is
31 evident that the two outer "doorways" are, in fact,
32 cased openings (*Figs. B7-B8*). Photographs prove
33 that the doors were certainly in place by September
34 1953 (*Fig. B9*). Given the climate of the area, it is

Photo Comparisons: 1952 and 2018



Figure B11. The dining room in 1952, looking northeast. Note three-and-a-half bay counter with fifteen stools. Items can be seen resting on a perpendicular portion of the counter meeting the north wall. Glass gift shop cases can be seen at right. Original flood light fixtures can be seen along the left side of the ceiling beam above the counter. (BLRI Coll.)



Figure B12. The view above in 2018. Note many remaining original fixtures and finishes, including flooring, central light fixtures, counter, and bar stools. The original hood at right, though repositioned, is also present. Changes include the removal of the far east bay of the counter and stools and addition of screening partition, as well as the installation of modern gift shop cabinets at right. Early rustic-design fixtures have been added to the underside of the beams on the north and south structural bays. Modern track lighting over counter replaces flood fixtures. (JKOA)



Figure B13. View of the dining room in May 1952. Note original length of counter at right. The east side of the original gift shop is visible in the background at left. A low gate, seemingly matching that shown on original drawings, provides employee access behind the counter. (BLRI Coll.)



Figure B14. The view above in 2018. The reduction of the counter is evident at right. Modern casework has replaced the original gift shop design. The far west wall and its openings remain unchanged. (JKOA)



Figure B15. Gift Shop area photographed in 1952. Note low glass showcases with wood cabinets on the outside corners. The gift shop appears to wrap around the corner and into the entryway as outlined in the original drawings, included in *Appendix A*. (BLRI Coll.)



Figure B16. The same area in 2018. Note new wood partitions installed as part of new casework that encompass a larger footprint than the original design and limit the view of the dining room from the entryway. (JKOA)



Figure B17. Asphalt tile patch where original section of counter was removed (JKOA, 2018)

- 1 plausible that this change was made after a single
 2 winter season.
- 3 Similar to the exterior, the coffee shop's principal
 4 public space, the dining room, has also seen few
 5 changes. The earliest photographs of the interior
 6 are dated 1952, and likely represent original
 7 conditions. The following pages include three pairs
 8 of photos comparing the dining room in 1952 and
 9 2018 (Figs. B11-B16).
- 10 The most evident of the changes is the removal
 11 of the easternmost section of the counter and its
 12 stools (Figs. B11-B14). The east end of the bar was
 13 originally L-shaped, turning to meet the north wall
 14 and creating a dead end (Fig. B11). The date of the
 15 modification is unknown; however, the use of early
 16 asphalt tiles to patch the area may suggest this was
 17 an early change made to improve circulation around
 18 the counter (Fig. B17). Photographic evidence shows
 19 that the counter had been removed by 1997.
- 20 The original gift shop in the southwest portion of
 21 the dining room is clearly depicted in two 1952
 22 photographs, and appears to follow the design
 23 shown in the original drawings. The three-sided
 24 counter is largely formed by glass showcases, two
 25 on the northern face and one on the west. Built-in
 26 casework lining the south wall makes up the rear
 27 counter. Two angled wood cabinets form the
 28 outside corners, and a small swinging gate on the
 29 east end allows access to the resulting enclosed
 30 space (Figs. B15, B18).
- 31 The gift shop area was reduced by 1997, with the east
 32 end pushed back and the original cabinet and gate
 33 apparently removed (Fig. B19). A photograph shows



Figure B18. An enhanced view of the gift shop as shown in 1953 photograph. A low gate can be seen beneath the window, attached to the west end of the casework along the south wall. (BLRI Coll.)



Figure B19. A 1997 photograph showing reduced floor area of gift shop. A glass display case extends perpendicular to the south wall. Casework previously behind the counter is visible below the window at left. (Library of Congress, HAER NC,11-ASHV,V,2--106)



Figure B20. Photograph of main entrance in 1998. What appears to be an original wood corner cabinet is visible at left. (ICAP Memorandum, 1999, Roll 2, Neg. 4 1999)



Figure B21. View of coffee shop from the parkway looking northeast. (BLRI Coll.)

1 the western end of what appears to be the original
 2 counter still in place in 1998 (Fig. B20). Regardless
 3 of whether the counter depicted is the original, the
 4 original footprint of the west end of the gift shop was
 5 intact at this time. The entirety of the counter, with
 6 the exception of the casework on the south wall, was
 7 replaced by modern casework around 2000.

1980 Renovation Study

8 A study prepared for NPS in February 1980 by
 9 Lee Wan and Associates, Inc. proposes radical
 10 changes to both the Lodge and Coffee Shop,
 11 including extensive re-configuration of the historic
 12 interior.⁴¹ Although the proposed design was not
 13 implemented, the study did bring critical electrical
 14 and life safety issues to light.

15 The scope of the study was to outline repairs and
 16 improvements necessary to modernize the facility,
 17 provide handicapped accessibility, and improve
 18 life safety systems.⁴² The study also identifies the
 19 layout of both the kitchen and dining room to be
 20 inadequate and requiring redesign.⁴³

21 Utility systems were noted as being generally
 22 deteriorated and undersized, with overloaded
 23 electrical panels.⁴⁴ The original terrazzo kitchen
 24 flooring is described as deteriorated and posing
 25 sanitation problems.⁴⁵ Other issues included a lack
 26 of air conditioning, inadequate ventilation, lack of

27 insulation, and insufficient fire protection systems
 28 in the kitchen.⁴⁶

29 At the basement level, heating units were described
 30 as having “little temperature control”, suggesting
 31 that the basement radiators were still in place
 32 in 1980. The coal-fired boiler was also still in
 33 operation.⁴⁷

34 Plans prepared as part of the report propose
 35 extensive changes to the interior layout, as well as
 36 an eight-foot addition to the north, expanding the
 37 dining room and kitchen (Fig. B22).⁴⁸

38 Seven guest rooms, each with its own bathroom,
 39 were proposed for the basement level (Fig. B23).⁴⁹

1981 Renovations

40 Although the extensive redesign proposed by
 41 the 1980 study was never implemented, in May
 42 of the following year the same firm prepared
 43 recommendations to overhaul the electrical
 44 system and make life safety modifications. A set
 45 of drawings including wiring diagrams, fixture
 46 locations, and emergency exit design were filed in
 47 June 1981, and revised in August of the same year.⁵⁰
 48 Most if not all of the changes proposed appear to
 49 have been implemented, based on remaining visual
 50 evidence.

41. Lee Wan and Associates, Inc., "Renovation Study, Bluffs Lodge and Bluffs Coffee Shop", unpublished, February 1980, BLRI collection 601/D644, ETIC, 1.

42. Ibid.

43. Ibid., 3.

44. Ibid.

45. Ibid.

46. Ibid.

47. Ibid., 4.

48. Ibid., 9, Plate A.

49. Ibid., Plate A.

50. Lee Wan and Associates, Inc., "Doughton Park Lodge, Coffee Shop & Service Station, Blue Ridge Parkway, N.C., Electrical and Life Safety Renovations", June 1981, Drawings, BLRI Collection, ETIC.




Figure B22. Proposed redesign of main level of the coffee shop as outlined by the 1980 study; filled walls represent new construction; north is oriented toward the top of the page. Of note is the significant extension of the building to the north, adding space to both the dining room and kitchen at the expense of the original counter and north exterior wall. The kitchen would have been significantly increased, and new men's and women's bathrooms would consume portions of the lobby and chimney space. Interior circulation to the basement was to be removed. (Lee Wan and Associates, Inc. "Bluffs Lodge and Coffee Shop Renovation Study", February 1980, BLRI Coll., ETIC)




Figure B23. Proposed redesign of basement of the coffee shop as outlined by the 1980 study; filled walls represent new construction; north is oriented toward the top of the page. Seven guest rooms with bathrooms are created at the basement level by extending the building footprint to the north and eliminating the interior stair and western rooms. A new walkway would allow all guest rooms to be accessed from the exterior. (Lee Wan and Associates, Inc. "Bluffs Lodge and Coffee Shop Renovation Study", February 1980, BLRI Coll., ETIC)

1 Emergency work was performed to increase
 2 electrical capacity for the kitchen, and by extension
 3 the entire building. A new 800 amp main panel
 4 was installed in the kitchen, coupled with a new
 5 electrical drop and wiring to existing loads and
 6 circuits.⁵¹ Existing appliances were reconnected to
 7 new breakers in the new main panel.⁵²

8 As part of non-emergency work, all wiring,
 9 switches, and receptacles were replaced.⁵³ The
 10 electrical panel in the entryway closet was
 11 replaced, and a new ventilating fan was added to
 12 the kitchen. Smoke detectors were added at the
 13 basement level, and connected to a new alarm
 14 panel. Fire suppression systems were installed
 15 beneath the kitchen hood, and fire extinguishing
 16 and suppression devices were tested and replaced
 17 as necessary. Emergency lighting was installed
 18 in key areas, including the dining room, as were
 19 lighted exit signs.⁵⁴

20 A paired emergency exit door with ramp was added
 21 to the east elevation, at the location of the original
 22 southernmost window.⁵⁵ Plans note that the doors
 23 should match the existing front doors; however, the
 24 doors have since been replaced. (Fig. B24-25).

25 With the exception of the thirteen early rustic
 26 fixtures in the dining room, light fixtures were
 27 generally replaced. The dining room fixtures were
 28 cleaned, repaired, and re-lamped.⁵⁶ Based on this
 29 evidence, the single-lamp rustic fixtures had been
 30 added to the dining room by 1981, and were old
 31 enough to require repair. New track lights were
 32 connected to the ceiling joists above the counter,
 33 gift shop, and entryway areas. These track fixtures
 34 replaced original fixed flood light fixtures mounted
 35 on the outside of the major roof beams (Fig. B11).⁵⁷

36 The electrical plans depict the original length of the
 37 bar with L-shaped return connecting to the north
 38 wall, as well as the original configuration of the gift
 39 shop.⁵⁸ Given that these plans were likely prepared
 40 by tracing the original set, this is not definitive
 41 evidence that these elements remained in 1981.

51. Lee Wan and Associates, Inc., "Comprehensive study and Recommendations for Unsafe Electrical System Life Safety Corrections, Doughton Park Lodge, Coffee Shop/Dining Facilities, Blue Ridge Parkway", unpublished, May 1981, BLRI Collection, ETIC, 4.

52. Ibid., 7.

53. Ibid., 10.

54. Ibid., 10-11.

55. "Electrical and Life Safety Renovations", Sheet 3.

56. Ibid., Sheet 2.

57. Ibid.

58. Ibid.




Figure B24. Drawing showing design added east doorway. Note single light-over-single panel design matching that of original doors. No photographic record of these doors has been found; however, the doors currently in place are replacements, as determined by visual inspection of the frame. (BLRI Coll., Drawing No. 106-80002, ETIC)



Figure B25. Current flagstone-paved ramp, railing, and replacement steel doors. Blocking at the top of the doorway suggests the height of the original doors. (JKOA, 2018)

Later Twentieth-Century Changes

The original coal-powered boiler was replaced with a gas-powered one sometime after 1981 and before 2005 when the final manager began work.⁵⁹ Likely at the same time, the coverage of the heating system was greatly reduced. All radiators were removed from the basement level, and roughly half were removed from the main level. Supply and return pipes for the basement radiators likely remain beneath the basement floor slab, and can be seen extending through the base of the north wall of the crawl space. Though the original heating plan shows the location of the basement radiators,

59. Bill Harrison, (General Manager, Bluffs Lodge and Coffee Shop), interviewed by Jeffrey Anderson, phone interview, July 5, 2018.

1 no obvious visual evidence remains.⁶⁰ Radiators
 2 remaining on the main level are limited largely to
 3 areas occupied by the public, such as the dining
 4 room. In an interview with general manager Bill
 5 Harrison, he explains that the hot water heating
 6 system was fully drained during the off season,
 7 meaning that heat was only required for a short
 8 time each year.⁶¹ It is reasonable to assume that the
 9 original system was sized and designed for service
 10 into the winter months, if not year-round.

11 Likely during this period, the entirety of the men's
 12 and women's bathrooms and bathroom vestibules
 13 on the main level were covered with 4x4 glazed
 14 ceramic tile. The new tile likely conceals the
 15 salt-glazed tile wainscoting shown in the original
 16 drawings, as well as a radiator niche below the
 17 south window in the men's bathroom (Room
 18 107B).⁶² Terracotta tile which appears to cover
 19 the original terrazzo floors was likely installed
 20 concurrently with the wall tile. A photograph
 21 taken during a 1999 inspection by National Park
 22 Concessions, Inc. shows the current tile in place.
 23 The employee bathroom (Room 104) likely reflects
 24 the original appearance of the main bathrooms.

Forever Resorts

25 Arizona-based hospitality company Forever
 26 Resorts, a sister company of Forever Living
 27 Products, Inc., absorbed National Park
 28 Concessions, Inc. in the year 2000.⁶³ Garner
 29 Hanson, CEO of NPC was in failing health by the
 30 late 1990s, and reached out to long-time friend
 31 and CEO of Forever Living Products, Inc., Rex
 32 Maughan to assume operation NPC's properties,
 33 including Bluffs.

34 An agreement was reached that Forever would
 35 retain the current staff, consisting of about 50
 36 people between all the facilities at Bluffs.⁶⁴ Nearly
 37 all staff members had been working at the coffee
 38 shop or lodge for a decade or more. One waitress,
 39 Ellen Smith, had worked at the coffee shop since
 40 its second season in operation in 1950, and several
 41 others weren't far behind.⁶⁵

60. Heating Plan, Coffee Shop Bldg. No. 106, Drawing BL-5323A, August 1948, Sheet 1.

61. Bill Harrison, interview, July 2018.

62. Heating Plan, Coffee Shop Bldg. No. 106, Drawing BL-5323A, August 1948, Sheet 1.

63. Bill Harrison, interview, July 2018.

64. Ibid.

65. Ibid.



Figure B26. Current casework in gift shop installed in c.2000. (JKOA, 2018)



Figure B27. Original terrazzo flooring and salt-glazed tile base in kitchen in 1998. (ICAP Memorandum, 1999, Roll 2, Neg. 11, BLRI Col.)

42 Shortly after Forever stepped in as concessionaire,
 43 the current gift shop casework and shelving
 44 was installed (*Fig. B26*).⁶⁶ The new gift shop
 45 was designed to focus on the sale of dishes and
 46 decorative items, coupled with the camp store in
 47 the adjacent service station, which provided basic
 48 camping times.⁶⁷

49 At some point between 1998 and 2005, 6x6
 50 terracotta tile was installed in the kitchen and store

66. Ibid.

67. Ibid.



Figure B28. Re-roofing underway in 2010. Exposed sheathing is visible on the service station at left. (Superintendents Annual Report, 2010)

1 rooms. Based on a difference in floor height at the
 2 doorway between the kitchen and dining room,
 3 it appears that the new tile was laid on top of the
 4 original terrazzo kitchen flooring (Fig. B27).
 5 In 2003, plans for accessible bathroom addition
 6 to the rear of the building were submitted for
 7 compliance review with the Southeast Regional
 8 Office.⁶⁸ This project never came to fruition.
 9 In 2005, Bill Harrison took over as general manager
 10 of the coffee shop and lodge, a position he would
 11 hold until their closure in 2010.⁶⁹ Bill placed
 12 emphasis on modernizing and streamlining
 13 operations that had remained largely unchanged
 14 since restaurant opened.⁷⁰
 15 New equipment included a walk-in cooler
 16 installed at the basement level in 2006.⁷¹ The cooler
 17 occupies the majority of the original men's locker
 18 room (Room 005). The locker room had previously
 19 served as maintenance storage for NPS for many
 20 years; however, the original fixtures, including
 21 toilet, urinal, shower, and sink were still in place in
 22 2006.⁷²
 23 Also in 2006, a wood partition was constructed at
 24 the east end of the counter in the dining Room,

25 where the counter had previously been removed
 26 (Figs. B12, B17).⁷³ This addition served to hide the
 27 bus carts and other service items from the public
 28 view. Repairs were made to the roof in 2006, which
 29 spurred planning to replace the original roof.⁷⁴
 30 Original furniture including dining tables and
 31 chairs, as well as bar stools were carefully
 32 maintained, with upholstery being completed as
 33 necessary.⁷⁵
 34 Replacement of the original cement shingle roof
 35 began during the 2010 operating season
 36 (Fig. B28).⁷⁶ Complications involving the
 37 replacement shingles “breaking as they were being
 38 placed on the roofs” resulted in the delay of the
 39 project pending the contractor contacting the
 40 manufacturer. The project was to be resumed in
 41 spring 2011.⁷⁷

Closure

42 Forever Resorts provided a letter to the Park in
 43 August of 2010 stating that they did not wish to
 44 continue providing concessions services for the

68. *Superintendent's Annual Report*, 2003, p. 86.

69. Bill Harrison, interview, July 2018.

70. *Ibid.*

71. *Ibid.*

72. *Ibid.*

73. *Ibid.*

74. *Ibid.*

75. In his interview with the author, Bill Harrison noted that the maintaining the counter stools was an ongoing challenge, and that stools were often un-installed and reinstalled as parts became available. When reupholstering of the stools and dining chairs was necessary, great care was taken to ensure that the earlier vinyl color and pattern was closely matched.

76. *Superintendent's Annual Report*, 2010, p.30.

77. *Ibid.*

1 2011 season.⁷⁸ The concessionaire cited a lack
 2 of financial viability and difficulty marketing
 3 such small-scale locations as the main reasons
 4 for ending the contract.⁷⁹ Forever operated
 5 several concession locations in addition to those
 6 at Bluffs, including Mabry Mill, Rocky Knob
 7 Cabins, Crabtree Falls, and Price Lake. With the
 8 exception of Crabtree Falls and Bluffs Coffee
 9 Shop and Lodge, Forever Resorts properties were
 10 operated on two-year temporary contracts with
 11 new concessionaires beginning in 2011.⁸⁰ Bluffs
 12 Lodge and the Coffee Shop has remained closed
 13 and without concessionaire since the contract
 14 ended.

Post-closure

15 A substantial roof leak at the chimney combined
 16 with subsurface drainage issues in front of the
 17 building resulted in interior mold growth. In
 18 September 2016, mold remediation and roof
 19 and site drainage work began, and continued
 20 into January 2017.⁸¹ Asbestos surveying and lead
 21 paint sampling were carried out concurrently.
 22 Both mold remediation and hazardous material
 23 testing were completed by Workplace Hygiene,
 24 Inc. of Greensboro, North Carolina, who were
 25 authorized by Lightsey Corporation of Atlanta,
 26 Georgia.⁸² Both the coffee shop and service
 27 station gift shop were noted as having passed air
 28 quality testing for mold spores in a letter dated
 29 December 12, 2016.⁸³

30 As part of the project, rainwater collection and
 31 drainage systems at the front of the building were
 32 largely replaced, and portable dehumidifiers were
 33 installed in the coffee shop.⁸⁴ The underground
 34 culvert beneath the roadway was replaced,
 35 as was the perimeter drain tile that serves all
 36 but the easternmost downspout on the south
 37 elevation (*Fig. B29*).⁸⁵ The exposed portion of the



Figure B29. Drainage work in progress in November 2016. Note excavated foundation wall left of the doors. (<https://goo.gl/images/UbnngBb>)

38 foundation wall was given a waterproof coating.⁸⁶ A
 39 metal cover was fabricated to cap the catch basin in
 40 the crawl space.⁸⁷ The downspouts and aluminum-
 41 lined wood gutters on the south elevation, with the
 42 exception of the metal hangers, were also replaced
 43 as part of this work.⁸⁸

44 Many interior elements were disturbed during
 45 this time period, and likely relate to the mold
 46 cleanup efforts. The majority of light fixtures were
 47 partially or fully detached from walls and ceilings.
 48 The majority of fixture globes and diffusers were
 49 removed and stored or discarded. Glass chimneys
 50 associated with both the early and original fixtures
 51 in the dining room were removed. Switch plates
 52 and receptacle covers were removed. Bathroom
 53 stall partitions in the main bathrooms were
 54 removed. Both the main counter and rear cabinets
 55 in the dining room were lifted and set on wood
 56 blocks. The sliding doors for the rear cabinets were
 57 removed and stored.

58 Most regrettably, the original dining room tables
 59 and chairs were discarded.⁸⁹

60 Temporary three-ply composition shingles were
 61 installed on the section of roof extending above the
 62 main entrance, as well as the roof ridge in August
 63 2017.⁹⁰ Chimney flashing was also replaced as
 64 part of this project.⁹¹ Currently, a composite shake

78. Ibid.

79. Ibid.

80. *Superintendent's Annual Report on Commercial Services*, 2011, 1.

81. Henderson, Matt (District Facility Manager, Highlands District, BLRI), email correspondence with the author, July 9, 2018.

82. Dennis Forbis, "Report of Asbestos Survey and Lead Paint Sampling, Gift Shop and Coffee Shops Renovation Areas", unpublished, September 16, 2016, 1.

83. Dennis Forbis, "Mold Remediation at the Bluffs Coffee Shop and Gift Shop – Post Remediation Assessment Results – Coffee Shop Building", unpublished, December 12, 2016, 2.

84. Ibid.

85. Henderson, Matt, email correspondence with the author, July 9, 2018.

86. Ibid.

87. Ibid.

88. Ibid.

89. In his interview with the author, Bill Harrison recalls receiving a telephone call from an Allegheny county recycler in 2016, informing him that the tables and chairs from the coffee shop had been brought in.

90. Henderson, Matt, email correspondence with the author, July 9, 2018.

91. Ibid.

- 1 roof is being considered as a long-term roofing
- 2 material.⁹²
- 3 In June 2017, the adjacent service station reopened
- 4 as the Doughton Park Visitor's Center and store,
- 5 operated by Eastern National.⁹³

92. Ibid.

93. Bridgette Sturgill, "Blue Ridge Parkway opens Doughton Park Visitor Center and Park Store" mountaintimes.com, June 29, 2017.



Figure B30. Ribbon-cutting for the Doughton Park Visitors Center and Park Store, June 29, 2017. (https://www.wataugademocrat.com/mountaintimes/blue-ridge-parkway-opens-doughton-park-visitor-center-and-park/article_8a906fdf-851c-5241-a1ea-a52e58a363a0.html)

Timeline

Dec. 1934	The Master Plan for the Blue Ridge Parkway is prepared, and includes locations of planned recreational developments including the future Bluffs/Doughton Park.
1935	Construction begins on the Blue Ridge Parkway as part of the New Deal.
1937	Preliminary planning begins for future recreation area at The Bluffs, including coffee shop, lodging, and service station.
1938	Access road to Wildcat Rocks Overlook and future site of Bluffs Lodge constructed.
By 1939	Water supply including water tank and pump house are constructed for Bluffs recreation area.
1938-39	Roadway and parking lot portion of Bluffs Coffee Shop and service station completed, serving initially as parking for Picnic Area #1.
1941-42	Water supply extended to serve comfort station in Picnic Area #1.
1946-47	Design concepts are explored for both Bluffs Coffee Shop and the service station.
Mar 1947	Preliminary plan for coffee shop resembling final design is approved.
Aug 1948	Final construction drawings for the coffee shop are approved.
Sep. 1948	Construction on coffee shop underway.
1949	Bluffs Coffee Shop and the service station welcome their first customers during the operating season.
Sep. 1950	The first unit of Bluffs Lodge opens to the public.
Bef. Sep. 1953	Exterior screen-sash doors are added to the main entrance; a louvered vent was added to the west gable end of the main body; the south elevation downspouts were reworked.
1980	Renovation study prepared for extensive design modifications to coffee shop and lodge. The plan included an overhaul of the utility systems and improving life safety systems.
June 1981	Plans for electrical renovations and life safety improvements are filed. Electrical systems, including interior wiring, most fixtures, and panels were replaced at this time. The east door and ramp was added at the location of previous window. Various life safety systems were installed or upgraded.
Before 1981	Single-lamp rustic fixtures installed in north and south bays of dining room.
1981-2005	Coal-powered hot-water boiler replaced with gas-powered boiler. The coverage of the original heating system was likely reduced at this time.

Before 1997	Original gift shop layout modified at east end, removing original gate and corner casework.
Before 1997	Far eastern portion of the counter and associated stools removed.
Before 1998	Original salt-glazed tile wainscoting in men and women's bathrooms on the main level covered with floor-to-ceiling ceramic tile. Terracotta tile flooring was likely installed simultaneously.
1998-2005	Original terrazzo flooring in kitchen covered with terracotta tile, with matching tile installed in the adjacent stair hall and store room.
2000	Forever Resorts replaces National Park Concessions, Inc. as concessionaire.
c.2000	New cabinets and shelves installed in gift shop. Original casework on south wall of dining room and east wall of entryway remain.
2003	Plans for addition containing ADA accessible restrooms submitted to SERO for approval. The project never came to fruition.
2005	Bill Harrison replaces Bill Oliver as general manager of Bluffs Coffee Shop and Bluffs Lodge.
2006	Partition screening wall constructed at east end of counter in dining room.
2006	Walk-in cooler installed in former men's locker room.
2006	Roof leaks repaired around chimney and at ridge.
2006	Cultural Landscape Report on Doughton Park
2010-2011	Replacement of original cement shingle roof.
Aug 2010	Forever Resorts states intent to end concessionaire services at the Parkway.
Oct 2010	Bluffs Coffee Shop and Lodge close at the end of the 2010 operating season.
Sep. '16-Jan. '17	Mold remediation and hazardous material testing performed. The original dining room tables and chairs were likely discarded at this time. Drainage system in front of the building was largely replaced, including wood gutters, downspouts, drain tile, and culvert beneath the roadway. A cover was installed on the collection basin in the crawlspace.
Aug 2017	Temporary composition shingle roof installed on ridge and western portion of south roof slope.
June 2017	Service station reopens as Doughton Park Visitors' Center and store.
2018	Historic Structure Report.

I.C Physical Description



Figure C1. Bluffs Coffee Shop (right) and service station visitor's center (left) viewed from the southeast, across the Blue Ridge Parkway. Unless otherwise stated, all photos in this section were taken by JKOA in 2018.

General Description

Doughton Park

1 Part of the Parkway's Highlands District, Doughton
2 Park, originally known as Bluffs Park, offered one
3 of the first recreation areas along the Parkway.
4 Concentrated in the northern portion of Doughton
5 Park near milepost 241, the recreation area at
6 Doughton included a coffee shop, service station,
7 two-building lodge, and two picnic areas by 1950.
8 Just east of coffee shop site, between mileposts 239
9 and 240, is Doughton Park Campground.
10 The coffee shop sits about 120 feet from the
11 Parkway, and is readily visible by passing motorists.
12 An access road parallels the Parkway and provides
13 convenient access to both the coffee shop and
14 adjacent gift shop and visitors center (*Fig. C.1*).

15 Parking areas to the east and west serve both
16 buildings.

17 Across the Parkway to the south, a loop road leads
18 to the nearby Bluffs Lodge and current Doughton
19 Park picnic area. Immediately northeast of the
20 coffee shop is a picnic area with its c.1942 comfort
21 station and stone picnic tables.

Climate

22 Robert Hellmann's 2005 Archeological
23 Investigations conducted at the Blue Ridge
24 Parkway describe the climate at Doughton Park as
25 follows:

"According to data provided by the Southeast Regional Climate Center, average maximum temperatures in January are 43.0° F and a minimum of 22.1° F. The highest temperatures

are recorded in July with a maximum high of 80.1° F and a minimum of 56.9° F. The highest and lowest averages of total precipitation are recorded in March at 5.38 inches, and December at 3.85 inches. Total rainfall, however, is relatively even throughout the year with a total annual average of 55.20 inches. The highest average of snowfall is recorded in January at 7.9 inches. The total average of snowfall is 23.6 inches per year.”⁹¹

Bluffs Coffee Shop Site

1 The coffee shop sits about 120 feet off the parkway,
 2 near the northern boundary of Doughton Park.
 3 The approximately six acre site includes the coffee
 4 shop, former service station, two parking lots to the
 5 east and west of the complex, and a picnic area to
 6 the northeast (Figs. C2-C3).

7 The coffee shop and service station are built into
 8 a substantial slope, allowing a full height walk-out
 9 basement at the rear of both buildings. A nearly
 10 30’-0” wide loop road parallels the Parkway and
 11 accommodates two-way traffic as well as parallel
 12 parking spaces along its southern curb
 13 (Fig. C3). A mowed grassy median separates the
 14 access road from the Parkway. Parallel parking
 15 spaces are close by, along the southern edge of
 16 the access road. Parking lots provide additional
 17 parking. Stone steps at the eastern lot lead to the
 18 picnic area below.

19 Pedestrian walkways surrounding the coffee shop
 20 are paved with mortared flagstone. Stone curbing
 21 borders the edges of the roadway (Figs. C4-C5).
 22 Two wood barrier rails measuring about 12’-0”
 23 long are placed at the north curb, flanking the
 24 entry doors (Fig. C4).

25 A collection basin is along the south curb of the
 26 loop road, opposite the main entrance of the coffee
 27 shop. Parking lot rainwater runoff is collected
 28 here and carried by underground pipe through the
 29 crawl space and finally discharges to grade a short
 30 distance north of the building.

31 A poured concrete-paved service area measuring
 32 about 20’-0” east-west and 22’-6” in the north-
 33 south direction separates the coffee shop from
 34 the service station (Figs. C6-C7). The area is
 35 retained on its north side by a stone and concrete
 36 wall measuring 2’-3” thick (Figs. C8-C9). A pair



Figure C2. Parking area east of the coffee shop, note low stone walls and stairs to Woods Picnic Area at right.



Figure C3. Loop road viewed from west parking area.



Figure C4. Flagstone walkways and wood barriers.

37 of board-and-batten gates along the south end
 38 of the service area measure 13’-0” wide overall;
 39 the eastern leaf is sized for pedestrian use, while
 40 the other is considerably larger to accommodate
 41 vehicular access. East and west gate posts measure
 42 6x6 and 4x6, respectively. A section of horizontal
 43 wood rail fencing spans between the east gate post

91. Robert Hellmann. *Archeological Investigations Conducted at the Blue Ridge Parkway: Doughton Park, North Carolina*. (Southeast Archeological Center, 2002), 11. (As cited in Jaeger, *Cultural Landscape Report*).



Figure C5. Storm water collection basin, note asphalt patch from recent drainage repair.



Figure C8. Concrete retaining wall and stone railing. Note heavy deterioration of concrete due to moisture.



Figure C6. Service area viewed from the south. Coffee shop at right, service station at left.



Figure C7. Service area looking northeast.



Figure C9. Hand-operated winch on north retaining wall.

- 1 and the west elevation of the coffee shop. A 2'-3"
- 2 thick stone wall extends from the service station to
- 3 the western gate post, completing the barrier
- 4 (Fig. C6). The larger gate has a wheel-guide and
- 5 metal rod keeper secured in the concrete paving.



Figure C10. Concrete exterior stair.

1 A hand-operated winch mounted on the top of the
 2 stone wall was likely used to bring refuse from the
 3 lower level of both the service station and coffee
 4 shop (Fig. C9).
 5 A poured-in-place concrete exterior stair descends
 6 eastward from the service area along the north
 7 elevation of the coffee shop. The stair measures
 8 4'-0" wide with ten 9 ½" treads and eleven 8 ½"
 9 tall risers. A pipe railing along the outside edge
 10 measures 1 ¾" in diameter (Fig. C10). A large
 11 propane tank sits on a concrete pad near the base
 12 of the stairs (Fig. C11).

Bluffs Coffee Shop - Architecture

Architectural Description

13 *The coffee shop faces south-southeast, for the purposes*
 14 *of this report, the building is said to face south.*

15 Bluffs Coffee Shop is a two-story building built
 16 into a steeply-sloped site, resulting in a walk-
 17 out basement at the rear and at-grade access to
 18 the main level at the front (Figs. C12-C15). The
 19 building's massing can be divided into an eastern
 20 main body and a western wing. Both portions of
 21 the building are side gabled. The western bay of
 22 the main body extends toward the parkway, giving
 23 prominence to the main entrance and introducing
 24 a second, shallower roof slope (Figs. C12, C14).



Figure C11. Propane tank at base of exterior stair.



Figure C12. South elevation.



Figure C13. East Elevation.



Figure C14. West Elevation.



Figure C15. North elevation.

- 1 The smaller wing to the west recedes to match the
2 depth of the adjacent service station building, but
3 matches the roof slope of the main body.
- 4 The main level is accessed from grade on the south
5 side, while most basement areas are accessed from
6 the exterior at the rear, or north side. The concrete
7 walls of the lower level are exposed on the north
8 and east elevations, where grade drops away. A shed-
9 roofed covering protects the exterior walkway that
10 accesses the basement level rooms (*Fig. C15*).
- 11 The upper level of the main body uses a timber
12 frame, supported by concrete beams, engaged
13 columns, and poured-in-place concrete walls at the
14 basement level (*Fig. C15*). The western wing has
15 CMU exterior walls and a wood-framed roof.
- 16 Exterior cladding includes horizontal
17 weatherboard, vertical wood siding, and local
18 stone masonry. The roof is clad primarily in
19 cement shingles; however asphalt shingles have
20 recently been installed on the roof slope above the
21 entrance and across the ridge of the main body.
22 A rectangular interior chimney with stone veneer
23 extends from the roof, roughly-centered on the
24 main entrance (*Figs. C12-C15*).
- 25 There are three window designs; the first and most
26 prevalent are three-light steel awning windows; the

1 second are two-light steel awning windows, and
2 the third are six-light wood hopper-type windows.
3 Exterior doors consist of wood sash doors at the
4 main entrance, and nine-light over two-vertical-
5 panel sash doors at all other locations, with the
6 exception of the east exterior doors which are
7 flush-panel steel sash doors.

8 The main body holds the main public spaces,
9 as well as the main kitchen, while the wing and
10 basement hold mostly support spaces. Most spaces
11 on the basement level can be accessed by exterior
12 doorways along the north elevation. The southern
13 half of the basement beneath the main body is a
14 partially-excavated crawl space. The first-floor
15 plan measures approximately 3,411 square feet.
16 The basement plan measures about 1,842 square
17 feet, not including the crawl space.

Architectural Style

18 The building is a unique coupling of rustic
19 vernacular architecture with a modern aesthetic
20 reflecting the era in which it was built. Vernacular
21 roof forms and the use of stone and naturally-
22 weathered wood connect the building to the rustic
23 heritage of earlier structures along the Parkway.
24 On the interior, this rustic theme is carried
25 through the use of exposed timber framing and
26 wood paneling throughout the dining room and
27 gift shop areas. The extension of the timber frame
28 to the exterior in the form of a projecting hood at
29 the east gable end gives the structure a barn-like
30 quality.

31 More modern are the design and arrangement of
32 window openings; which transition from a more
33 traditional punched opening with six-light wood
34 sash windows at the western end, to a decidedly
35 modern steel-sash ribbon window at the eastern
36 end. The use of steel windows continues across
37 the north and east elevations. The design of the
38 windows places an emphasis on horizontality, an
39 idea typically associated with modernism.

Construction Characteristics

Structural System

Foundation and Footings

40 The foundation consists of poured-in-place
41 concrete walls and columns with concrete masonry
42 unit (CMU) infill walls (*Fig. C16*). A poured-
43 in-place floor slab is consistent throughout the
44 majority of the basement level, with the exception

45 of the crawl space, which has a dirt floor and is
46 largely occupied by a stone outcropping.

Floor Framing

47 A poured-in-place concrete floor slab measuring
48 approximately 6" thick is consistent throughout the
49 first floor.

50 Concrete beams running in the north-south
51 direction measure 1'-0" wide by 1'-4" deep and
52 are spaced according to the structural bays of the
53 timber-framed main body of the building. On the
54 north exterior wall, these beams bear on engaged
55 concrete columns measuring about 1'-0" by 1'-0"
56 square (*Fig. C17*).

57 At the center and southern bearing points, the
58 beams rest on a poured-in place concrete wall.
59 The edges of the beams are chamfered; in all but
60 Room 001, the beam spacing corresponds with the
61 placement of basement partition walls (*Fig. C17*).



Figure C16. Typical concrete foundation walls.



Figure C17. Engaged concrete column (left) and concrete beam in Room 001.

1 Two freestanding columns at the western end of
 2 the crawl space, matching the dimensions of those
 3 in the north wall, provide bearing points for posts
 4 at the southeast corner of the kitchen (Room 102)
 5 and between the two main bathroom vestibules
 6 (Rooms 106A and 107A) (Fig. C18).

Wall Framing

Basement - Exterior Walls

7 With the exception of the north wall, exterior
 8 basement walls are poured-in-place concrete and
 9 measure 10" thick.

10 Beginning at the west wall of the refuse room (Room
 11 007) and moving east, the north exterior wall is
 12 constructed of CMU infill panels measuring 8"
 13 thick between the concrete columns described in
 14 the previous section. A concrete header, formed as
 15 part of the floor slab above, extends about 2" from
 16 in the face of the interior wall, resulting in an overall
 17 thickness of about 10" by about 1'-0" tall (Fig. C19).

Basement - Interior Walls

18 Basement level interior walls are generally of CMU
 19 construction; however, a poured-in-place concrete
 20 wall measuring 8" thick separates rooms on the
 21 northern half of the building from the crawl space
 22 on the southern half. The east wall of Rooms 006
 23 and 007, and the north wall of Room 008 are also
 24 of poured-in-place concrete construction. CMU
 25 walls dividing the three living quarters and locker
 26 rooms (Rooms 001-005) measure 6" thick. The wall
 27 between the boiler room (Room 006) and the coal
 28 bunker (Room 008) measures 8" thick.

Main Level - Exterior Walls

29 Three different wall systems are used on the main
 30 level. Stone walls on the south elevation measure
 31 approximately 1'-6" thick (Fig. C20). CMU walls
 32 measuring 4" thick line the walls of the men's and
 33 women's bathrooms and bathroom vestibules on
 34 the main level (Rooms 106 A and B, and Rooms
 35 107A and B). Based on the original drawings, the



Figure C18. Concrete column in crawl space. CMU column to immediate left is not structural.



Figure C20. Stone exterior wall on south elevation, note depth at window opening.



Figure C19. CMU infill section on north basement wall. Note concrete header above window and doorway, and concrete beams at left and right.



Figure C21. Termination point of stone exterior wall at eastern end of south dining room windows. Wood-framed exterior wall at right.



Figure C22. Exterior wall framing at west wall of extending southern bay.

- 1 base of these walls has salt-glazed structural tile
- 2 wainscoting to a height of 4'-0". The presence
- 3 of this wainscoting has not been verified, as it is
- 4 currently concealed by ceramic tile.
- 5 Stone walls measuring about 1'-4" thick on the
- 6 south face of the dining room (Room 101A) have
- 7 interior furring walls, likely of 2x4 construction.
- 8 Wood-framed walls with likely 2x4 studs are typical
- 9 on the north and east walls of the dining room (Room
- 10 101A). The east and west walls of the projecting
- 11 southern bay have 2x4 studs spaced at 16" on center.
- 12 Diagonal sheathing measures 5" wide (Fig. C22).
- 13 CMU walls measuring 8" thick are typical on
- 14 the north exterior wall, beginning at the kitchen
- 15 (Room 102) and moving west. Wood furring on
- 16 the exterior provides a nailing surface for wood
- 17 exterior siding. This wall system is common on the
- 18 entirety of the west wing.

Main Level - Interior Walls

- 19 The majority of the interior walls at the main
- 20 level are constructed of CMU. Rooms with tile
- 21 wainscoting have a hybrid wall of salt-glazed tile
- 22 and CMU construction.

Ceiling and Roof Framing

Main Body

- 23 The roof framing of the main body is a braced
- 24 timber frame that is fully exposed in the dining
- 25 room and entry (Rooms 101A and 101B), and
- 26 partially exposed in the kitchen (Room 102)
- 27 (Figs. C23-C28).
- 28 The roof framing is divided into seven bays by
- 29 trusses running north-south. Each truss typically

30 has four 8" by 8" chamfered posts that form 3 bays

31 running east-west; however, the truss between the

32 fifth and sixth bays from the east has no southern

33 post due to the entry door placement, and instead

34 relies on two 10" by 10" posts at trusses 5 and 7

35 to carry a larger beam across the entryway (Fig.

36 C24). The posts along both the north and east walls

37 are embedded within the exterior wall framing

38 (Fig. C25). Each post rests on a concrete plinth

39 measuring about 6" tall.

40 Truss spacing, moving from east to west, measures

41 9'-2", 13'-1", 12'-11", 13'-0", 11'-1", 10'-3", and

42 11'-6" on center. From north to south, posts

43 measure 7'-8" on center off both the north and

44 south walls, and 12'-8" on center in the central

45 aisle.

46 Chamfered diagonal braces at the top of each post

47 generally measure 4x6 (Fig. C25). Beams running

48 in the east west direction measure about 8x8. The

49 major beams of the center aisle have an additional



Figure C23. Overview of timber framing in Room 101A, looking west.



Figure C24. Larger 10x10 post and increased-depth beam spanning main entrance.

1 member measuring approximately 6x8 that runs
 2 beneath the main beam at each post, and appear
 3 to be connected with wood keys (Fig. C26). Beams
 4 along the north and south walls and have lap joints
 5 at each truss, some of which appear to be tied by
 6 a steel plate (Fig. C25). The beams running north-
 7 south, over the two side aisles, measures about 6x6.

8 The timber frame above Room 102 lacks diagonal
 9 braces below the ceiling level, and instead uses
 10 steel angle plates. Metal straps connect the beam
 11 running east-west across the center of the ceiling.
 12 The majority of the trusses above are concealed
 13 within the attic level (Figs. C27-C28).

14 Rafters measure 4x6, spaced at 24" on center and
 15 are lapped at the two major beams. Ceiling joists
 16 above the kitchen are 2x10s, spaced at 16" on
 17 center, running north-south (Fig. C29). The ridge
 18 beam appears be a 2x10.

19 Fiberboard insulation is continuous between the
 20 roof decking and the rafters, and is exposed on
 21 the interior (Figs. C26, C28). Tongue-and-groove
 22 decking boards measure 4 7/8" wide by about 1"
 23 thick and are exposed at the eaves (Fig. C31).

West Wing

24 Rafters above the west wing are 2x8s, spaced
 25 at 16" on center. Rafter tails measuring 4x6 are
 26 sistered to the ends of the rafters. The ridge beam
 27 measures 2x10. Ceiling joists are 2x4s spaced at 16"
 28 on center. Every third joist is sistered at its center



Figure C25. Typical chamfered bracket and embedded timber post on north wall. Note lap joint at top of post.



Figure C26. Typical beam at main center aisle post. Arrow indicates a wood key. Note exposed rafters.



Figure C27. Metal plates and ties at ceiling beam in Room 102.



Figure C28. Timber frame extending into attic above Room 102.



Figure C29. Roof framing above Room 102.



Figure C30. Roof framing of west wing.



Figure C32. Hot-water boiler in Room 006.



Figure C31. Typical roof decking at eave.



Figure C33. Typical boiler pump.

- 1 and has a 2x4 vertical member extending to the
- 2 ridge, connected to what are likely 2x8 collar ties.
- 3 Decking boards match those of the main body, and
- 4 are exposed at the eaves (Figs. C30-C31).

Utility Systems

Heating and Cooling

- 5 A Lochinvar model CBL0645 boiler provides
- 6 hot water for the heating system and is located in
- 7 Room 006 (Fig. C32).
- 8 Five boiler pumps are connected the various
- 9 branches of the hot water piping extending from
- 10 the boiler. Each is a Bell & Gossett ITT Industries
- 11 model 8-A56A117D57E (Fig. C33).
- 12 Wall-mounted radiators with fan are mounted in
- 13 the northeast and southeast corners of the dining
- 14 room (Room 101A), and the northwest corner
- 15 of the entryway (Room 101B). Floor-mounted
- 16 radiators are used in the storage room (Room
- 17 105A) and women's bathroom (Room 106B) (Figs.
- 18 C34-C36).



Figure C34. Typical wall-mounted unit in Room 101A



Figure C35. Floor-mounted radiator in Room 105A.



Figure C36. Floor-mounted radiator in Room 106B.

- 1 The building has no cooling system; relying instead
- 2 on operable awning windows for ventilation.

Electrical System

- 3 Electric service enters the building on the north
- 4 roof slope, above the north exterior wall of the
- 5 kitchen (Room 102). An 800 amperes electrical
- 6 panel is mounted on the north wall of the kitchen,
- 7 between the two window openings (Figs. C37-C38).
- 8 A secondary 225 amperes electrical panel in
- 9 the west closet in the entryway (Room 101B) is
- 10 connected to the panel in the kitchen (Fig. C39).
- 11 Another panel is mounted on the west wall of the
- 12 refuse room (Room 007), and appears to have
- 13 served kitchen equipment and likely basement
- 14 walk-in cooler (Fig. C40).
- 15 What appears to be a large junction box is mounted
- 16 in the northwest corner of the boiler room (Room
- 17 006) (Fig. C41).
- 18 An attic fan on the west gable end of the main body
- 19 of the building is controlled by a thermostat in the
- 20 attic. The fan is mounted behind an opening with
- 21 operable metal louvers (Fig. C42).



Figure C37. Weatherheads on north roof slope.



Figure C38. Main electrical panel on north wall of Room 102.



Figure C39. Electrical panel in closet of Room 101B.



Figure C40. Electrical panel on west wall of Room 007.



Figure C42. Electric attic ventilation fan. Note thermostat at left.



Figure C43. Example of typical surface-mounted receptacle.



Figure C41. Junction box in Room 006.

1 The majority of receptacles and switches on the
 2 first floor are mounted in recessed boxes. Most if
 3 not all receptacle and switch cover plates have been
 4 removed as part of the mold remediation efforts.
 5 Receptacles and switches at the basement level are
 6 typically surface-mounted, as are some likely later
 7 additions on the first-floor (Fig. C43).

8 The majority of interior and exterior lighting
 9 fixtures appear to be replacements installed as
 10 part of the 1981 electrical work. Examples of early
 11 fixtures can be found in the dining room entryway,
 12 and vestibule (Rooms 101A, 101B, and 108). Other
 13 fixtures throughout the building are utilitarian in
 14 nature. More detailed descriptions of fixtures can
 15 be found in the *Interior Features Room-by-Room*
 16 section.

Plumbing System

17 Plumbing throughout the building reflects multiple
 18 generations of improvised modifications. Pipes
 19 vary between earlier galvanized supply lines and
 20 cast-iron drains to more modern copper and both
 21 rigid and flexible PVC supply lines.

22 The majority of the plumbing for the main level is
 23 exposed on the basement ceiling. The haphazard
 24 nature of the work suggests that little planning was
 25 involved in making modifications to the system. In



Figure C44. Electric hot water heater in Room 000.



Figure C45. Electric hot water heater in Room 006.

1 several cases, multiple different types of pipe are
 2 used in a single line, such as PEX tubing being used
 3 in conjunction with copper and galvanized lines.

4 The building has three hot water heaters, one in
 5 the crawl space (Room 000), and two in the boiler
 6 room (Room 006).

7 A State Industries Inc. brand electric hot water
 8 heater, model number P6402DRS is near the north
 9 wall of Room 000 (*Fig. C44*).

10 An eighty-gallon Bradford-White electric hot water
 11 heater, model MI80R6DS13, is near the north wall
 12 of Room 006 (*Fig. C45*).

13 An indirect hot water heater, model RJA100-6837
 14 is in the southwest corner of Room 006. The tank
 15 is connected to the hot water heating system and
 16 reportedly provided domestic hot water to the
 17 kitchen (*Fig. C46*).

18 At the basement level, the women's locker room and
 19 coal bunker no. 2 (Rooms 004 and 011, respectively)
 20 contain lavatories; Room 004 also has a toilet.

21 On the main level, the kitchen (Room102) has a
 22 three-basin stainless steel sink and a wall-mounted



Figure C46. Indirect hot water heater connected to boiler in Room 006.

1 lavatory. The employee toilet (Room 104) contains
2 a toilet and wall-mounted lavatory. The storage
3 room (Room 105A) has a two-basin stainless steel
4 sink and a wall-mounted janitor's sink. The men's
5 bathroom vestibule (Room 107A) contains a wall-
6 mounted lavatory, and the adjacent men's bathroom
7 (Room 107B) has a toilet and floor-mounted urinal.
8 The women's bathroom (Room 106B) contains two
9 wall-mounted lavatories and two toilets.

10 Photographs of fixtures can be found in the
11 *Interior features Room-by-Room* section.

Fire Detection and Life Safety

12 The majority of the current fire detection and
13 emergency lighting system was initially installed
14 as part of the 1981 electrical upgrades, though
15 the system has seen later modifications. Wired
16 smoke detectors are placed throughout both
17 levels. The majority of smoke detectors have been
18 detached from walls and ceilings and are hanging
19 by wires (*Fig. C47*). Emergency lights are spaced
20 throughout most circulation spaces, including
21 along the north exterior walkway, as well as the
22 dining room (*Fig. C50*). Fire alarm beacons are
23 found in the dining room as well as beneath the
24 rear porch roof (*Fig. C48*). One pull station was
25 noted near the north exterior doorway leading to
26 Room 009 (*Fig. C49*).

27 Fire extinguishers and hoses have been removed
28 from their cases. A fire extinguisher in the kitchen
29 (Room 102) is connected to a fire suppression system
30 beneath the ventilation hood (*Figs. C51-C52*).

Telecommunications

31 A telephone interface box is mounted on the
32 north elevation, near the base of the exterior
33 stair (*Fig. C53*). No other evidence of telephone
34 equipment was noted.



Figure C48. Fire alarm beacon, in this case on the north elevation beneath the porch.



Figure C49. Fire alarm pull station on north elevation near doorway to Room 009.



Figure C47. Typical wired smoke detector, detached from fixture box.



Figure C50. Typical emergency lighting fixture.



Figure C51. Empty fire extinguisher cabinet on north elevation.



Figure C53. Telephone network interface box at west end of north elevation.



Figure C52. Remaining fire extinguisher near vent hood in Room 102.



Figure C54. Honeywell alarm system panel in Room 006.

Exterior Features

Foundation Walls

- 6 With the exception of stone portions of the south
- 7 elevation, the perimeter concrete foundation walls
- 8 are exposed around the entire building footprint.
- 9 The CMU infill sections of the north exterior wall
- 10 are barely discernible, as joints are pointed flush
- 11 with the face of the unit. Seams are visible where
- 12 the concrete columns supporting the first floor
- 13 framing intersect the wall (*Fig. C55*). All exposed
- 14 portions of the foundation walls are painted
- 15 blue-grey.

Siding, Stonework, and Trim

Alarm System

- 1 A Honeywell-branded alarm system panel is
- 2 mounted on the west wall of the boiler room
- 3 (Room 006), and is labeled as being serviced by
- 4 "Secure South". No other security equipment was
- 5 observed (*Fig. C54*).

- 16 Stone walls on the south elevation are described as
- 17 being constructed of local stone, and are made up of
- 18 roughly-squared rectangular blocks laid in courses.
- 19 Pointing has no defined profile, with most joints
- 20 measuring about ½" and 1" wide. Stone coloration
- 21 varies, with most being a dark greyish-blue



Figure C55. Foundation wall on north elevation. Note seam for concrete header and floor slab (left), and seam for concrete column (right).



Figure C56. Coloration and pattern of stone exterior walls.

- 1 color with some lighter grey and brown stones
- 2 interspersed. White horizontal banding is common
- 3 on many of the stones (*Fig. C56*).
- 4 Exterior cladding varies between two siding types;
- 5 all siding has a largely-homogenous, naturally-
- 6 weathered appearance.
- 7 The entirety of the north elevation, the majority
- 8 of the east elevation, the east and west side walls
- 9 of the south projection, the west gable end of the
- 10 western wing, as well as the easternmost portion
- 11 of the south elevation are clad with vertical plank
- 12 board siding (*Figs. C57-C61*). Board widths include
- 13 $6\frac{3}{4}$ " $7\frac{1}{2}$ ", $8\frac{1}{4}$ ", 9 ", $10\frac{7}{8}$ ", $12\frac{1}{2}$ " and $13\frac{1}{4}$ ", applied
- 14 in no particular pattern. On the east elevation, the
- 15 seam above the window openings has a beveled
- 16 detail to protect the end grain (*Fig. C59*). The siding
- 17 has shrunk significantly, resulting in gaps varying
- 18 typically between $\frac{1}{4}$ " and $\frac{1}{2}$ ", exposing the diagonal
- 19 tongue-and-groove sheathing and building felt
- 20 beneath (*Fig. C58*). In many areas, nails have popped
- 21 and stand proud of the siding surface, suggesting a
- 22 possible failed substrate (*Figs. C59-C61*).
- 23 The south and western faces of the west wing, as
- 24 well as the upper portion of the east gable end are
- 25 clad with horizontal weatherboard measuring $\frac{3}{4}$ "
- 26 thick with an 8 " exposure and mitered corners
- 27 (*Fig. C62*). While the boards do overlap, they do



Figure C57. Vertical plank board siding at southeast corner.




Figure C58. Typical shrinkage cracks, note diagonal sheathing visible between boards.



Figure C59. Detail of siding at top of window and door openings on east elevation. Note popped nails.



Figure C62. Horizontal weatherboard on west wing.



Figure C60. Recently-replaced siding on west gable end of main body. Note warped board; also note popped nails.



Figure C63. Louvered vent on west gable end of wing.



Figure C61. Recently-replaced siding on east wall of projecting south bay. Note popped nails.

1 not appear to be tapered. On the west gable end
 2 of the wing, this siding is used to form a large
 3 louvered gable vent by angling the boards outward
 4 to form approximately 1 1/4" wide spaces for
 5 ventilation (*Fig. C63*).

6 Fascia boards on the south elevation are 2x4s with
 7 the top edge beveled to follow the slope of the roof
 8 and fit beneath the outside edge of the roof decking
 9 boards. Rake boards measure 4 3/4" wide by 7/8"
 10 thick (*Fig. C64*). The eastern portion of the south
 11 elevation above the ribbon windows has no fascia
 12 board. The north elevation also has no fascia board.

Windows

13 The majority of window sash are of similar
 14 steel construction and operate as awning-type



Figure C64. Facia and rake boards.



Figure C66. Ribbon windows on south elevation. Note awning sash operation.

1 casement windows. The most prevalent window
 2 configuration is a three-horizontal-light steel-sash
 3 awning window, consisting of a two-light operable
 4 awning sash above a third, fixed-light. All windows
 5 appear to be original to the building and are
 6 painted blue-grey (Figs. C65-C66).

7 Window openings of this design on the main level
 8 measure 4'-1" wide by 4'-1" tall. The awning sash
 9 measures 4'-0" wide by 2'-7 1/2" tall by 1 1/2" thick; the
 10 lower fixed sash measures 4'-1" wide by 1'-6" tall.
 11 Stiles and rails of the operable sash measure 1 1/4"
 12 wide and are made up 1/16" thick angle steel (Figs
 13 C66, C72). Sloped wood sills measure 2 1/2" thick at
 14 the inside edge and taper to 1 3/4" thick at their front
 15 face; these sills are typical of most window openings
 16 on the main level (Fig. C68). On the southern ribbon
 17 windows, a stone subsill measures 4 1/2" to 5" thick,
 18 and a wood peg detail connects the wood sill near
 19 the center (Figs. C67-C68). Side casings on this large
 20 opening measure 6" wide by 1 5/8" thick; the head

21 casing measures 10 1/4" wide (Fig. C70). In all other
 22 locations, typical window casings measure 3 1/2"
 23 wide by 1 5/8" thick (Fig. C65). All casing are lintel
 24 cut.

25 Awning operators double as window props, and
 26 consist of a pivoting piece of rectangular stock that
 27 rests on brackets mounted on the lock rail. The
 28 prop swings outward to be perpendicular to the
 29 sash, unlocking it, and is pushed through a slot in
 30 the stationary lock rail. At full extension, the sash
 31 is held open at an approximately 30-degree angle.
 32 The prop has a round loop handle that remains on
 33 the interior to pull the sash closed (Fig. C71). When
 34 opened, the top of the sash slides along a track in
 35 the window jamb, and two non-articulating hinges
 36 brace the window sash as the bottom rail moves
 37 outward (Fig. C72). Brackets remain on several
 38 windows for fixed interior screen panels, all of
 39 which have unfortunately been removed since the
 40 restaurant's closure.



Figure C65. Examples of two-over-one-light awnings-sash windows on east elevation.



Figure C67. Projecting stone stubsill below south ribbon windows.



Figure C68. Example of typical sloped sill. Note wood peg connecting sill near center of ribbon windows.



Figure C70. Plank board casing on ribbon window opening.



Figure C69. Typical window mullion.



Figure C71. Typical prop-type awning operator.

- 1 The majority of the windows of this three-light
- 2 design are paired, or in the case of the south
- 3 elevation, assembled in a curtain-wall type
- 4 configuration. Each mullion measures 3" wide and
- 5 is covered with a steel strap with exposed screw
- 6 fasteners (*Figs. C68-C69*).
- 7 The second window type on the main level is a
- 8 two-light steel awning-type casement window,



Figure C72. Detail of awning hinge and profile of sash frame.



Figure C73. Paired two-light awning sash at west end of north elevation.



Figure C75. Typical screen and casing detail. Note rusted lintel at top right.

1 similar in dimension of the first, but lacking the
 2 lower fixed light. The only instance of this window
 3 type is a paired opening on the north elevation
 4 shared between Rooms 103 and 105. Each
 5 measures 3'-5" wide by 2'-9" tall (Fig. C73). These
 6 windows share the same prop-rod style operation
 7 described previously, though the hardware has
 8 been removed. Interior screens on these windows
 9 have also been removed.

10 The third main-level window type is a six-light
 11 wood-sash hopper window measuring 2'-8" wide
 12 by 2'-5" tall by 1 1/8" thick (Fig. C74). The wood
 13 sill is sloped, measuring 3" thick at the inside edge
 14 and tapering to 1 3/4" thick at the front face. A piece
 15 of molded wood stop trim at the base of the sash
 16 holds the base of the sash in place when opened
 17 (Fig. C76). Stone subsills matching the coloration
 18 of the surrounding stone walls are common on the
 19 three examples of this window used in masonry
 20 walls and measures 4 1/2" to 5" thick with a gentle



Figure C76. Detail of sill and wood stop trim at base of sash.



Figure C74. Typical six-light hopper-sash window.

21 slope, extending about 2" from the face of the
 22 stone wall (Fig. C74). Each opening has a wood
 23 exterior screen sash measuring 2'-8" wide by 2'-6"
 24 tall, with 1 1/2" wide side rails, 2 1/4" wide bottom
 25 rail, and 1 3/4" top rail. Half-round trim measuring
 26 3/4" wide holds the metal screen mesh in place. The
 27 screen sash is mounted at the top by two surface-
 28 mounted hanging brackets (Fig. C75). On the
 29 interior, a loop-pull cabinet latch holds the sash
 30 in place at the top; when opened, the sash rests
 31 on chains. Exterior casings on examples found in
 32 stone walls measure 3" wide by 1 5/8" thick and are
 33 lintel-cut; while those on the south elevation of the
 34 west wing are the typical 3 1/2" wide by 1 5/8" thick
 35 found elsewhere. Steel lintels support the masonry
 36 opening at the CMU interior portion of the
 37 exterior wall system on examples of this window
 38 type set into masonry walls (Fig. C75).

39 Two window types are used at the basement
 40 level, and are similar in design to the steel awning

1 windows of the main level. The first is a three-
 2 horizontal-light window with two-light awning
 3 sash and fixed third lower light measuring 3'-5"
 4 wide by 4'-1" tall overall. Sloped concrete sills
 5 measure the width of the window opening by 5 ½"
 6 thick, extending 1 ½" from the face of the concrete
 7 exterior wall (*Fig. C77*). With noted exceptions,
 8 most basement windows of this type use the
 9 same prop rod operators found on the three-light
 10 windows of the first floor. Some, however, have
 11 a rotating handle lock which turns 90 degrees to
 12 allow the sash to pivot outward.

13 The second basement window type shares the
 14 same dimensions and design as the two-light steel
 15 sash described on the main level, but shares the
 16 concrete sills found on other basement windows



Figure C77. Typical two-over-one light awning-sash basement window.



Figure C78. Two-light awning-sash basement window on north elevation.

17 (*Fig. C78*). There is only one example of this
 18 window type at the basement level.

19 Both types of basement windows lack exterior
 20 casings, and are instead fit into the masonry or
 21 poured concrete openings (*Figs. C77-C78*).

Exterior Doorways

22 The main entrance has two pairs of exterior screen
 23 doors leading to a small entry vestibule or airlock
 24 (Room 108). Both doorways measure 5'-4" wide
 25 by 7'-0 ½" tall and hold matching pairs of one-
 26 light-over-one-panel screen sash doors (*Fig. C79*).
 27 Each leaf measures 2'-8" wide by 7'-0 ½" tall by 1
 28 ½" thick and is made up of 5 ¼" wide inner stiles,
 29 5 ½" hinge stiles, and 5 ½", 11", and 8" top, lock,
 30 and bottom rails, respectively. Metal straps have
 31 been added at the head of the doors to further
 32 secure the top rail to the stiles. Stiles and rails have
 33 ¼" chamfers at the screened openings and lower
 34 panels. Each lower panel is made up of v-groove
 35 boards and has a 5 ½" wide diagonal rail (*Fig. C80*).
 36 The easternmost door has been repaired; the panel
 37 and its diagonal have been replaced and are of
 38 different proportions. The exterior casing is lintel
 39 cut; the head casing measures about 10" tall, and
 40 side casings measure about 5 ½" wide. The two
 41 pairs of doors are separated by an 8" wide post.
 42 A menu display board is mounted between the
 43 doorways (*Fig. C79*).

44 The doors are hung with three 3 ½" tall, five
 45 knuckle ball-pin hinges, though with the exception
 46 of the easternmost bottom hinge, all lower hinges
 47 have been replaced with modern 3 ½" tall butt
 48 hinges (*Fig. C81*). Brass pull handles measure 5"
 49 tall, and back plates on each door measure 1'-3"



Figure C79. Overview of main entrance doorways. Note inconsistent size of lower panel at far right.



Figure C80. Detail of panels. Note added plywood at lock rails and handles.



Figure C81. Early ball-pin hinge.




Figure C82. Exterior face of inner set of doors.




Figure C83. Inner set of paired doors, viewed from interior.

1 tall by 3 1/2" wide. The plates are mounted on
 2 plywood spacers that may be part of a previous
 3 repair. Thin plywood covers the majority of the
 4 lock rail, necessitating shims behind pull handle
 5 plates. More recent brass kick plates at the base of
 6 each door measure 7" tall (Fig. C80). The screen
 7 opening measures 1'-9 1/4" wide by 3'-5 1/2" tall and
 8 holds a fiberglass screen fitted within a removable
 9 aluminum frame mounted on the interior of the
 10 door. Six screen guards on the interior measure 3/4"
 11 in diameter are spaced at about 2 1/2" on center. The
 12 guards vary slightly in position between the two
 13 pairs of doors (Fig. C79). Both pairs of doors are
 14 equipped with modern closers.

15 The inner doorways, originally exposed on the
 16 exterior, also hold two pairs of original six-vertical-
 17 light over-one-panel sash doors (Fig C82-C83). The
 18 opening measures 6'-0" wide by 7'-0 1/2" tall; each
 19 leaf measures 2'-11 5/8" wide by 7'-0 3/8" tall by 2 1/4"
 20 thick. Stiles measure 4 3/4" wide on the inside edge,

21 and 5" wide on the hinge side. Top rails measure 5"
 22 wide, and lock and bottom rails measure 8" wide. A
 23 5 3/8" wide diagonal rail crosses the v-groove panel.
 24 Stiles and rails have a 1/4" chamfer around both the
 25 panel and glazed sections. A chamfered center post
 26 measuring 4 5/8" wide by 1'-3 5/8" deep separates the
 27 two pairs of doors.

28 The glazed portion of the doors measures 2'-1 1/2"
 29 wide by 3'-4 3/4" tall. The muntins in the glazed
 30 portion resemble square spindles turned on-point

1 with tapered, rounded ends (*Fig. C82*). Each
 2 measures $1\frac{1}{8}$ " square, and $1\frac{5}{8}$ " in diagonal width,
 3 spaced at about $2\frac{5}{8}$ " apart. The square section
 4 tapers over a length of $2\frac{1}{2}$ " to form a round base
 5 measuring $1\frac{1}{4}$ " in diameter where it meets the top
 6 and lock rails. Each muntin is assembled in two
 7 pieces, with the glass intersecting the muntin at
 8 its center. Wood strips on the exterior of the door
 9 help to hold the glass in place (*Fig. C82*).

10 The doors are hung on swivel hinges embedded in
 11 the floor, which work in conjunction with a round
 12 peg at the top of the door that allows operation in
 13 both directions. The hinges also serve as automatic
 14 door closers. Hardware includes pull handles
 15 mounted on back plates measuring about $3\frac{3}{4}$ "
 16 wide by 1'-3" tall on the exterior; the interior has
 17 laminate push plates of similar measurements.
 18 Swiveling, keyed deadbolts are common to both
 19 pairs of doors. Kick plates on the interior measure
 20 6" tall. Each door has a folding door stop (*Fig. C83*).

21 The west doorway holds a pair of original nine-
 22 light over two-raised-vertical-panel doors (*Figs.*
 23 *C84-C85*). The doorway measures 5'-1" wide by
 24 7'-0" tall; the primary and secondary leaves measure
 25 2'-5 $\frac{1}{2}$ " and 2'-7" wide, respectively; both measure
 26 6'-11" tall by $1\frac{3}{4}$ " thick. Inside stiles measure 4 $\frac{1}{2}$ "
 27 wide, while those at the hinge measure 4" wide.



Figure C84. Overview of west doorway.



Figure C85. Detail of typical nine-light sash door muntins.




Figure C86. Typical original mortised lockset and brass knob.

28 Top, lock, and bottom rails measure 4", 7", and
 29 9", respectively. Each door is hung with three, 4
 30 $\frac{1}{2}$ " tall ball-pin hinges. A mortised lockset with 2
 31 $\frac{1}{4}$ " brass knob has both an un-keyed knob lock
 32 and deadbolt, which has been blanked out on the
 33 exterior (*Fig. C86*). A 4" barrel bolt is mounted on
 34 the secondary leaf, as is a 4" long head bolt with
 35 pull chain (*Fig. C87*). The doorway has a concrete
 36 subsill measuring 5" thick and an aluminum
 37 threshold measuring 4" wide by $\frac{5}{8}$ " thick. Lintel-



Figure C87. Likely-original interior head bolt with chain on west doorway.




Figure C88. Exterior pull handles on screen doors. Note overall deterioration of doors and inferior construction.



Figure C89. Replacement steel doors in added doorway on east elevation.

8 doors are hung with three, 2 ½” tall spring hinges
 9 and also have spring returns. Hardware includes
 10 two 4” pull handles on the exterior, and two 3 ½”
 11 pull handles on the interior (Fig. C88).

12 The added east doorway measures 6’-4” wide
 13 overall by 6’-7 ½” tall and holds two steel, flush-
 14 panel, single-light sash replacement doors (Fig. C89).
 15 Each door measures 2’-11 ½” by 6’-7 ½”, separated
 16 by a stationary steel post measuring 1 ¼” wide. The
 17 glazed panels measure 1’-10” wide by 2’-4” tall. The
 18 doors are hung with three, 4 ½” tall butt hinges. The
 19 current doors are at least the second to be installed
 20 at this location, as incised hinge marks for previous
 21 doors are visible on the jamb. Blocking installed
 22 above the doors infills what was once a 7’-0” tall
 23 opening.

24 Although the doors are manufactured to hold a
 25 mortised lockset, none is currently installed.
 26 The southern door has a pull handle and keyed
 27 deadbolt. The northern door lacks hardware
 28 and is secured with chain and wedged shut with
 29 a plank board. The exterior casing is lintel cut,
 30 and measures 7” wide by ¾” thick. A 1” ear on
 31 the northern corner is likely the result of poor
 32 carpentry (Fig. C89).

33 A total of seven exterior doorways on the north
 34 elevation access rooms in the basement. With
 35 the exception of the doorway to the refuse room
 36 (Room 007), which has only a screen door, all hold
 37 doors of the same original nine-light-over-two-
 38 raised-vertical-panel design and measure 2’-8” wide
 39 by 6’-7” tall by 1 ½” thick. Lintel-cut plank board
 40 casings measure 3” wide by 1 ¼” thick (Fig. C90).
 41 The doors are hung with three typical 4 ½” tall ball-
 42 pin hinges and have typical mortised locksets with 2

1 cut plank board casings measure 3 ½” wide by 1 ¾”
 2 thick.

3 A pair of replacement two-panel screen doors are
 4 mounted on the outside of the west doorway
 5 (Fig. C84). Each leaf measures 2’-6” wide by 7’-0”
 6 tall by 1 ½” thick. Stiles measure 3 ½” wide, and top
 7 lock, and bottom rails each measure 5 ¼” wide. The



Figure C90. Typical exterior door at basement level.



Figure C92. Typical original ball-pin screen door hinge.



Figure C93. Example of likely-original screen door latch.



Figure C91. Example of original basement screen door.

- 1 ¼" diameter brass knobs and integrated deadbolts
- 2 and un-keyed knob locks. The exterior of many of
- 3 the locks have been blanked out.
- 4 Each of the seven doorways has a two-panel
- 5 exterior screen door. Each door measures 2'-8"
- 6 wide by 6'-6" tall by 1 ½" thick; however, the door
- 7 to Room 007 measures 3'-0" wide. Four of the
- 8 seven doors are likely original, and include those
- 9 leading to Rooms 001, 002, 003, and 005. The
- 10 original doors have stiles measuring 3 ½" wide,
- 11 with top, lock, and bottom rails measuring 3 ½",
- 12 5", and 8", respectively. The upper panel measures
- 13 3'-5" tall (*Fig. C91*). The doors are hung with
- 14 three, 3" tall ball-pin hinges. Hardware includes
- 15 a 1 ¾" knob and surface-mounted screen door
- 16 latch on the door's interior face (*Figs. C91, C93*).

1 Half-round screen trim holds the metal screen
2 material in place. The non-original screen doors
3 are also two-panel, however their designs vary
4 slightly and appear largely improvised.

Exterior Steps and Rear Porch

5 A covered poured-in-place concrete walkway
6 extends the majority of the length of the north
7 elevation and serves as both a circulation space and
8 rear porch. The walkway measures 4'-0" wide, and
9 extends from the exterior stair to just beyond the
10 easternmost exterior doorway (Figs. C94-C95).

11 A shed-roofed cover shielding the exterior walkway
12 begins at the westernmost exterior doorway and
13 extends to just beyond the easternmost doorway.
14 The roof is supported by seven 5x5 posts, with
15 on-center spacing relating to the spacing of
16 structural columns the main level. From east to west,
17 post spacing measures 13'-0", 13'-0", 13'-0", 10'-6",
18 10'-6", and 11'-6" on center. Each post supports
19 a 5" wide by 7" deep beam along the low end of
20 the roof slope; 5x3 brackets extend from the posts
21 to the underside of the beam at an approximately
22 45-degree angle. Roof rafters measure 2 3/4" wide
23 by 3 3/4" deep, and are spaced at 24" on center. Roof
24 decking is 5 1/2" wide by 1 1/2" thick plank boards,
25 supporting a cement shingle roof matching that of
26 the rest of the building (Fig. C96). A 3 3/4" wide by
27 7/8" thick rake board lines the sides of the roof; there
28 is no fascia board. Downspouts remain for a gutter
29 along the low end of the shed roof; however, the
30 gutter itself has been removed.

31 A run of poured-concrete exterior steps extends
32 from the northwest corner of the building to the
33 covered walkway that parallels the north wall
34 of the basement and is described in the earlier



Figure C95. Concrete walkway along north elevation.



Figure C96. Porch roof framing.



Figure C94. Shed-roofed open rear porch.

35 *Site Features* section. The area beneath the stairs
36 is open, and has a screened partition wall of
37 dimensional lumber and hardware cloth mesh (Fig.
38 C97). A two-panel screen door access the space,
39 which contains the compressor for the walk-in
40 cooler (Room 105B). An electrical cutoff switch
41 and timer are mounted on the wall beneath the
42 stair (Fig. C98).

43 On the east elevation, a flagstone-paved ramp
44 accesses the east doorway from the sidewalk



Figure C97. Screened area beneath exterior stair.

1 adjacent to the loop road. The ramp measures 6'-6"
 2 wide. A 6" wide poured-in-place concrete retaining
 3 wall extends to form a curb on the north and east
 4 sides as grade drops away. A 3'-6" tall pipe railing
 5 measuring 1 1/2" in diameter is embedded in the
 6 concrete curb (Fig. C99).

7 The west doorway is accessed by a single concrete
 8 step from the fenced service area. The step
 9 measures 5'-8" wide by 1'-3 1/2" deep by 7" tall and
 10 is centered on the doorway (Fig. C84).

11 The main entry is approached at grade level. The
 12 flagstone paving of the surrounding walkways
 13 continues through the screen doors and into the
 14 airlock.

Roof

15 Both the main body and west wing of the coffee
 16 shop are side gabled, and typically have an 8:12
 17 roof slope based on the original drawings. The
 18 roof of the extending south bay has a considerably



Figure C98. Compressor unit for walk-in cooler on main level (Room 105B).



Figure C100. Cement shingle roof. Note several courses of composition shingle at ridge.



Figure C99. Ramp leading to east doorway.



Figure C101. Temporary composition shingles meeting cement shingles east of chimney.

1 shallower slope; measuring 5 ¼:12 according to
 2 the drawings. Until recently, all roof surfaces were
 3 clad with cement shingles, combed to give the
 4 appearance of wood shakes (*Fig. C100*). Shingles
 5 measure about 19 ½" long and taper from about
 6 ½" thick to about ⅞" thick. Shingle widths vary
 7 between 5", 8", and 10" wide with a 7 ½" exposure.
 8 Where protected, the shingles have a light grey
 9 coloration; exposed areas have weathered to a
 10 grey-green color (*Fig. C101*). The current cement



Figure C104. Detail of hood on east elevation.



Figure C102. Exposed rafter tails and decking on south elevation.

11 shingle roof replaced the original in 2010-2011,
 12 and was intended as an in-kind replacement.
 13 Rafter tails and decking boards are exposed
 14 beneath the eaves. Rafter tails are horizontally-cut.
 15 Tongue and groove decking boards measure 4 ⅞"
 16 wide by about 1" thick (*Fig. C102*).

17 On the east elevation, a projecting hood is
 18 formed by an approximately 4'-0" extension the
 19 timber framing of the central bay (*Fig. C103*).
 20 Two approximately 8x8 beams extend the full
 21 depth of the hood, and are supported by two 4x6
 22 brackets. Two rafter bays with exposed decking
 23 and horizontal-cut rafter tails are visible on the
 24 underside of the hood.

25 In response to recent roof leaks at the chimney,
 26 architectural composition shingles were installed
 27 as a temporary measure on the western end of the
 28 southern roof slope of the main body, extending
 29 the full width of the lower-sloped portion of the
 30 roof. As a precautionary measure, composition
 31 shingles were also installed across the entirety of
 32 the roof ridge (*Figs. C100-C101*).

Chimney and Vents

33 The base of the chimney is of poured-in-place
 34 concrete construction, which transitions to CMU
 35 and salt-glazed tile as it passes through the kitchen



Figure C103. Projecting hood on east elevation.

1 and attic (*Fig. C105*). The portion of the chimney
 2 above the roof slope is constructed of stone
 3 masonry (*Fig. C106*). The chimney contains a flue
 4 that serves as a vent for the boiler with round vent
 5 cap. The chimney also contains the main plumbing
 6 vent stack, which appears to serve the entire
 7 building. Aluminum coping with a drip edge covers
 8 the top of the chimney (*Fig. C106*). The base of the
 9 chimney has copper flashing; a cricket abuts the
 10 north side of the chimney.

11 Two large commercial vents on the north roof
 12 slope served equipment in Room 102 (*Fig. C107*).



Figure C107. Commercial vents on north roof slope.



Figure C105. View of chimney in the attic. Note water damage left of the chimney, and signs of moisture on CMU.



Figure C108. Wall vent on north elevation. Note discoloration of siding beneath.



Figure C109. Metal louvered vent on west gable end of main body.



Figure C106. Exterior view of chimney. Note metal coping and copper flashing.

13 Based on evidence in the attic, the eastern vent
 14 served the large hood over the stove, just north of
 15 the chimney. The second vent appears to have been
 16 an exhaust fan. Both are connected to rectangular
 17 ducts that pass through the attic.

18 A commercial wall vent near the center of the
 19 north elevation serves a vent hood in the northwest
 20 corner of the dining room (*Fig. C108*).



Figure C110. Larger aluminum-lined wood gutter above entrance. Gutter on west wing is similar.



Figure C112. Bracket passing through aluminum liner on large gutter.

- 1 A metal louvered vent on the west gable end of
- 2 the main body works in conjunction with an attic
- 3 ventilation fan. The vent is cased as a window
- 4 opening (Fig. C109).

Gutters & Downspouts

- 5 Aluminum-lined wood boxed gutters line the
- 6 southern roof slope, extending the entire length
- 7 of the elevation. Those above the entrance and on
- 8 the west wing are larger than those on the dining
- 9 room section. Historic photographs, as well as the
- 10 original drawings, show that the smaller version
- 11 reflects the original design.

- 12 On the larger variant, metal straps measuring 3/16"
- 13 thick extend from between the roof decking and
- 14 shingles to form brackets that hold a two-sided
- 15 wooden trough-like gutter from both the front
- 16 and back (Figs. C110-C112). The wood gutter is
- 17 connected at a right angle and hangs on-point.
- 18 The front face of the larger gutters is made up of



Figure C113. Original smaller gutter design on east end of south elevation.



Figure C111. Metal bracket supporting large gutter.



Figure C114. Metal bracket supporting small gutter.



Figure C115. Typical round metal downspouts with wood wrapping on south elevation.

1 two plank boards and measures 12 1/8 inches wide
 2 overall. The rear face is a single 9 1/2 inch wide plank
 3 board (Fig C110). The inside of the trough is lined
 4 with aluminum sheeting (Fig. C112). The brackets
 5 for the larger gutters pass through both the liner
 6 and front face of the gutter, while a third strap
 7 extends over the top edge of the gutter, both straps
 8 overlap at the front and are connected with two
 9 screws (Figs. C110, C112).

10 The smaller gutters on the east end of the south
 11 elevation, are considerably simpler; consisting
 12 of a similarly-designed metal bracket, but in this
 13 case holding a symmetrical gutter measuring 9 1/4 inch
 14 wide on both the front and back sides (Fig. C113).
 15 The metal brackets wrap the outside of the wood
 16 gutter in one continuous piece. No fasteners
 17 connect the brackets to the wood portion of the
 18 gutters (Fig. C114).

19 A total of four 4 inch diameter downspouts drain the
 20 gutters on the south elevation. The portion that
 21 abuts the exterior wall is enclosed within a wood
 22 box made up of 1x6 boards (Fig. C115).



Figure C116. Aluminum gutter and downspout on north elevation of west wing. Note downspout for rear porch.

23 A modern 6 inch wide ogee gutter lines the north roof
 24 slope of the west wing. A single 4 inch wide rectangular
 25 downspout drains the gutter at its east end. The
 26 remainder of the north elevation has no remaining
 27 evidence of gutters, with the exception of the rear
 28 porch, which retains a modern 4 inch downspout at
 29 the easternmost post, but lacks gutters (Fig. C116).



Figure C117. Typical wall-mounted replacement light fixture.



Figure C118. Exterior floodlight.



Figure C119. One of two coal hatches on west elevation.



Figure C120. Typical flush-panel V-groove door.

Exterior Lighting

1 Exterior lighting consists mostly of surface-
 2 mounted replacement fixtures with rounded
 3 plastic globes (Fig. C117). An electric eye on the
 4 west elevation likely controlled the exterior lighting
 5 system. Fixtures are connected by rigid metal
 6 conduit, though earlier recessed fixture boxes are
 7 present near the modern fixtures in most areas.

8 An early if not original metal floodlight is mounted
 9 at grade near the southeast corner (Fig. C118).

Other features

10 Two top-hinged cast metal coal hatches on the west
 11 elevation measure 1'-11" wide by 1'-6" tall. Each is
 12 surrounded by a concrete well with 4" wide curb
 13 (Fig. C119).

Common Interior Features

Doors and Door Casings

14 The majority of the interior doors are of two main
 15 designs. The first type is a flush-panel door used on
 16 the main level that is made up of V-groove boards
 17 varying between 4" and 9" wide (Fig. C120).

18 Typical interior doors at the basement level are six-
 19 raised-panel doors, most measuring 2'-8" wide by
 20 6'-5 1/2" tall by 1 3/4" thick (Fig. C121).




Figure C121. Typical six-panel basement door.



Figure C122. Typical ball-pin hinge.



Figure C124. Example of mortised lockset with privacy lock at basement level.



Figure C123. Typical mortised lockset with deadbolt on main level.



Figure C125. Typical rounded-corner door casing.

- 1 Interior door hinges are consistent throughout the
- 2 building. With few exceptions, 5-knuckle ball-
- 3 pin hinges measuring 4 ½” tall are present on all
- 4 interior doorways (*Fig. C122*).
- 5 Mortised locksets with 2 ¼” diameter brass knobs
- 6 are consistent on most latching doors. Most
- 7 examples on the main level are coupled with a
- 8 keyed deadbolt and un-keyed knob lock; those at



Figure C126. Typical window sill and apron coupled with quarter-round trim used on openings in wood-framed walls.



Figure C127. Trim at typical window opening in masonry wall.

1 the basement level typically have a privacy lock
2 (Figs. C123-C124).

3 With few exceptions, all interior doorways have
4 miter-cut, rounded-corner casings measuring 2 1/2"
5 wide by 3/4" thick (Fig. C125).

Window Casings and Sills

6 Window openings in wood-framed walls on the
7 main level have 3/4" wide quarter-round trim that lies
8 flush with the surrounding wall paneling (Fig. C126).

9 At main-level window openings containing steel
10 sash windows set in masonry walls, trim is inset
11 within the masonry opening. A miter-cut cove
12 molding measuring 1" wide is coupled with a
13 rounded piece of trim measuring about 2 1/2"
14 wide by 3/4" thick which lines the jamb and meets
15 the steel-sash window (Fig. C127). A variant of
16 this treatment at wood-sash windows lacks the
17 rounded trim, and has cove molding applied to the
18 window frame.

19 With noted exceptions, window sills typically
20 consist of a 3/4" thick rounded sill with 2 1/2" wide by
21 5/8" thick molded apron (Fig. C126).

22 Basement window openings have no casing or
23 trim, but do have typical sills and aprons.

Interior Overview

24 The basement level is finished consistently in all areas
25 except the crawl space (Room 000). Walls and ceilings
26 are painted poured-in-place concrete or CMU and
27 decoration is minimal. In addition to mechanical
28 spaces, the basement was most recently devoted to
29 retail and food storage, and office occupancy.

30 The majority of the main level is devoted to the
31 main dining room and gift shop space (Room
32 101A). Room 101A contains the vast majority of
33 the character-defining features of the interior
34 and retains the majority of its historic finishes.
35 Public bathrooms (Rooms 106A-B and 107A-B)
36 complete the public areas of the coffee shop. The
37 kitchen, preparation areas, and other back-of-
38 house functions are focused toward the western
39 end of the building and are mostly utilitarian in
40 appearance.

Interior Features Room-by-Room

Room 000 – Crawl space

41 The crawl space is a partially-excavated,
42 unfinished area accessed from Room 004. The
43 space measures about 80'-1" east-west by 20'-3"
44 north-south at the west end, and 13'-0" north
45 south at the east end. An approximately 6'-0"
46 wide, full-height walkway along the north wall has
47 a ceiling height of 8'-9". The ceiling height in the
48 above the stone ranges from about 3'-0" to 3'-11"
49 (Figs. C130-C131).

Flooring

50 A dirt floor is consistent along the north wall. The
51 south wall is lined by an approximately 5'-0" tall
52 stone outcropping (Fig. C130).

Baseboards

53 The room has no baseboards.

Walls and Ceilings

54 Both walls and ceilings are unpainted poured-in-
55 place concrete. Remnants of tar paper are present
56 on the ceiling (Figs. C130-C131).

Doorways

57 The doorway on the south wall leading to the crawl
58 space from Room 004 holds a six-raised-panel door
59 measuring 2'-6" wide by 6'-8" tall by 1 3/4" thick (Fig.
60 C132). The door is hung with three typical ball-pin




Figure C128. Basement level plan. A larger version of this plan can be found in *Appendix B*.




Figure C129. Main-floor plan. A larger version of this plan can be found in *Appendix B*.

- 1 hinges and has a slide bolt and deadbolt. The
- 2 doorway has a typical rounded-corner casing.

Windows

- 3 The room has no windows.

Finishes

- 4 All surfaces are unpainted.

Mechanical Systems

- 5 The crawl space itself is not heated or cooled.
- 6 Piping is visible for the hot water radiator heating
- 7 serving the dining room above. Severed pipes
- 8 at the base of the north wall likely remain from
- 9 the removed basement radiators specified in the
- 10 original heating plan (*Fig. C133*).



Figure C130. Room 000 looking southwest.

Electrical System

- 1 Two ceiling-mounted fixtures are controlled
- 2 by a light switch east of the doorway. Both lack
- 3 globes. Rigid metal conduit and junction boxes are
- 4 mounted on the ceiling, serving the spaces above.

Plumbing System

- 5 An electric hot water heater east of the doorway is
- 6 described in the *Utility Systems* section.



Figure C131. Room 000 looking east.



Figure C133. Cast iron drain pipe and severed plumbing and heating pipes at base of north wall.



Figure C132. Doorway to crawl space viewed from Room 004.



Figure C134. Typical surface-mounted fixture in Room 000.



Figure C135. Corrugated storm water pipe leading to collection basin.



Figure C136. Sliding metal cover on stormwater collection basin.



Figure C137. Blocked crawl space vent, viewed from exterior.

1 Galvanized and copper supply pipes in the
2 southwest corner serve the bathrooms above. Cast
3 iron drain pipes measuring 4" in diameter rest on
4 16" by 8" CMU piers extend from the bathrooms
5 and kitchen above to drain and vent stacks along
6 the north wall. Remnants of plumbing leading to
7 the removed fixtures in Rooms 001, 003, 003 and
8 004 is also visible near the base of the north wall.

9 A corrugated storm water pipe enters the crawl
10 space just west of the chimney, and connects to
11 a large poured-in-place concrete storm water
12 collection basin with sliding metal cover
13 (Figs. C135-C136). From the basin, a second
14 corrugated pipe passes beneath the basement floor
15 slab and discharges to grade just north of Room 007.

Fire Protection and Life Safety

16 No fire protection or life safety systems were
17 observed.

Other Features

18 A vent opening at the east end of the crawl space
19 measures 1'-4" wide by 8" tall and holds a metal
20 grate, mortared into the surround wall. On the
21 inside, the opening has been covered with a plank
22 board.

Room 001 – Living Quarters 1

23 Room 001 is at the far east end of the northern half
24 of the basement and originally served as employee
25 quarters, in conjunction with Rooms 002 and 003.
26 It measures about 21'-6" by 13'-9". The floor-to-
27 ceiling height measures 7'-9".

Flooring

28 The concrete slab floor is covered with green asphalt
29 tile with a black and tan veining pattern (Fig. C140).

Baseboards

30 No baseboard is currently in place; however, ghost
31 marks remain for a vinyl wall base measuring about
32 8" tall.

Walls and Ceiling

33 The south and east walls are poured-in-place
34 concrete; the north and west walls are constructed
35 of flush-pointed CMU. Concrete beams running
36 above the east wall and through the center of
37 the space are described in the *Structural Systems*
38 section. The ceiling is poured-in-place concrete.

Doorways

39 The exterior door on the north wall is described in
40 the *Exterior Features* section.



Figure C138. Room 001 - Oblique view looking northwest.



Figure C140. Typical 9x9 asphalt tile flooring.



Figure C139. Room 001 - Oblique view looking southeast

Mechanical Systems

18 There is no remaining evidence of previous
19 radiators, though a thermostat is hanging near
20 the center of the north wall. Heating pipe serving
21 Room 101A above passes above the east window.

Electrical System

22 Two 4'-0" long, two-tube fluorescent fixtures
23 are equally-spaced across the ceiling. A recessed
24 outlet is on the east wall, north of the doorway
25 and a disconnected surface-mounted GFI outlet is
26 mounted near the northwest corner. A double-gang
27 light switch is just east of the exterior doorway. A
28 covered fixture box in the northwest corner likely
29 served a sconce above the now-removed lavatory.

Plumbing System

30 Ghost marks and capped supply and drain pipes
31 remain for a wall-mounted lavatory in the
32 northwest corner. Flexible PVC piping extends
33 from the north to the south wall at the ceiling.

Fire Protection and Life Safety

34 A hard-wired ceiling-mounted smoke detector is
35 near the east end of the room.

Room 002 – Living Quarters 2

36 Room 002 measures about 13'-5" by 13'-9". The
37 floor-to-ceiling height measures 7'-9"
38 (Figs. C141-C142).

Flooring

39 The concrete slab floor is covered with green
40 asphalt tile with a black and tan veining pattern.

Baseboards

41 No baseboard is currently in place; however, ghost
42 marks remain for a vinyl wall base measuring about
43 8" tall.

1 The doorway on the east wall holds a typical six-
2 raised-panel door hung with typical hardware,
3 hinges and casing.

Windows

4 The room has three windows, two on the north
5 wall and one on the east. The east window and
6 eastern window on the north wall are both three-
7 horizontal-light windows with two-light awning
8 sash and fixed lower light. The western window
9 on the north wall is the only instance of a two-light
10 awning window at the basement level. Although
11 the east window uses a handle-type operator; the
12 two north-facing windows once had prop-rods as
13 found on the three-light windows of the first floor,
14 though both have been removed. Both openings
15 have typical rounded sills and molded aprons.

Finishes

16 All elements of walls, ceiling, and trim are painted
17 cream color.



Figure C141. Room 002 - Oblique view looking northwest.



Figure C142. Room 002 - Oblique view looking southeast.

Walls and Ceiling

1 The south wall is poured-in-place concrete; all
 2 other walls are constructed of flush-pointed
 3 CMU. Concrete beams running above the east and
 4 west walls are described in the *Structural Systems*
 5 section. The ceiling is poured-in-place concrete.

Doorways

6 The exterior door on the north wall is described in
 7 the *Exterior Features* section.

8 The doorway on the east wall leading to Room 001
 9 is described in the *Room 001 – Living Quarters 1*
 10 section. The doorway on the west wall leading to
 11 Room 003 holds a typical six-raised-panel door
 12 with typical hardware and casing.

Windows

13 There is one three-horizontal-light window on the
 14 north elevation with missing prop rod operator.
 15 The opening has a typical rounded sill and
 16 molded apron.

Finishes

17 All elements of walls, ceiling, and trim are painted a
 18 cream color.

Mechanical Systems

19 The room has no mechanical systems, and no
 20 evidence of previous radiator remains.

Electrical System

21 Ghost marks for a round surface-mounted light
 22 fixture are visible at the center of the ceiling. Two
 23 surface-mounted outlets are on the east wall; one
 24 recessed outlet is south of the doorway to Room
 25 003. A double gang light switch is just west of the
 26 exterior doorway. A covered fixture box in the
 27 northeast corner likely served a sconce above the
 28 removed lavatory.

Plumbing System

29 Ghost marks and capped supply and drain
 30 pipes remain for a wall-mounted lavatory in the
 31 northwest corner.

Fire Protection and Life Safety

32 A hard-wired ceiling-mounted smoke detector is
 33 near the center of the room.

Room 003 – Living Quarters 3

34 Room 003 measures about 12'-0" by 13'-9". The
 35 floor-to-ceiling height measures 7'-9"
 36 (Figs. C143-C144).

Flooring

37 The concrete slab floor is covered with green
 38 asphalt tile with a black and tan veining pattern.

Baseboards

39 No baseboard is currently in place; however, ghost
 40 marks remain for a vinyl wall base measuring about
 41 8" tall.

Walls and Ceiling

42 The south wall is poured-in-place concrete; all
 43 other walls are constructed of flush-pointed
 44 CMU. Concrete beams running above the east
 45 and west walls are described in the *Structural*
 46 *Systems* section. The ceiling is poured-in-place
 47 concrete.

Doorways

48 The exterior door on the north wall is described in
 49 the *Exterior Features* section.

50 The doorway on the east wall leading to Room 002
 51 is described in the *Room 002 – Living Quarters 2*
 52 section. The doorway on the west wall leading to

1 Room 004 holds a typical six-raised-panel door
2 with typical hardware and casing.

Windows

3 There is one three-horizontal-light window on
4 the north elevation with prop rod operator. The
5 opening has a typical rounded sill and molded
6 apron.

Finishes

7 All elements of walls, ceiling, and trim are painted a
8 cream color.

Mechanical Systems

9 The room has no mechanical systems, and no
10 evidence of previous radiator remains.

Electrical System

11 The base for a surface-mounted light fixture is
12 centered on the ceiling, surrounded by the ghost
13 marks of an earlier fixture. Surface-mounted
14 outlets are on the south, east, and west walls. A

15 double gang light switch is just east of the exterior
16 doorway. A silver wall sconce is detached and
17 hanging above the location of a previous lavatory
18 just north of the doorway on the west wall.

Plumbing System

19 Ghost marks and capped supply and drain pipes
20 remain for a wall-mounted lavatory on the west
21 wall. Added PVC drain pipes cross the ceiling, and
22 pass through holes made in the west CMU wall,
23 presumably to reach an existing drain beneath the
24 floor. Expanding insulation foam is used to seal
25 openings in the floor slab around the added pipes.
26 An earlier galvanized pipe crosses the ceiling and is
27 capped on the other side of the north exterior wall.

Fire Protection and Life Safety

28 A hard-wired ceiling-mounted smoke detector is
29 near the center of the room.

Room 004 – Women’s Locker Room

30 Room 004 measures about 10’-7” by 13’-9”. The
31 floor-to-ceiling height measures 7’-9”
32 (Figs. C145-C146). Originally, this room served as a
33 locker room and bathroom for female employees.

Flooring

34 A concrete slab floor is consistent throughout the
35 room.

Baseboards

36 No baseboard is currently in place, and there are
37 no ghost marks for previous baseboards.

Walls and Ceiling

38 The south wall is poured-in-place concrete; all
39 other walls are constructed of flush-pointed
40 CMU. Concrete beams running above the east and



Figure C143. Room 003 - Oblique view looking northwest.




Figure C144. Room 003 - Oblique view looking southeast.




Figure C145. Room 004 - View looking south.



Figure C146. Room 004 - View looking north.



Figure C147. Disconnected lavatory on east wall.

1 west walls are described in the *Structural Systems*
2 section. The ceiling is poured-in-place concrete.

Doorways

3 The exterior door on the north wall is described in
4 the *Exterior Features* section.

5 The doorway on the east wall leading to Room 003
6 is described in the *Room 003 – Living Quarters 3*
7 section.

8 The doorway on the south wall leading to Room
9 000 is described in the *Room 000 – Crawl Space*
10 section.

Windows

11 There is one three-horizontal-light window on the
12 north elevation with missing prop rod operator.
13 The glass is frosted for privacy. The opening has a
14 typical rounded sill and molded apron.

Finishes

15 All elements of walls, ceiling, and trim are painted a
16 cream color.

Mechanical Systems

17 The room has no mechanical systems, and no
18 evidence of previous radiator remains.

Electrical System

19 A surface-mounted 4'-0" long two-tube fluorescent
20 light fixture is centered in the southern portion
21 of the room. A bare fixture box on the north end
22 of the room likely held a similar fixture. Surface-
23 mounted outlets are on the south, east, and west
24 walls. A double gang light switch is just west of the
25 exterior doorway. A bare fixture box is centered
26 above the lavatory on the east wall.

Plumbing System

27 A likely-original disconnected lavatory is on the
28 east wall, just south of the doorway (Fig. C147).
29 A mixture of copper and flexible PVC cross the
30 walls and ceiling. A cast iron drain pipe passes
31 through the ceiling near the doorway to Room 003
32 and continues along the wall to the crawl space.
33 A vertical opening has been made at north end
34 of the east wall to accommodate pipes from the
35 floor above. A toilet is in the southwest corner. The
36 northeast corner has an indentation at the location
37 of the previous shower drain.

Fire Protection and Life Safety

38 A hard-wired ceiling-mounted smoke detector is
39 near the center of the room.

Room 005 – Men's Locker Room

40 Room 005 measures about 10'-2" by 13'-9". The
41 floor-to-ceiling height measures 7'-9". Originally,
42 the room served as a locker room and bathroom
43 for male employees. The majority of the room is
44 occupied by a large walk-in cooler which extends
45 almost the full ceiling height (Figs. 148-150).

Flooring

46 A concrete slab floor is consistent throughout the
47 room.

Baseboards

48 No baseboard is currently in place, and there are
49 no ghost marks for previous baseboards.

Walls and Ceiling

50 The south and west walls are poured-in-place
51 concrete; all other walls are constructed of flush-
52 pointed CMU. A concrete beam running along

1 the east wall is described in the *Structural Systems*
2 section. A large metal-clad walk-in freezer has been
3 installed in the southwest corner, and conceals the
4 majority of the south and west walls. The ceiling is
5 poured-in-place concrete.

Doorways

6 The exterior door on the north wall is described in
7 the *Exterior Features* section.

Windows

8 There is one three-horizontal-light window on the
9 north wall with frosted glass for privacy. The opening
10 has a typical rounded sill and molded apron.

Finishes

11 All elements of walls, ceiling, and trim are painted a
12 cream color.

Mechanical Systems

13 The room has no mechanical systems, and no
14 evidence of previous radiator remains. Refrigerant
15 lines run from the front of the cooler through the
16 west wall.

Electrical System

17 A surface-mounted 4'-0" long two-tube fluorescent
18 light fixture is centered in the northern portion of



Figure C149. Room 005 - View looking south along side of walk-in cooler.



Figure C148. Room 005 - View looking west.



Figure C150. Interior of walk-in cooler looking southeast.

19 the room. Electrical boxes and conduit related to
20 the freezer are mounted to the west wall and the
21 north face of the cooler itself.

Plumbing System

22 Fixtures and piping relating to the original
23 bathroom have been obscured or removed.

Fire Protection and Life Safety

24 No fire protection or life safety equipment was
25 observed; however, the majority of the ceiling is
26 not visible.

Room 006 – Boiler Room

- 1 Room 006 measures about 11'-5" by 12'-3 1/2"
- 2 with a floor to ceiling height of 7'-9". It houses the
- 3 majority of the mechanical systems for the building
- 4 (Figs. 151-154).

Flooring

- 5 A concrete slab floor is consistent throughout the
- 6 room.

Baseboards

- 7 The room has no baseboards.

Walls and Ceiling

- 8 The south, east, and west walls are poured-in-place
- 9 concrete. The north wall is flush-pointed CMU.
- 10 The ceiling is poured-in-place concrete.

Doorways

- 11 A doorway in the north wall leads to Room 007,
- 12 and holds a nine-light-over-two-panel door
- 13 measuring 3'-0" wide by 6'-8" tall by 1 3/4" thick



Figure C153. Room 006 - Oblique view looking southeast.



Figure C154. Room 006 - Oblique view looking northeast.



Figure C151. Room 006 - Oblique view looking northwest.



Figure C152. Room 006 - Oblique view looking southwest.

- 14 (Figs. C151, C155). The door is hung with three
- 15 typical, five-knuckle ball-pin hinges and has a
- 16 typical mortised lockset with brass knob. The door
- 17 is secured with a keyed deadbolt and has a padlock
- 18 hasp. The lower two panels have been removed and
- 19 covered with screen on the outside, secured with
- 20 wood strips. On the inside, the panels have been
- 21 covered with plywood. Both the panels and inside
- 22 of the door jamb have been sealed with expanding
- 23 foam insulation. The doorway has typical rounded-
- 24 corner casing.

- 25 An opening extending from floor-to-ceiling on
- 26 the west wall leads to Room 008, and measures 3'-0
- 27 1/4" wide. The opening has no casing.

Windows

- 28 A three-horizontal-light window on the north wall
- 29 looks into Room 007. The glass has been removed
- 30 from the top and bottom lights; the top has been
- 31 replaced with diamond-shaped metal mesh on the



Figure C155. Nine-light sash door on north wall of Room 006.



Figure C156. Window on north wall.

1 interior, which has been covered with plywood
 2 from the exterior. The bottom light has been fitted
 3 with a plywood panel. The window has a handle
 4 operator. The perimeter of the operable sash, as
 5 well as the seams around the plywood patches have
 6 been sealed with expanding foam insulation. The
 7 opening has a typical rounded sill and molded apron
 8 (Fig. C156).

Finishes

9 With the exception of the floor and ceiling, all
 10 elements of the room are painted a blue-grey color.

Mechanical Systems

11 A gas-powered hot water boiler sits on a concrete
 12 plinth in the southeast corner, vented to the
 13 adjacent chimney (Fig. C153). An unmarked
 14 pressure tank lies immediately east of the boiler
 15 (Fig. C157). Five boiler pumps are connected the
 16 various branches of the hot water piping extending
 17 from the boiler. A more detailed description of the
 18 mechanical systems is found in the *Utility Systems*
 19 section.

Electrical System

20 Two 4'-0" long, surface-mounted fluorescent
 21 fixtures with translucent covers light the room.



Figure C157. Pressure tank east of boiler.

22 One fixture is mounted on the ceiling near the east
 23 wall, and the other is mounted across the top of
 24 the opening in the west wall. Both are controlled
 25 by a surface-mounted switch just east of the north
 26 doorway (Fig. C158). A second switch, north of the
 27 opening on the west wall likely controls the fixtures
 28 in Room 008.

29 Various surface-mounted junction boxes are
 30 connected by rigid and flexible metal conduit. A
 31 surface mounted receptacle is just below the light




Figure C158. Switches and transformers east of doorway on north wall.

- 1 switch by the north doorway. Three electrical
- 2 transformers, which appear to be for the boiler
- 3 pumps are mounted east of the north doorway
- 4 (Fig. C158).

Plumbing System

- 5 An indirect hot water heater in the southwest
- 6 corner is connected to the buildings hot water
- 7 heating system (Fig. C152).
- 8 An eighty-gallon electric hot water heater, model
- 9 near the window, along the north wall (Fig. C154).
- 10 An Amtrol-branded tank in the northeast corner
- 11 appears to be a pressurized well water storage tank
- 12 (Fig. C159).
- 13 A rectangular drain measuring 1'-6" by 1'-0" is
- 14 along the east wall, behind the boiler (Fig. C160).
- 15 A drain pipe made up of a mixture of cast iron and
- 16 PVC pipe extends the length of the south wall,
- 17 passing through the wall at the southeast corner to
- 18 enter the crawl space. Though most of the piping is
- 19 related to the heating system, a few pipes crossing
- 20 the ceiling appear to serve fixtures on the main level.
- 21 A more detailed description of the plumbing
- 22 system is found in the *Utility Systems* section.



Figure C159. Pressurized tank in northeast corner.



Figure C160. Floor drain along east wall, obscured by plastic.



Figure C161. Chimney cleanout on east wall.

Fire Protection and Life Safety

- 23 Two surface-mounted panels on the west wall
- 24 likely control the fire alarm and associated dial-out
- 25 security system (Fig C151). No smoke alarm was
- 26 observed.

Other Features

- 1 A cleanout on the west side of the chimney has a
- 2 hinged metal door and measures 1'-0" wide by 8"
- 3 tall (Fig. C161).

Room 007 - Refuse Room

- 4 Room 007 is a partially open-air room between
- 5 the exterior and Room 006, originally intended to
- 6 hold trash. It measures about 11'-5" by 6'-7" with a
- 7 ceiling height of 7'-9" (Figs. C162-C163).

Flooring

- 8 A poured-in-place concrete floor is consistent
- 9 throughout the room.

Baseboards

- 10 The room has no baseboards.

Walls and Ceiling

- 11 The ceiling and east and west walls are poured-in-
- 12 place concrete. The north and south walls are

- 13 flush-pointed CMU. A large amount of expanding
- 14 foam insulation fills a gap across the top of the
- 15 south wall.

Doorways

- 16 The doorway in the south wall leading to Room
- 17 006 is discussed in the *Room 006 - Boiler Room*
- 18 section. The doorway has typical rounded-corner
- 19 casings (Fig. C163). The doorway to the exterior on
- 20 the north wall is a two-panel screen door described
- 21 in the *Exterior Features* section (Fig. C163). The
- 22 lintel-cut plank board interior casing measures
- 23 about 4" wide.

Windows

- 24 The three-light window in the south wall is
- 25 described in the *Room 006 - Boiler Room* section.
- 26 The window has a concrete sill matching those of
- 27 other basement windows (Fig. C163).
- 28 On the north wall, a six-light screened opening
- 29 measures 7'-0" wide by about 4'-0" tall. The
- 30 opening has a typical rounded sill and molded apron.
- 31 The lintel-cut plank board interior casing measures
- 32 about 4" wide and extends to the masonry opening
- 33 (Fig. C162).

Finishes

- 34 All surfaces are painted blue-grey with the
- 35 exception of the concrete floor.

Mechanical Systems

- 36 A condensing unit for the walk-in freezer in Room
- 37 005 rests on a CMU base near the center of the
- 38 south wall (Fig. C163).

Electrical System

- 39 A surface-mounted electrical panel is in the
- 40 southwest corner, large diameter conduit passes
- 41 from the panel through the wall into Room 006.
- 42 Flexible metal conduit supplies power to the
- 43 condensing unit. Two recessed light switches are
- 44 just east of the exterior doorway.
- 45 A 4'-0" long surface-mounted fluorescent fixture
- 46 with translucent cover is centered on the ceiling.

Plumbing System

- 47 A PVC drain trap serving the main floor extends
- 48 into the space. A mixture of copper and PVC
- 49 piping crosses the ceiling. A black iron gas pipe
- 50 runs along the east wall, continuing into Room 006.
- 51 A covered rectangular floor drain is near the center
- 52 of the north wall.



Figure C162. Room 007 - Oblique view looking northwest.



Figure C163. Room 007 - Oblique view looking southeast

Fire Protection and Life Safety

- 1 A surface-mounted, hard-wired smoke alarm is on
- 2 the ceiling.
- 3 On the south wall, between the door and window,
- 4 a large metal cabinet likely once held a fire hose
- 5 (Fig. C163).

Room 008 – Coal Bunker No. 2

- 6 Room 008 originally served as coal storage for the
- 7 heating system, and measures about 22'-6" by 9'-9
- 8 ½" with a ceiling height of 7'-9" (Figs. C164-C165).

Flooring

- 9 A poured-in-place concrete floor is consistent
- 10 throughout the room.

Baseboards

- 11 The room has no baseboards.

Walls and Ceiling

- 12 The walls and ceiling are all poured-in-place
- 13 concrete.

Doorways

- 14 An opening in the east wall leading to Room 006 is
- 15 described in the *Room 006 – Boiler Room* section.
- 16 On the Room 008 side, a metal flange remains on
- 17 the north jamb for some type of door or cover
- 18 (Fig. C166).

Windows

- 19 The room has no windows.

Finishes

- 20 All elements of the room are unfinished concrete.

Mechanical System

- 21 Piping likely related to radiators on the main level
- 22 extend along the south wall.



Figure C164. Room 008 - View looking west.



Figure C165. Room 008 - View looking east.




Figure C166. Metal flange on north door jamb.

Electrical System

- 23 Two replacement light fixtures without globes are
- 24 mounted on the ceiling and connected by flexible
- 25 metal conduit (Fig. 167).

Plumbing System

- 26 Several PVC drain pipes run along the ceiling near
- 27 the south wall, serving the sink in Room 105A.
- 28 Copper supply pipes, some of which are not
- 29 connected, are also mounted near on the ceiling.

Fire Protection and Life Safety

- 30 A surface-mounted, hard-wired smoke detector is
- 31 on the ceiling.



Figure C167. Typical ceiling fixture in Room 008.

Room 009 – Basement Vestibule

11 Room 009 contains the staircase to the main level,
 12 as well as a small lower vestibule. The vestibule
 13 measures about 3'-9" by 2'-10" (Figs. C170-C172).

Flooring

14 Modern 1'-0" by 1'-0" vinyl composition tile
 15 flooring is used in the vestibule at the base of the
 16 stair.

Baseboard

17 The room currently has no baseboards; however,
 18 ghost marks for vinyl wall base are on the north
 19 and east walls.

Walls and Ceiling

20 At the basement level, the east wall is poured-in-
 21 place concrete. The west wall is flush-pointed
 22 CMU. The upper walls and ceiling are described in
 23 the later *Room 103 – Stair Hall* section.

Doorways

24 The door in the north wall is described in the
 25 *Exterior Features* Section.

26 The doorway in the west wall leading to Room
 27 010 holds a six-raised-panel-door measuring 2'-6"
 28 wide by 2'-8" tall by 1 3/4" thick (Fig. C171). The



Figure C168. Grease trap on ceiling.



Figure C169. Secured coal door on west wall.

Other Features

1 A grease trap near center of the ceiling consists of a
 2 metal box measuring about 1'-9" wide by 2'-6" long
 3 by 2'-2" tall (Fig. C168). The grease trap is connected
 4 to the PVC drain system and has a valve on its
 5 western face, presumably for cleaning purposes.

6 A top-hinged cast metal coal door on the west wall
 7 is described in the *Exterior Features* section. A
 8 wood screen sash has been fitted to the inside of
 9 the opening, and the metal door has been secured
 10 with a threaded metal rod (Fig. C169).



Figure C170. Room 009 - View looking east from Room 010.



Figure C171. Doorway in west wall accessing Room 010.



Figure C172. Stair to main level.

- 1 door is hung with three typical ball-pin hinges and
- 2 has typical hardware. Both doorways have typical
- 3 rounded-corner casings.

Windows

- 4 The room has no windows.

Finishes

- 5 The walls, doors, and trim are painted white. The
- 6 tile flooring is cream colored.

Staircase

- 7 A concrete staircase measuring 3'-8" wide consists
- 8 of twelve 10" deep treads with squared nosings and
- 9 thirteen 7 ½" tall risers. Metal grip plates line the
- 10 edge of each tread. Rounded, wall-mounted wood
- 11 railings line both sides of the staircase (Fig. C172).

Mechanical Systems

- 12 There is no apparent evidence of any mechanical
- 13 systems.

Electrical System

- 14 A surface-mounted light switch is just west of the
- 15 exterior door.

Plumbing System

- 16 There is no apparent evidence of any plumbing
- 17 system.

Fire Protection and Life Safety

- 18 Remnants of a lighted exit sign hang above the
- 19 north doorway.

Room 010 – Compressor Room

- 20 Most recently serving as food storage, Room 010
- 21 measures 6'-7" by 9-10 ½" with a floor to ceiling
- 22 height of 7'-9" (Figs. C173-C175).

Flooring

- 23 Vinyl composition tile matching that found in
- 24 Room 010 is consistent throughout the majority of
- 25 the room, with the exception of the area beneath
- 26 the stairs, which has a painted concrete floor.

Baseboards

- 27 The room has no baseboards.

Walls and Ceiling

- 28 The north and south walls are poured-in-place
- 29 concrete; all other walls are flush-pointed CMU.
- 30 The ceiling is poured-in-place concrete.

Doorways

- 31 The doorway in the east wall to Room 009 is
- 32 described in the *Room 009 – Basement Vestibule*
- 33 section. The doorway has a typical rounded-corner
- 34 casing.



Figure C173. Room 010 - Oblique view looking northeast.



Figure C174. Room 010 - Oblique view looking southwest.

- 1 The doorway in the west wall leading to Room
- 2 011 lacks a door, but measures 2'-3 1/4" wide by
- 3 about 6'-5" tall. Leafs of two modern, 5-knuckle
- 4 butt hinges remain on the south jamb. The lintel-
- 5 cut plank board casing measures about 5" wide
- 6 (Fig. C174).

Windows

- 7 A three-horizontal-light window on the north wall
- 8 has a handle operator. The opening has a typical
- 9 rounded sill and molded apron (Fig. C175).

Finishes

- 10 The walls, doors, and trim are painted white. The
- 11 tile flooring is cream colored. The floor beneath
- 12 the stairs is painted blue-green.

Mechanical Systems

- 13 Pipes supplying hot water to the radiator in Room
- 14 105A above run along the east wall and above the
- 15 window (Fig. C173).

Electrical System

- 16 A 4'-0" long fluorescent tube fixture is centered on
- 17 the ceiling (Fig. C174).

- 18 A surface-mounted receptacle is on the west wall.
- 19 A surface-mounted light switch is south of the
- 20 doorway to Room 009.



Figure C175. Room 010 - View looking north.

Plumbing System

- 21 There is no apparent evidence of any plumbing
- 22 system.

Fire Protection and Life Safety

- 23 A surface-mounted, hard-wired smoke detector is
- 24 on the ceiling.

Other Features

- 25 Modern wood shelving with metal angled brackets
- 26 is mounted on the south and east walls
- 27 (Figs. C173-C174).

Room 011 – Coal Bunker No. 2

- 1 Originally a second coal bunker but most recently
 2 used for flour storage, Room 011 measures 9'-10
 3 ½" by 11'-0" with a ceiling height of 7'-9" (Figs.
 4 C176-C177).

Flooring

- 5 A painted, poured-in-place concrete floor is
 6 consistent throughout the room.

Baseboards

- 7 The room has no baseboards.

Walls and Ceiling

- 8 The ceiling and walls are all poured-in-place
 9 concrete, with the exception of the east wall, which
 10 is flush-pointed CMU.

Doorways

- 11 The doorway in the east wall leading to Room 010
 12 is described in the *Room 010 – Compressor Room*
 13 section. The Room 011 side of the opening has no
 14 casing.

Windows

- 15 The room has no windows.

Finishes

- 16 The walls and ceiling are painted white, the floor is
 17 painted blue-green.

Mechanical Systems

- 18 Refrigerant lines leading from the walk-in freezer
 19 on the main level above pass through the north
 20 wall to the compressor unit beneath the exterior
 21 staircase.

Electrical System

- 22 A 4'-0" long fluorescent tube fixture is centered
 23 on the ceiling. Wires leading to the fixture pass



Figure C177. Room 011 - View looking west.

- 24 through the wall to Room 010. A surface-mounted
 25 receptacle is on the east wall.

Plumbing System

- 26 A wall-mounted lavatory is mounted in the
 27 southeast corner, connecting to a PVC drain pipe
 28 which in turn drains to a cast iron drain and vent
 29 stack (Fig. C176).

Fire Protection and Life Safety

- 30 No fire protection or life safety equipment was
 31 observed.

Other Features

- 32 A top-hinged cast metal coal door on the west wall
 33 is described in the *Exterior Features* section.

Room 101A – Dining Room

- 34 Serving as the dining room and the coffee shop's
 35 most characterizing space, Room 101A measures
 36 about 28'-1" in the north-south direction by 59'-3"
 37 in the east-west. The roof ridge measures about
 38 19'-3" from the floor (Figs. C178-C181).

Flooring

- 39 Asphalt tile measuring 9" by 9" is consistent
 40 throughout the majority of the dining room. Some
 41 patched areas behind the counter along the north
 42 wall are replacement 12" by 12" square vinyl tiles.

- 43 The majority of the original tile floor is intact and
 44 is laid in a checkerboard pattern. Two, two-tile
 45 wide bands run east-west, aligned with posts of the
 46 center structural bay. A one-tile-wide border lines
 47 the exterior walls.

- 48 The field of the floor is made up of dark green
 49 tiles with an off-white marble-veining pattern, and
 50 off-white tiles with a grey marble-veining pattern.



Figure C176. Room 011 - View looking east.



Figure C178. Room 101A - Overview looking west.



Figure C179. Room 101A - Oblique view looking northeast.



Figure C180. Room 101A - Oblique view looking southeast.

- 1 The east-west banding and perimeter border tile
- 2 has a green and off-white scuff-mark pattern (Fig.
- 3 C182).
- 4 At the east end of the counter, a section of the original
- 5 floor tile has been replaced with early 9x9 tile in a
- 6 black-and-white checkerboard pattern (Fig C192).
- 7 The majority of the area behind the counter has
- 8 12" by 12" cream-colored vinyl tile (Fig. C195).

Baseboards

- 9 A 7 1/2" tall by 3/8" thick baseboard with 3/8" tall
- 10 beveled cap is consistent throughout the room (Fig.
- 11 C183). At the base of each freestanding post, a 6"
- 12 tall concrete plinth was originally wrapped with
- 13 vinyl or asphalt wall base, since removed (Fig. C184).

Walls and Ceiling

- 14 The north, south, and east walls are clad with
- 15 V-groove paneling with measurements varying



Figure C181. Room 101A - View looking northeast from entryway (Room 101B).




Figure C182. Coloration and pattern of flooring in Room 101A. Note black perimeter border and band in-line with structural post.



Figure C183. Typical v-groove paneling and baseboard in Room 101A. This area at the east end of the north wall is likely an example of the original wall finish.

- 1 between 3 ¼", 5 ¼", and 7 ¼" wide. The boards
- 2 are applied in a semi-regular repeating pattern
- 3 (Fig. C183). Cove molding measuring about 7/8" is
- 4 applied at the top of the paneling on the north and
- 5 south walls (Fig. C185).
- 6 The west wall is finished with plaster. Timber
- 7 members are exposed on the wall surface (Fig. C186),
- 8 At the gable end of the east wall, a louvered vent
- 9 is made up of horizontal weatherboard with an
- 10 approximately 8" exposure. The west gable end has
- 11 similar, horizontal weatherboard cladding.
- 12 The timber roof framing and roof joists are
- 13 exposed on the ceiling and are described in detail
- 14 in the *Structural Systems* section.



Figure C184. Concrete plinth at base of structural post.



Figure C185. Typical cove molding at top of paneling.



Figure C187. Louvered gable on west wall, partially obscured by plastic.



Figure C188. Weatherboard gable on east wall.

- 1 On the west wall, recessed panels with vertical
- 2 spindles bookend the two serving windows. The
- 3 spindles measure 1 1/8" square, and are turned
- 4 on-point. The spindles have a 2 1/2" long taper at
- 5 their top and base, ending in a 1-3/16" diameter
- 6 round peg embedded in the sill and header of the
- 7 serving window openings (*Figs. C186, C191*).

Doorways

- 8 The exterior door on the east wall is described in
- 9 the *Exterior Features* section. The interior casing is
- 10 lintel-cut and measures about 5" wide. Two push-
- 11 bars are mounted on the interior, one of which is
- 12 detached from the door (*Fig. C189*).



Figure C189. Interior view of east doorway.



Figure C186. Plaster finish on west wall.

- 13 The doorway in the west wall leading to Room
- 14 102 holds a one-light flush-panel door measuring
- 15 3'-0" wide by 6'-11" tall by 1 7/8" thick. The door
- 16 is made up of V-groove boards ranging between
- 17 4" and 9" wide (*Fig. C186*). The door is hung with
- 18 a swivel hinge mounted in the floor and rotating
- 19 pin at the top, allowing the door to operate in both
- 20 directions. The lower two-thirds of the door is
- 21 wrapped with stainless steel. A metal push bar is



Figure C190. South ribbon windows viewed from interior.



Figure C191. Example of serving window on west wall. Note spindles on both sides of the opening.

1 mounted near the center of the door's height. The
 2 door's casing is formed by an 8x8 structural post
 3 on the northern side, a 6x6 post on the south, and
 4 an 8" tall beam spanning the top of the doorway
 5 (Fig. C186).

Windows

6 Typical two-over-one-light awning sash windows
 7 are present in all window openings. All awning
 8 sash have the same prop-rod type operation, and
 9 many of the windows have intact hardware. All
 10 screen sashes have been removed, though several
 11 examples of screen sash brackets remain.

12 On the south wall, eight windows of this design form
 13 a continuous band, punctuated by wood mullions
 14 where the roof framing posts meet the south wall
 15 (Figs. C180, C190). The large opening has a 1'-4"
 16 deep rounded sill with typical molded apron.

17 The east wall has one paired and one single
 18 window opening with typical quarter-round trim

19 applied flush with the surrounding panelling and
 20 typical molded aprons.

21 The north wall has two paired openings and one
 22 single window opening matching the detailing of
 23 the east wall.

24 Two serving windows along the west wall open to
 25 Room 102, and are fitted with vertically-sliding
 26 shutters made up of V-groove boards ranging
 27 between 7" and 9" wide (Figs. C186, C191). The
 28 northern opening measures 4'-6" wide by about
 29 3'-0" tall, while the southern opening measures
 30 6'-0" wide by 3'-0" tall. The jambs of both
 31 windows consist of 3x6 chamfered posts. The
 32 header is formed by an 8" tall beam. An off-white
 33 laminate counter top with rounded edges fills the
 34 base of the opening.

Casework

35 An original rear counter with base cabinet and
 36 two-tiered black counter top extends the majority
 37 of the north wall and measures about 34'-0" long
 38 by 1'-6" deep overall (Fig. C192). The length of the
 39 counter is divided into openings holding flush-
 40 panel, V-groove sliding doors that run on metal
 41 tracks. Recessed hand holds are carved into the
 42 face of each door. Currently the counter is lifted
 43 on wood blocks and the doors have been removed
 44 and stored within the building. Similar casework
 45 is found on the south wall in the gift shop area, and
 46 has three original wood upper shelves (Fig. C193).



Figure C192. Rear counter. Note replacement tile.



Figure C193. Original casework on south wall in gift shop area.



Figure C195. Back of serving counter showing general condition. Note replacement tile.

1 The original serving counter measures about 3'-7"
 2 tall by 24" deep and extends about 30'-0" in the
 3 east-west direction (Figs. C181, C194-C195). The
 4 counter is largely of plywood construction, with
 5 shelving on the rear behind a veneered plywood
 6 face. The foot rest at the base of the counter
 7 measures 9" from the floor and 10 ½" deep. The
 8 counter top extends 8" from the face of the base
 9 and measures 1 ½" thick, with a black laminate top
 10 and stainless steel band (Fig. C194-C195).

11 Modern cabinets form an L-shaped partition that
 12 delineates the gift shop area. The cabinet running
 13 east-west measures about 13'-0" long by 1'-7"
 14 deep, while the one running north-south measures
 15 about 5'-0" long by 1'-0" deep (Figs. C178, C181,
 16 C196) The east-west cabinet is attached to a back
 17 panel made up of V-groove boards. An opening in
 18 the back panel allows views into the gift shop from
 19 the dining room; the shelving above the east-west
 20 cabinet is open to the dining room. The wood base



Figure C196. Modern cabinets forming gift shop area.

21 cabinets have flush-panel grooved doors hung with
 22 cabinet hinges. The counter top is black laminate.
 23 Wood shelves with laminate top surfaces lie above
 24 the base cabinets; shelves above the east-west
 25 counter are adjustable.

Finishes

26 The majority of the walls and trim are painted
 27 varying shades of dark brown. Examples of an
 28 early satin semi-clear finish can be found on the
 29 east gable end, as well as many areas along the
 30 north wall (Figs. C.183, C188).

31 Timber framing has been largely painted brown up
 32 to the underside of the roof beams. A semi-clear
 33 finish similar to the original wall finish is typical on
 34 the highest framing members.

35 The plaster walls are painted a peach color.

36 The casework along the north and south walls are
 37 painted dark brown.



Figure C194. Front of serving counter.



Figure C197. Typical original bar stool.

- 1 The face of the counter is furniture-grade veneer
- 2 plywood with a maple stain.
- 3 The fiber insulation board exposed on the ceiling is
- 4 a reddish-brown color.

Other Features

- 5 Seven original bar stools line the outside of the
- 6 serving counter. The stool seats rest on a 4"
- 7 diameter metal post with 8 ½ diameter base collar.
- 8 Each seat measures about 1'-2" square and sits at
- 9 a height of 2'-7" from the floor. The overall height
- 10 measures 3'-6" to the top of the back rest. The seats
- 11 are covered with light-brown vinyl.
- 12 A wood partition made up of vertical pickets is at
- 13 the east end of the serving counter (*Fig. C179*).

Mechanical Systems

- 14 Wall-mounted radiators with blower fans are in the
- 15 northeast and southeast corners.
- 16 An original ventilation hood with decorative
- 17 grooves at its base is on the north wall near the
- 18 west end (*Fig. C198*). The hood vents to a large duct
- 19 that passes through the exterior wall. A stainless
- 20 steel case below the hood has had all equipment
- 21 removed
- 22 A thermostat is mounted on the structural post at
- 23 the east corner of the gift shop.

Electrical System

- 24 Four original three-lamp rustic light pendant
- 25 fixtures with red shades are equally-spaced across



Figure C198. Original stainless steel hood on north wall.



Figure C199. Typical original three-lamp fixture.



Figure C200. Typical early one-lamp fixture.



Figure C201. Typical track lighting fixtures. Note earlier fixture boxes mounted on side of beam.

32 Capped pipes for a sink are near the center of the
 33 bar.
 34 Flexible water hoses are mounted to a plywood
 35 panel on the north wall, at the far east end of the
 36 rear counter (Fig. C202).
Fire Protection and Life Safety
 37 Wired smoke detectors are surface-mounted on
 38 the underside of the north-south running beams
 39 near the ridge.
 40 A fire alarm beacon is mounted on the west wall.
 41 Remnants of a lighted exit sign remain above the
 42 east doorway (Fig. C189).

1 the center line of the room, mounted on the
 2 underside of the major north-south beams
 3 (Fig. C199). The lights are missing their glass
 4 chimneys.

5 Eight early single-lamp rustic fixtures are mounted
 6 on the north-south beams of the two side aisle
 7 areas (Fig. C200). These fixtures are also missing
 8 glass chimneys.

9 Modern track lighting with black cylindrical
 10 fixtures is mounted above the counter and gift
 11 shop. The majority of these fixtures are in poor
 12 condition. On the north side of major east-west
 13 beam above the counter, blanked fixture boxes for
 14 the original spotlights seen in historic photographs
 15 remain (Fig. C201).

16 With the exception of a few added outlets at the
 17 east end of the north wall, all outlets in the dining
 18 room are recessed. In-floor outlets with brass
 19 covers are common throughout the southern half
 20 of the room.

21 At the far end of the counter that abuts the north
 22 wall are two disconnect switches, one of which is
 23 labeled "ice maker" (Fig. C202).

24 An electrical sub panel is mounted beneath the
 25 east end of the serving counter (Fig. C203). The
 26 majority of the junction boxes and flexible conduit
 27 feeding the panel have been dismantled and are
 28 hanging behind the face of the bar (Fig. C195).

Plumbing System

29 A shadow remains near the west end of the north
 30 wall for a wall-mounted lavatory with mirror.
 31 Plumbing lines have been capped.



Figure C202. Flexible water lines and disconnect switches on north wall.



Figure C203. Electrical sub panel beneath east end of serving counter.



Figure C204. Firehose cabinet on south wall.

1 Remnants of emergency lights are on the west
2 wall and on the freestanding post nearest the east
3 doorway.

4 A firehose cabinet is on the south wall, at the east
5 end of the windows. The cabinet appears empty
6 (Fig. C204).

7 Room 101B – Entryway

8 Room 101B serves as the main entrance foyer and
9 opens to Room 101A at the northeast corner. The
10 room measures about 22'-0 by 11'-0"
11 (Figs. C205-C206).

Flooring

12 The flooring matches that of Room 101A and is
13 scribed in the *Room 101A - Dining Room* section.

Baseboards

14 The baseboards match those found in Room 101A,
15 with the exception of the south wall, which has a
16 plank baseboard measuring about 5" tall.

Walls and Ceiling

17 The south and east walls are finished with
18 V-groove wood paneling matching that of Room
19 101A. The north and west walls are plaster with
20 exposed timber framing elements. Significant
21 water damage is visible at the top of the north wall
22 at the ceiling (Fig. C207).

23 The timber roof framing and roof joists are
24 exposed on the ceiling and are described in
25 detail in the *Structural Systems* section. Staining



Figure C205. Room 101B - View looking west.



Figure C206. Room 101B - Oblique view looking northeast.

26 associated with previous roof leak is visible along
27 the north wall (Fig. C207).

28 A recess in the wall above the south doorways
29 has wood spindles matching those at the serving
30 windows described in the *Room 101A - Dining
31 Room* section (Fig. C208).

Doorways

32 The paired doorways on the south wall are
33 described in the *Exterior Features* section.



Figure C207. Water damage along north wall in Room 101B.



Figure C208. Spindle detail above south doorways.



Figure C209. Concealed closet door in southeast corner. Note damage to right jamb.

1 Two doorways on the west wall hold typical
 2 V-groove doors measuring 2'-8" wide by 7'-0"
 3 tall by 1 3/4" thick (Fig. C205). The doors are hung
 4 with three typical ball pin hinges and have closers.
 5 Stainless steel push plates are mounted on the
 6 101B side of the doors. Both doorways have typical
 7 casings. The door to the women's bathroom retains
 8 an original metal sign depicting the silhouette of a
 9 woman and child.

10 Two concealed closet doorways on the south wall
 11 are made up of the same V-groove boards as the
 12 surrounding wall paneling (Fig. C209). Both doors
 13 measure 1'-10" wide by 6'-6" tall by 1 3/4" thick, and
 14 are hung with concealed hinges. The east closet
 15 door has typical mortised hardware; the west has
 16 a chrome cabinet pull handl, as well as a deadbolt
 17 and barrel bolt. The jamb of the east doorway has
 18 been damaged where the door was likely forced
 19 open.

Windows

20 The room has no windows.

Casework

21 Original base cabinets with shelving above wrap
 22 around the corner from Room 101A and line the
 23 east wall (Fig. C209).

Finishes

24 The majority of the walls and trim are painted
 25 varying shades of dark brown. Examples of an
 26 early satin semi-clear finish can be found on the
 27 south and east walls (Fig. C208).

28 Timber framing has been largely painted brown up
 29 to the underside of the roof beams. A semi-clear
 30 finish similar to the original wall finish is typical on
 31 the highest framing members.

32 The plaster walls are painted a peach color.

33 The casework along the east wall is painted dark
 34 brown.

35 The fiber insulation board exposed on the ceiling is
 36 a reddish-brown color.

Closets

37 The east closet is lined with V-groove wood
 38 paneling and has wood shelving.

39 The west closet is finished with plaster and
 40 contains an electrical panel and single surface-
 41 mounted fixture (Fig. C210).




Figure C210. Interior of closet in southwest corner.

Baseboards

21 Terracotta base tiles matching the coloration of
 22 the flooring measure 6" by 6". The tiles angle
 23 outward at their base due to being applied over the
 24 existing base tile integrated into the original tile
 25 wainscoting (Fig. C213).

26 The base of the two timber posts rest on concrete
 27 plinths covered with thin reddish-brown terrazzo
 28 tile.

Walls and Ceiling

29 A salt-glazed tile wainscot extends to a height of
 30 4'-0" from the floor, each tile measures 7 5/8" wide
 31 by 5" tall (Fig. C213). On the north face of the
 32 chimney, the glazed tile extends the full height of
 33 the room. The walls above the wainscoting are
 34 constructed of flush-pointed CMU, giving the
 35 walls a smooth appearance. The ceiling is plaster.

36 Much of the ceiling on the west side of the room is
 37 covered with plastic sheeting.

Mechanical Systems

1 A wall-mounted radiator with blower fan is in the
 2 northwest corner (Fig. C205).

Electrical System

3 An original three-lamp pendant fixture matching
 4 those in Room 101A is centered above on the
 5 ceiling (Fig. C205).

6 A modern track light matching those in Room
 7 101A is mounted near the pendant fixture.

8 Two receptacles attached to flexible metal conduit
 9 extend from the floor near the end of the north
 10 wall.

Plumbing System

11 There is no apparent evidence of any plumbing
 12 system.

Fire Protection and Life Safety

13 Remnant of a lighted exit sign remain centered
 14 over the paired doorways to the vestibule (Room
 15 108).

Room 102 – Kitchen

16 Room 102 is the main kitchen space and measures
 17 about 19'-8" by 22'-3" with a floor to ceiling height
 18 of about 10'-0" (Figs. C211-C212).

Flooring

19 Terracotta tile flooring laid over the original
 20 flooring measures 6" by 6" (Fig. C213).



Figure C211. Room 102 - Oblique view looking southeast.



Figure C212. Room 102 - Oblique view looking northwest.



Figure C213. Terra cotta tile floor, base tile, and salt-glazed tile wainscoting.



Figure C215. Detail of window and sill in Room 102.



Figure C214. Doorway on west wall. Note remaining partial hinges.

1 The timber-frame structural system is exposed below
 2 the ceiling. Chamfered posts and beams are nearly
 3 flush with the north and east walls. Two 8x8 posts,
 4 one near the center of the room and one at the west
 5 wall, are connected by metal corner plates to a beam
 6 running east-west across the ceiling (Fig. C211).

Doorways

7 A doorway near the center of the east wall leads to
 8 Room 101A and is described in the *Room 101A –*
 9 *Dining Room* section.

10 The doorway at the south end of the west wall leads
 11 to Room 103 (Fig. C214). The opening lacks doors
 12 and measures 3'-8" wide by 6'-8" tall, and once held
 13 a pair of doors measuring 1 3/4" thick based on the
 14 size of the jamb. Three partial typical ball-pin hinges
 15 are incised into both sides of the opening. The
 16 doorway has typical rounded-corner casings.

Windows

17 Two paired sets of typical first-floor three-
 18 horizontal light windows are on the north wall.
 19 All awning sash have prop rod operators. The
 20 window openings lack casings, but do have an
 21 inset miter-cut cove molding measuring 1" wide
 22 within the masonry opening. A rounded piece
 23 of trim measuring about 2 1/2" wide by 3/4" thick
 24 meets the steel-sash window. The sill is formed by
 25 rounded salt-glazed tile that also serve to cap the
 26 wainscoting along the north wall (Fig. C215).

27 The eastern window of the western pair is partially
 28 obstructed by a wood panel constructed to mount
 29 the large main electrical panel.

30 Two serving windows along the east wall open to
 31 Room 101A, and are described in the *Room 101A*
 32 *- Dining Room* section. Both shutters are held in
 33 place by a wood track on either side. Metal straps
 34 connect the shutters to spring-return mechanisms
 35 near the ceiling. Two pull handles near the base of
 36 the shutters allow the shutters to be lifted from the
 37 kitchen side (Figs. C211, C216).

Finishes

38 The ceiling and upper portion of the walls are
 39 painted white, as is the casing on the west doorway
 40 and window sash. All other trim, as well as the
 41 exposed structural members, are painted brown.



Figure C216. Serving window and pot rack in southeast corner.

- 1 The salt glazed tile wainscoting has a satin finish
- 2 and is a sandy brown color.
- 3 The terracotta floor tile is reddish brown with
- 4 some darker variegation.

Mechanical Systems

- 5 A stainless-steel ventilation hood adjacent to the
- 6 north side of the chimney measures 5'-10 1/2"
- 7 square (Fig. C211).
- 8 A ceiling opening near the center of the west wall
- 9 serves a second ventilation fan, which connects
- 10 through an attic duct to a roof-mounted fan.

Electrical System

- 11 A total of eight 4'-0" long, surface-mounted
- 12 fluorescent tube fixtures are mounted on the
- 13 ceiling. Originally these fixtures likely had
- 14 translucent covers.
- 15 Five fixture sockets are mounted on the inside edge
- 16 of the large ventilation hood.



Figure C217. Electrical box and cleanout on north face of chimney.

- 17 A large 800 amperes electrical panel is mounted
- 18 on the north wall between the paired window
- 19 openings. A large junction box just below the panel
- 20 is connected to flexible conduit that likely served
- 21 various kitchen equipment, since removed (Figs.
- 22 C212-C213). A similarly-sized electrical junction
- 23 box is mounted on the west face of the chimney,
- 24 and is connected to three large rigid conduits; these
- 25 lines likely served the main stove (Fig. C217).

- 26 Receptacles and light switches vary between
- 27 recessed and surface-mounted, and are found on
- 28 all four walls.

Plumbing System

- 29 A three-basin, stainless steel sink is near the
- 30 western end of the south wall (Fig. C218).
- 31 A wall-mounted lavatory is just north of the
- 32 doorway to Room 103 (Fig. C219).



Figure C218. Stainless steel sink on south wall.




Figure C219. Lavatory on west wall.

- 1 Two 6" by 6" floor drains with metal grates are in
- 2 the northwestern quadrant of the room.

Fire Protection and Life Safety

- 3 A ProTex-branded fire extinguisher is mounted on
- 4 the east side of the chimney, and is connected to
- 5 a fire suppression system beneath the ventilation
- 6 hood (Fig. C52).

- 7 A ceiling-mounted smoke detector is near the
- 8 center of the room.

Other Features

- 9 Cleanouts on the north and east sides of the
- 10 chimney have hinged metal doors and measure
- 11 1'-0" wide by 8" tall (Fig. C217).
- 12 A likely-original ceiling-mounted pot rack above
- 13 the southern serving window measures 12'-0" in
- 14 the north-south direction by 8'-0" in the east-west
- 15 (Fig. C216).

Room 103 – Stair Hall

- 16 Room 103 consists of a passageway connecting
- 17 Rooms 102, 104, and 105, and contains the
- 18 staircase leading to the basement vestibule (Room
- 19 009). The area at the top of the stairs measures
- 20 about 3'-8" by 5'-0"; the full length of the space
- 21 over the stairs is about 19'-8" (Figs. C220-C221).



Figure C221. Room 103 - Oblique view looking southeast into Room 104.

Flooring

- 22 The terracotta tile flooring measures 6" by 6".

Baseboards

- 23 Terracotta base tiles matching the coloration of the
- 24 flooring measure 6" by 6".

Walls and Ceiling

- 25 All walls are of flush-pointed CMU construction;
- 26 the ceiling is plaster.

Doorways

- 27 Doorways on the east and west walls lead to
- 28 Rooms 102 and 105, respectively, and identical. The
- 29 doorway to Room 102 is described in the *Room 102*
- 30 – *Kitchen* Section.

- 31 The doorway in the south wall accesses Room
- 32 104 and holds a typical flush-panel V-groove
- 33 door measuring 2'-5 1/2" wide by 6'-7 1/2" tall by 1
- 34 3/4" thick (Fig. C221). The door is hung with three
- 35 typical hinges and has a typical mortised lockset.
- 36 The base of the door has an approximately 8" tall
- 37 kick plate. All doorways have typical casings.

Windows

- 38 A typical two-light steel awning window on the
- 39 north wall above the stairs is part of a paired window




Figure C220. Room 003 - View looking north.

- 1 opening shared with the adjacent Room 105. The
 2 window opening lacks casings, and has typical trim
 3 of a main level window opening in a masonry wall.
 4 The opening has a typical sill and apron.

Crown Molding

- 5 Cove molding measuring about 1" tall runs the
 6 perimeter of the ceiling.

Finishes

- 7 All elements are painted white, with the exception
 8 of the floor tile, which is reddish brown with some
 9 darker variegation.

Mechanical Systems

- 10 There is no apparent evidence of any mechanical
 11 systems.

Electrical System

- 12 Two surface-mounted 4'-0" long fluorescent tube
 13 fixtures are centered toward the south end of the
 14 ceiling.

Plumbing System

- 15 There is no apparent evidence of any plumbing
 16 system.

Fire Protection and Life Safety

- 17 There is no apparent evidence of any fire
 18 protection or life safety systems.



Figure C222. Room 104 - View looking west.

Room 104 – Employee Toilet

- 19 Room 104 measures about 2'-9 ½" by 11'-5" with a
 20 ceiling height of about 8'-1" (Figs. C221-C222).

Flooring

- 21 Terrazzo flooring is consistent throughout the
 22 room (Fig. C222). Ghost marks remain for a
 23 removed bathroom stall partition separating the
 24 western portion of the room.

Baseboard

- 25 The room has no baseboards; however, the salt-
 26 glazed tile wainscoting has a curved base tile
 27 (Fig. C222).

Walls and Ceiling

- 28 All walls are of flush-pointed CMU construction;
 29 the ceiling is plaster. Salt-glazed tile wainscoting
 30 matching that described in Room 102 extends to a
 31 height of 4'-0" from floor level.

Doorways

- 32 A doorway at the east end of the north wall
 33 accesses Room 103, and is described in the *Room*
 34 *103- Stair Hall* section. The Room 104 side of the
 35 door has a chrome knob, 2 ½" long barrel bolt, and
 36 is equipped with a closer. The doorway has typical
 37 miter-cut, rounded-corner casing measuring 2 ½"
 38 wide by ¾" thick.

Windows

- 39 One six-light wood-sash hopper window is near
 40 the eastern end of the south wall. The opening has
 41 no casing; however a cove molding trim measuring
 42 1" wide is inset within the masonry opening. The
 43 sill is formed by rounded salt-glazed tile.

Finishes

- 44 The ceiling and upper portion of the walls are
 45 painted white, as is the door and door casing.
 46 The window sash and trim is painted brown. The
 47 salt glazed tile wainscoting has a satin finish and is
 48 a sandy brown color.
 49 The terrazzo flooring is reddish-brown with darker
 50 brown aggregate.

Mechanical Systems

- 51 Radiator pipes remain beneath the window, though
 52 the radiator itself has been removed.

Electrical Systems

- 53 A 4'-0" long fluorescent tube fixture is mounted on
 54 the ceiling.

- 1 A modern sconce fixture is centered over the
- 2 lavatory on the east wall.

Plumbing Systems

- 3 A wall-mounted lavatory is on the east wall. A toilet
- 4 is centered on the west wall.

Fire Protection and Life Safety

- 5 There is no apparent evidence of fire protection or
- 6 life safety systems.

Other features

- 7 A chrome-framed mirror is mounted above the
- 8 sink.

Room 105A – Storage Room

- 9 Room 105A measures about 18'-6" by 20'-8" at its
- 10 widest points with a ceiling height of about 8'-1"
- 11 (Figs. C223-C225). The room's primary purpose was
- 12 food storage.

Flooring

- 13 Terracotta tile flooring measures 6" by 6".
- 14 The doorway to the walk-in cooler (Room 105B) is
- 15 accessed by a small concrete step measuring about
- 16 2'-8" wide by 10" deep by 6" tall (Fig. C226).

Baseboards

- 17 Terracotta base tiles matching the coloration of the
- 18 flooring measure 6" by 6".

Walls and Ceiling

- 19 All walls are of flush-pointed CMU construction;
- 20 the ceiling is plaster. The partition wall separating
- 21 the walk-in cooler is finished with plywood panels.
- 22 A vertical opening at the north end of the north-
- 23 south wall of the cooler has been covered in plastic.



Figure C223. Room 105A - Oblique view looking northeast.



Figure C224. Room 105A - Oblique view looking southeast.



Figure C225. Room 105A - Oblique view looking southwest.

Doorways

- 24 A doorway in the east wall leading to Room 003 is
- 25 described in the *Room 003- Stair Hall* section.
- 26 The doorway to a janitor's closet on the south
- 27 wall holds a typical flush-panel V-groove door
- 28 measuring 2'-6" wide by 6'-7 1/2" tall by 1 3/4" thick
- 29 (Fig. C224). The door is hung with three typical
- 30 ball-pin hinges and has typical hardware.
- 31 The exterior doorway on the west wall is described
- 32 in the *Exterior Features* section.
- 33 An insulated, flush-panel plywood-clad door on
- 34 the south wall of the walk-in cooler measures
- 35 2'-10" wide by 6'-3" tall by 5" thick (Fig. C226). The
- 36 door is hung with two 14" long hinges and has a
- 37 10" long lock mechanism.
- 38 All doorways, with the exception of the door to
- 39 Room 105B have typical casings. The doorway to
- 40 the cooler has no casing.



Figure C226. Doorway to walk-in cooler (Room 105B).




Figure C227. Janitor's sink in closet in Room 105A

Windows

1 A typical two-light steel awning window at the
 2 far east end of the north wall is part of a paired
 3 window opening shared with the adjacent Room
 4 103 (Fig. C223). The window opening lacks casings,
 5 and has typical trim of a main level window
 6 opening in a masonry wall. The opening has a
 7 typical sill and apron.

8 A six-light wood-sash hopper window is near the
 9 center of the south wall, west of the closet (Fig.
 10 C225). The opening has no casing; however a cove
 11 molding trim measuring 1" wide is inset within the
 12 masonry opening. The sill and side jambs of the
 13 window are formed by rounded-corner CMU.

Crown Molding

14 Cove-and-ovolo crown molding measuring about 1
 15 ½" tall lines all but the eastern portion of the north
 16 wall.

Finishes

17 All elements are painted white, with the exception
 18 of the floor tile, which is reddish brown with some
 19 darker variegation.

Mechanical Systems

20 A radiator beneath the north window measures
 21 2'-8" wide by 7 ½" deep by 2'-1" tall.

22 An ice machine is vented through the ceiling
 23 adjacent to the north wall of the cooler. The
 24 machine vents to the attic space above.

Electrical System

25 A total of six 4'-0" long, surface-mounted
 26 fluorescent tube fixtures are mounted on the
 27 ceiling. Originally these fixtures likely had
 28 translucent covers.

29 Wall switches and receptacles vary between
 30 surface-mounted and recessed installations.

Plumbing System

31 A two-basin, stainless steel sink is on the south wall
 32 beneath the window (Fig. C225).

33 PVC drain pipes serving both the ice machine and
 34 likely the walk-in cooler pass through the floor slab
 35 at the corner of the partition wall.

36 A wall-mounted janitor's sink is on the south wall
 37 of the closet (Fig. C227).

Fire Protection and Life Safety

38 A ceiling-mounted, hard-wired smoke detector is
 39 near the center of the room.

40 A fire alarm beacon is mounted above the closet
 41 door on the north wall (Fig. C224).



Figure C228. Attic access hatch in southeast corner of Room 105A.



Figure C229. Room 105B - Oblique view looking northwest.

Closet

- 1 Plank board shelf supports line the south, east, and
- 2 west sides of the closet. Closet flooring appears
- 3 to be modern peel-and-stick vinyl tile. Supply and
- 4 vent piping for the adjacent bathroom (Room 104)
- 5 are on the east wall (Fig. C227).

Other Features

- 6 Improvised wood shelving lines the south
- 7 wall above and to the west of the window, and
- 8 continues about the west doorway. A second
- 9 section of shelving is above the doorway to Room
- 10 103 (Figs. C224-C225).
- 11 An opening in the ceiling measuring 2'-7" by 2'-4"
- 12 ½" holds a plywood hatch accessing the unfinished
- 13 attic space above (Fig. C228).

Room 105B – Walk-in Cooler

- 14 Room 105B is an insulated room created by
- 15 partition walls in Room 105A. The space is early
- 16 if not original and measures about 9'-3" by 9'-7"
- 17 (Figs. C229-C230).

Flooring

- 18 The poured-in-place concrete floor slab is exposed
- 19 throughout the room.

Baseboards

- 20 The room has no baseboards.

Walls and Ceiling

- 21 Both the walls and ceiling are clad with plywood
- 22 panels. Several holes in the north wall have been
- 23 covered with plastic (Figs C229-C230).

Doorways

- 24 A doorway on the south wall leads to Room 105A
- 25 and is described in the *Room 105A Storage Room*



Figure C230. Room 105B - Oblique view looking southeast.

- 26 section. The inside of the doorway has no casing;
- 27 however, there is a pull-release handle to allow the
- 28 latch to be operated from the inside (Fig. C230).

Windows

- 29 The room has no windows.

Crown Molding and Trim

- 30 Plank board crown molding and corner boards
- 31 measure about 3" wide (Figs. C229-C230).

Finishes

- 32 The plywood wall and ceiling panels are finished
- 33 with a clear varnish or urethane finish. The floor is
- 34 unpainted.

Mechanical Systems

- 35 A wall mounted coil unit along the north wall
- 36 works in conjunction with the compressor unit
- 37 beneath the exterior staircase (Fig. C229).

Electrical System

- 38 A single ceiling-mounted light fixture with rounded
- 39 glass globe and protective cage is near the doorway.

- 1 Switches and timers related to the coil unit are on
2 the north wall (Figs. C229-C230).

Plumbing system

- 3 A PVC condensate line runs from the coil unit
4 through the floor slab at the southeast corner.

Room 106A – Women’s Bathroom

Vestibule

- 5 Room 106A serves as a pass-through space
6 accessing the women’s bathroom (Room 106B).
7 The room measures about 3’-5” by 3’-6” with a
8 ceiling height of about 8’-11” (Fig. C231).

Flooring

- 9 The terracotta tile flooring measures 6” by 6”.

Baseboards

- 10 Ceramic base tiles measure about 4” by 6”.

Walls and Ceiling

- 11 Walls are finished with 4” by 4” ceramic tile; the
12 ceiling is plaster (Fig. C231).

Doorways

- 13 A doorway on the east wall leading to Room 101A
14 is described in the *Room 101B– Main Entryway*
15 section.



Figure C231. Room 106A - View looking south.

- 16 The doorway in the north wall leads to Room 106B
17 and holds a typical flush-panel V-groove door
18 measuring 2’-6” wide by 6’-7 ½” tall by 1 ¾” thick.
19 The door is hung with three typical ball-pin hinges.
20 The door is equipped with a closer and has a pull
21 handle on the Room 106B side. Both doorways
22 have typical casings.

Windows

- 23 The Room has no windows.

Finishes

- 24 The wall tile has a gloss glaze and is tan with brown
25 specs; the floor tile is reddish-brown; all trim is
26 painted brown.

Mechanical Systems

- 27 There is no apparent evidence of any mechanical
28 systems.

Electrical Systems

- 29 A surface-mounted light fixture is centered on the
30 ceiling.

Plumbing System

- 31 There is no apparent evidence of any plumbing
32 systems.

Fire Protection and Life Safety

- 33 There is no apparent evidence of any fire
34 protection or life safety systems.

Room 106B – Women’s Bathroom

- 35 Room 106B is L-shaped and measures about 9’-4”
36 by 10’-0” at its widest points with a ceiling height of
37 about 8’-11”.

Flooring

- 38 The terracotta tile flooring measures 6” by 6”.

Baseboards

- 39 Ceramic base tiles measure about 4” by 6”.

Walls and Ceiling

- 40 Walls are finished with 4” by 4” ceramic tile; the
41 ceiling is plaster.

Doorways

- 42 A doorway on the south wall leading to Room
43 106A is described in the *Room 106A – Women’s*
44 *Restroom Vestibule* section. The inside of the
45 doorway has a typical casing.

Windows

- 46 One six-light wood-sash hopper window is on the
47 west wall. The opening has no casing; however



Figure C232. Room 106B - Oblique view looking southwest.




Figure C233. Typical remaining stall partition brackets.

Fire Protection and Life Safety Systems

20 There is no apparent evidence of any fire
21 protection or life safety systems.

Other Features

22 Wall brackets remain for two stall partitions at the
23 north end of the room (Fig. C233).

Room 107A – Men’s Bathroom Vestibule

24 Room 106B serves as a pass-through space
25 containing the sink for the men’s bathroom (Room
26 107B). The room measures about 3’-5” by 5’-10”
27 with a ceiling height of about 8’-11”
28 (Fig. C234-C235).

Flooring

29 The terracotta tile flooring measures 6” by 6”.

Baseboards

30 Ceramic base tiles measure about 4” by 6”.

Walls and Ceiling

31 Walls are finished with 4” by 4” ceramic tile; the
32 ceiling is plaster (Fig. C234).

Doorways

33 A doorway on the east wall leading to Room 101A
34 is described in the *Room 101A – Entryway* section.

35 The doorway in the west wall leads to Room 107B
36 and holds a typical flush-panel V-groove door
37 measuring 2’-6” wide by 6’-7 ½” tall by 1 ¾” thick
38 (Fig. C234). The door is hung with three typical
39 ball-pin hinges. The door is equipped with a closer

1 a cove molding trim measuring 1” wide is inset
2 within the masonry opening. Rounded ceramic tile
3 matching the surrounding walls continues into the
4 window opening.

Finishes

5 The wall tile has a gloss glaze and is tan with brown
6 specs. The floor tile is reddish-brown; all trim is
7 painted brown.

Mechanical Systems

8 A floor-mounted radiator is beneath the window
9 and measures 1’-5 ½” wide by 3 ½” deep by 2’-1”
10 tall (Fig. C232).

Electrical Systems

11 Two four-foot fluorescent tube fixtures are
12 mounted on the ceiling.

13 Two modern sconces are centered over the
14 lavatories on the south wall.

15 A recessed light switch is near the doorway.

Plumbing System

16 Two toilets are on the east and west walls, at the
17 north end of the room.

18 Two wall-mounted lavatories are on the south wall
19 (Fig. C232).



Figure C234. Room 107A - Oblique view looking southwest.



Figure C235. Room 107A - View looking north.

1 and has a pull handle on the Room 107B side. Both
2 doorways have typical casings.

Windows

3 One six-light wood-sash hopper window is on the
4 south wall. The opening has no casing; however
5 a cove molding trim measuring 1" wide is inset
6 within the masonry opening. Rounded ceramic tile
7 matching the surrounding walls continues into the
8 window opening (Fig. C234).

Finishes

9 The wall tile has a gloss glaze and is tan with brown
10 specs; the floor tile is reddish-brown; all trim is
11 painted brown (Figs. C234-C235).

Mechanical Systems

12 There is no apparent evidence of any mechanical
13 systems.

Electrical Systems

14 One four-foot fluorescent tube fixtures are
15 mounted on the ceiling.

16 A modern sconce fixture is centered over the
17 lavatory on the east wall.

Plumbing System

18 A wall-mounted lavatory is on the east wall.

Fire Protection and Life Safety

19 There is no apparent evidence of any fire
20 protection or life safety systems.

Room 107B – Men's Bathroom

21 Room 107B measures about 5'-8" by 5'-7" with a
22 ceiling height of about 8'-11" (Fig. C236).

Flooring

23 The terra-cotta tile flooring measures 6" by 6".

Baseboards

24 Ceramic base tiles measure about 4" by 6".

Walls and Ceiling

25 Walls are finished with 4" by 4" ceramic tile; the
26 ceiling is plaster (Fig. C236).

Doorways

27 A doorway on the east wall leading to Room 107A
28 is described in the *Room 107A- Men's Restroom*
29 *Vestibule* section. The inside of the doorway has a
30 typical casing.

Windows

31 One six-light wood-sash hopper window is on the
32 west wall. The opening has no casing; however
33 a cove molding trim measuring 1" wide is inset




Figure C236. Room 107B - Oblique view looking northwest.



Figure C237. Room 108 - View looking west.

- 1 within the masonry opening. Rounded ceramic tile
- 2 matching the surrounding walls continues into the
- 3 window opening.

Finishes

- 4 The wall tile has a gloss glaze and is tan with brown
- 5 specs. The floor tile is reddish-brown; all trim is
- 6 painted brown.

Mechanical Systems

- 7 There is no apparent evidence of any mechanical
- 8 systems.

Electrical Systems

- 9 One four-foot fluorescent tube fixtures are
- 10 mounted on the ceiling.

Plumbing System

- 11 One toilet and one floor-mounted urinal are along
- 12 the north wall (Fig. C236).

Fire Protection and Life Safety Systems

- 13 There is no apparent evidence of any fire
- 14 protection or life safety systems.

Other Features

- 15 Wall brackets remain for two stall partitions remain
- 16 near the center of the north wall (Fig. C236).

Room 108 – Entrance Vestibule

17 Room 108 is an airlock for the main entrance, and
18 measures 3'-1" by 12'-4" with a ceiling height of
19 about 7'-3" (Fig. C237). Upon initial construction,
20 this space was open to the exterior on its south
21 side.

Flooring

- 22 Mortared flagstone paving is consistent throughout
- 23 the space, and is a continuation of the paving of the
- 24 exterior walkways.

Baseboards

- 25 Baseboards measure 7 1/2" tall by 7/8" thick with a
- 26 cove molding cap measuring 7/8" tall.

Walls and Ceiling

- 27 V-groove paneling matching that of Room 101A is
- 28 installed on both the walls and ceiling.

Doorways

- 29 Two pairs of doors make up both the north and
- 30 south walls and are described in the *Exterior*
- 31 *Features* section.

Windows

- 32 The room has no windows.




Figure C238. Room 108 - View looking northwest.



Figure C239. Original ceiling fixture in Room 108.

Finishes

- 1 The walls and ceiling are painted a blue-grey color
- 2 matching the exterior trim.

Mechanical Systems

- 3 There was no apparent evidence of any mechanical
- 4 systems.

Electrical System

- 5 Two original 8” square recessed fixtures with
- 6 starburst glass lenses are centered on the two
- 7 paired doorways.

Plumbing System

- 8 There is no apparent evidence of any plumbing
- 9 systems.

Fire Protection and Life Safety Systems

- 10 There is no apparent evidence of any fire
- 11 protection or life safety systems.

Attic

- 12 An unfinished attic is accessed from a hatch in
- 13 Room 105A, and consists of the area above Rooms
- 14 102, 103, 104, 105A and B, and 106 and 107 A and B
- 15 (Figs. C240-C242).

Flooring

- 16 Tongue-and-groove flooring measuring 5” wide
- 17 surrounds the hatch and is largely-continuous
- 18 above Room 102 (Fig. C242). The flooring over
- 19 Room 102 is laid over a 5” wide diagonal subfloor.

Walls and Ceiling

- 20 Framing is exposed on the walls and ceiling.
- 21 Fiberboard insulation is exposed between



Figure C240. View of attic looking east.



Figure C241. View of attic above west wing looking west.

- 1 the rafters. Both the west exterior and eastern
- 2 interior gable ends are vented, with horizontal
- 3 weatherboard siding serving as louvers.

Doorways

- 4 The hatch accessing the attic is described in the
- 5 *Room 105A – Storage Room* section (Fig. C243).

Windows

- 6 The attic has no windows.

Mechanical Systems

- 7 An exhaust fan with louvered opening on the west
- 8 gable of the main body is controlled by a wall-
- 9 mounted thermostat.
- 10 Two ventilation ducts extend from the kitchen
- 11 through the roof, one from the vent hood near the
- 12 chimney and one near the west end.
- 13 A vent for the ice machine the storage room (Room
- 14 105A) extends to the attic near the center of the
- 15 western section.

Electrical System

- 16 Two ceramic lamp holders are mounted above
- 17 Room 102, and are controlled by a rafter-mounted
- 18 light switch near the floor hatch.

Plumbing System

- 19 Cast iron plumbing vents are connected to the
- 20 chimney.

Fire Protection and Life Safety Systems

- 21 There is no apparent evidence of any fire
- 22 protection or life safety systems.



Figure C242. Tongue-and-groove flooring and ceiling height transition above kitchen.



Figure C243. Hatch accessing attic from Room 105A.



Figure C244. Bluffs Coffee Shop (right) and Park Visitors' Center in former service station (left), viewed from the southwest.

Character-defining Features

Distinctive Characteristics of the Site:

- | | | |
|----|---|----|
| 1 | • The mountain top setting with long vistas as | 24 |
| 2 | backdrop to the north. | 25 |
| 3 | • The long loop road paralleling the Parkway | 26 |
| 4 | and accessing the coffee shop and former | 27 |
| 5 | service station; | 28 |
| 6 | • The mowed grassy median opposite the | 29 |
| 7 | coffee shop and visitors' center. | 30 |
| 8 | • The stone curbing on the loop road; | 31 |
| 9 | • The fenced service area with wood rail gates | 32 |
| 10 | and original stone walls; | 33 |
| 11 | • The stone-curbed gas pump island of the | 34 |
| 12 | former service station; | 35 |
| 13 | • The adjacent former service station building; | 36 |
| 14 | • The steep grading of the site as it drops on | 37 |
| 15 | the north side of the coffee shop; | 38 |
| 16 | • The clear sight line visibility of the coffee | 39 |
| 17 | shop from the Parkway and vice versa; | 40 |
| 18 | • The obscured visibility of the east and west | 41 |
| 19 | parking lots. | 42 |
| 20 | • The low stone walls and stone stairs of the | 43 |
| 21 | east parking lot; | 44 |
| 22 | • The wooded picnic area down the hill from | 45 |
| 23 | the parking area to the northeast; | 46 |
| | | 47 |

Distinctive Characteristics of the Building Exterior:

- The concrete exterior stair and pipe railing leading to the basement walkway;
- The side-gabled roof with cement shingles of the main body and wing;
- The exposed rafter tails and roof decking at the eaves;
- The stone masonry chimney;
- The historic design of the aluminum-lined wood gutters and metal brackets on the south elevation;
- The historic design of the wood-wrapped round metal downspouts;
- The shed-roofed rear porch and square-post porch framing;
- The projecting hood with exposed timber framing on the east elevation;
- The louvered west gable vent of the west wing.
- The stone masonry walls of the south elevation.
- The random-width plank board siding;
- The horizontal weatherboard siding;
- The natural finish of all exterior siding;
- The concrete and CMU exterior foundation walls at the basement level;

1	• The original three-horizontal-light, two-over-one steel-sash awning windows in all locations;	41	• The original serving windows with operable shutters;
2		42	
3		43	• The plaster walls with exposed timber framing in Rooms 101A and 101B;
4	• The original two-horizontal-light steel-sash awning windows in all locations;	44	
5		45	• The flush-panel V-groove doors in all locations;
6	• The original six-light wood-sash hopper windows in all locations;	46	
7		47	• The original six-raised-panel doors in all locations;
8	• The original wood, stone, and concrete window sills in all locations;	48	
9		49	• The original mitered, rounded-corner door casing in all locations;
10	• The two pairs of early exterior two panel screen-sash doors at the main entrance;	50	
11		51	• The original concealed closet doors in Room 101B;
12	• The two pairs of original inner sash doors at the main entrance;	52	
13		53	• The original ball-pin hinges and mortised locksets in all locations;
14	• Plank-board exterior casings at all original window openings and doorways;	54	
15		55	• The original rounded window sills and molded aprons in all locations;
16	• The original paired nine-light-over-two-panel sash doors on the west elevation and historic design of the two-light screen doors;	56	
17		57	• The remaining interior window hardware;
18		58	• The original decorative spindle details above the main entrance and beside the serving windows.
19	• The six original nine-light-over-two-panel sash doors at the basement level.	59	
20		60	• The original casework with sliding doors in gift shop area of Rooms 101A and 101B;
21	• Original ball-pin hinges and mortised door hardware on exterior doors;	61	
22		62	• The original rear counter with sliding doors and black counter top with metal edge in Room 101A;
23	• The remaining four original two-panel basement screen doors and associated hardware;	63	
24		64	• The original main counter with varnished wood front and black counter top with metal edge in Room 101A;
25		65	• The four original three-lamp ceiling fixtures with shades in Room 101A, and the matching fixture above the main entrance in Room 101B;
	Character-defining Features of the Interior	66	
		67	• The early single-lamp rustic ceiling fixtures in Room 101A;
26	• The dimensions, pattern, and coloration of the original 9x9 green and white tiles with black banding in the dining room and main entryway (Rooms 101A and 101B);	68	
27		69	• The remaining original bar stools with vinyl covers in Room 101A;
28		70	• The original stainless steel hood at west end of Room 101A;
29		71	• The historic location of the gift shop area in Room 101A;
30	• The terrazzo flooring in the employee bathroom (Room 104);	72	
31		73	• The grouped configuration of tables and chairs as shown in historic photographs;
32	• The salt-glazed tile wainscoting in all locations;	74	
33		75	
34	• The exposed timber framing in the dining room, main entryway, and kitchen (Rooms 101A, 101B, and 102)	76	
35		77	
36		78	
37	• The original V-groove wall paneling in all locations;	79	
38		80	
39	• The original wood baseboard with molded cap in all locations;	81	
40		82	

Summary of Physical Conditions

1 Bluffs Coffee Shop was in continuous use from
2 1949 to 2010. Since 2010 the building has received
3 basic maintenance; most recently, a temporary
4 composition shingle roof was installed to protect
5 the interior from any further damage. The interior
6 layout of the building has seen no major changes
7 since construction.

Exterior

8 The concrete retaining wall of the service area on
9 the west side of the building exhibits excessive
10 spalling.

11 The exterior walkway along the north elevation has
12 several large cracks.

13 The concrete foundation walls appear to be in
14 good condition.

15 All elements of roof, wall, and floor structure
16 appear to be in sound condition based on basic
17 visual investigation.

18 The pointing of the exterior stonework appears to
19 be in good condition.

20 The exterior siding is in largely good condition;
21 however, in some areas the boards have shrunk
22 considerably, exposing the exterior sheathing
23 beneath. Several of the replacement vertical siding
24 on the side walls of the projecting south bay have
25 warped; nails have also popped-out from the face
26 of the siding in these areas, suggesting that the
27 sheathing beneath may be failing.

28 The steel-sash windows are in largely good
29 condition; however, rust is common on many of
30 the units. One pane of glass on the north elevation
31 is broken.

32 The wood sash windows on the south and west
33 elevations appear to be in good condition.

34 Painted window casings and sash on the north and
35 east elevations exhibit peeling.

36 The original exterior doors are in overall good
37 condition. The west exterior door has no
38 working lock mechanism; the west screen door is
39 deteriorated. The latch hardware for the east doors
40 is not functional, resulting the doors being chained
41 and propped closed.

42 The cement shingle roof has been partially
43 replaced and patched with temporary composition

44 shingle. The remaining cement shingles appear to
45 be in good condition; however, evidence suggests
46 that these shingles are of inferior design.

47 The wood gutters on the south elevation have been
48 recently rebuilt and are in good condition.

49 Downspouts and drainage systems on the south
50 elevation appear to be working properly following
51 recent drainage work. There is no form of
52 rainwater collection on the north elevation, except
53 for a gutter at the west end, which appears to be in
54 good condition.

55 The chimney has recently received new flashing;
56 the stonework appears to be in good condition, but
57 could benefit from cleaning.

Interior

58 The original asphalt tile is in fair condition, with
59 several patched and worn-through areas.

60 The replacement terracotta floor tiles appear to be
61 in good condition.

62 Original wood baseboards and trim throughout
63 the building remain in place and are in largely good
64 condition.

65 Plaster and concrete walls exhibit paint peeling.
66 The wood paneling on the main level is in largely
67 good condition; however, finishes have been
68 applied inconsistently. A portion of paneling in
69 the entryway has been damaged where one of the
70 closet doors was forced open.

71 Plaster ceilings are in generally good condition. The
72 exposed timber frame ceiling in the dining room
73 exhibits evidence of water staining from previous
74 roof leaks both on the fiberboard insulation and
75 framing members.

76 Windows in all locations are original and are in
77 generally good condition. On the interior, many
78 of the steel-sash windows lack operators. All steel
79 windows lack screen sash. Original interior sills
80 remain and appear to be in good condition.

81 With two exceptions, all original interior doors
82 remain in place and are appear to be in good
83 condition. Two sets of paired doors have been
84 removed from Room 103.

85 Original locksets and knobs remain in all locations,
86 and appear to be in good condition, though some
require repair to restore full functionality.

<p>1 Much of the original counter remains, though 2 partially dismantled. What remains provides a 3 valuable model for repairing and rebuilding this 4 important historic feature.</p> <p>5 Several original stools also remain. Like the counter 6 remnants, they present a valuable opportunity for 7 fabricating accurate reproductions.</p> <p>8 Original and early light fixtures in the dining room 9 are in fair condition, but lack glass chimneys and 10 require cleaning and minor repair. The remainder 11 of fixtures have been largely dismantled and 12 detached from walls and ceilings.</p>	<p>13 The original rear counter remains largely intact, 14 however it has been lifted off the floor and 15 detached from the wall. The sliding doors have 16 been removed and stored.</p> <p>17 The original casework on the south wall of the gift 18 shop area and east wall of the entryway is in good 19 condition.</p> <p>20 The utility systems are generally obsolete. 21 Plumbing throughout the building is installed 22 piecemeal. The heating system does not provide 23 adequate coverage to heat all spaces. There is no air 24 conditioning.</p>
--	---

II.A Ultimate Treatment and Use

- 1 Bluffs Coffee Shop remains a significant landmark 23
 2 along the Blue Ridge Parkway, and is a critical 24
 3 component of the recreation area at Doughton Park. 25
 4 Additionally, the coffee shop is an excellent example 26
 5 of the Parkway's post-war era rustic architecture. 27
 6 Together with the nearby lodge, adjacent repurposed 28
 7 service station, and historic site features, Bluffs 29
 8 is a highly-intact example of a comprehensively- 30
 9 designed recreation area on the Parkway. 31
- 10 For just over sixty years, Bluffs Coffee Shop served 32
 11 meals for both the passing motorist, as well as 33
 12 guests of the nearby lodge and campground. Its 34
 13 close proximity to the Parkway and high visibility 35
 14 from both directions of travel make the building 36
 15 well-suited for this purpose. The coffee shop's 37
 16 placement within walking distance of Bluffs Lodge 37
 17 allows the two concessions to be interdependent. 38
 18 The main level contains spaces designed for use as a 39
 19 restaurant, while the basement provides ample space 40
 20 for retail and food storage, as well as office space. 41
 21 The 2013 General Management Plan for the 42
 22 Parkway notes the importance of maintaining 43
 44
- concessions at key locations along the motorway, seeking to, "Continue to find ways to provide viable concession services at all existing locations to ensure the long-term availability of in-parkway lodging, food, and other services." Additionally, the Parkway has identified the coffee shop as a contributing historic resource of the proposed Blue Ridge Parkway Historic District.
- Accordingly, the recommended treatments and uses are as follows:
- *The Recommended Ultimate Treatment includes preservation of the exterior of the building and the major public interior spaces, the entrance foyer and dining room, according to its 1949 appearance, and rehabilitation of the interior ancillary spaces.*
 - *The Recommended Ultimate Use is a restaurant on the main level operated by a concessionaire with related ancillary uses, such as storage and office spaces, at the basement level.*



Figure II.1. Bluffs Coffee Shop as viewed from the median of the loop road, looking northeast. (JKOA, 2018)

II.B Requirements for Treatment and Use

1 The treatment and use of all historic properties
2 maintained by the National Park Service are guided
3 by federal laws and regulations as well as NPS
4 policies, directives, and functional requirements.
5 In addition to protecting cultural resources, they
6 address safety, fire protection, energy conservation
7 handicapped access, and abatement of hazardous
8 materials. If rigidly interpreted, some of these
9 requirements may be contradictory or at cross
10 purposes. Any treatment must be carefully
11 considered in order that the historic fabric of the
12 structure be preserved.

National Historic Preservation Act

13 The 1966 National Historic Preservation
14 Act (NHPA) as amended encourages federal
15 protection of significant cultural resources,
16 including buildings, landscapes, and
17 archaeological sites. Its implementation has
18 established laws and authorities that are binding
19 on the NPS.

Section 106

20 Section 106 of the NHPA requires a consultative
21 process prior to any federal agency undertaking,
22 or federal involvement in an undertaking, that
23 may have an effect on historic properties listed
24 in or eligible for listing in the National Register
25 of Historic Places. An agency, including NPS,
26 must determine whether such undertaking has
27 the potential to affect such historic resources,
28 and for those that do, initiate consultation under
29 the regulations for Section 106. The agency
30 must assess potential effects; take steps to avoid,
31 minimize, or mitigate adverse effects; and give
32 the Advisory Council on Historic Preservation “a
33 reasonable opportunity to comment with regard
34 to such undertaking.”

35 Section 106 strives to ensure that all interested
36 parties have a voice in the preservation of
37 our nation’s cultural heritage. The published
38 regulations (36 CFR Part 800, “Protection of



Figure II -2. View of Bluffs Coffee Shop and service station from the southwest, September 1953. (BLRI Coll.)

1 Historic Properties”) require, among other things,28
2 consultation with interested parties, which may 29
3 include local governments, government or non- 30
4 government applicants, State Historic Preservation31
5 Officers (SHPOs), Tribal Historic Preservation 32
6 Officers and tribal leaders, other parties, the 33
7 general public, and the Advisory Council.

8 The regulations establish criteria under which 34
9 the Advisory Council may comment, but the vast 35
10 majority of federal undertakings do not involve 36
11 Advisory Council review. 37

12 A programmatic agreement between the Advisory 38
13 Council for Historic Preservation, the National 39
14 Council of State Historic Preservation Officers, 40
15 and the NPS expedites the Section 106 review 41
16 process. With certain conditions, routine repairs 42
17 and maintenance that do not alter the appearance 43
18 of the historic structure or involve widespread or 44
19 total replacement of historic features or materials 45
20 are not subject to review outside the NPS. 46

21 The Secretary’s Standards 47

22 The Secretary of the Interior’s Standards for the 48
23 Treatment of Historic Properties articulate best 49
24 practices for protecting a wide range of historic 50
25 properties. They provide a philosophical rationale 51
26 for historic preservation that is almost universally 52
27 accepted in the United States and apply to a wide 53
28 variety of resource types, including buildings, sites,54
29 55

structures, objects, and districts. The Standards
are codified as 36 CFR Part 68, and treatment
guidelines under the Standards were revised
in 2017. A pdf of the updated Standards and
guidelines can be downloaded at [nps.gov/tps/
standards/treatment-guidelines-2017.htm](https://nps.gov/tps/standards/treatment-guidelines-2017.htm).

The Standards describe four broad approaches to
the treatment and use of historic properties. These
are, in hierarchical order:

- **Preservation** places a high premium on retaining the historic fabric through conservation, maintenance, and repair. It reflects a building’s continuum through successive occupancies and any respectful changes and alterations made.
- **Rehabilitation** applies to properties that have deteriorated prior to work and, while emphasizing the retention and repair of historic materials, provides more latitude for replacement. Both Preservation and Rehabilitation standards focus on preserving those materials, features, finishes, spaces, and spatial relationships that together give a property its historic character.
- **Restoration** focuses on retaining materials from the most significant time in a property’s history, while permitting the removal of materials from other periods.



Figure 11-3. Rear of coffee shop looking southwest. (JKOA 2018)



Figure II-4. View of Bluffs Coffee Shop and service station taken before 1953. (BLRI Coll.)

- 1 • **Reconstruction** establishes limited
- 2 opportunities to re-create with all new
- 3 materials a site, landscape, building,
- 4 structure, or object that has not survived.

5 Regardless of treatment approach, the Standards
 6 put a high priority on preserving historic materials
 7 and features, not just the architectural form
 8 and style. They also require that any alterations,
 9 additions, or other modifications be reversible; that
 10 is, they must be designed and constructed, so they
 11 can be removed or reversed in the future without
 12 loss of historic materials, features, or character.

Americans with Disabilities Act of 1990

13 The 1990 Americans with Disabilities Act (ADA)
 14 establishes comprehensive civil rights protection for
 15 disabled Americans, both in employment and their
 16 right to free, unaided access to public buildings.
 17 While people with restricted mobility have most
 18 benefited, protection extends to those with
 19 impaired vision or hearing or other disabilities.

20 Requirements for full compliance with ADA
 21 regulations are extensive and easiest to apply to new
 22 construction. Full compliance for historic buildings
 23 is more difficult. When it would require significant
 24 alterations to their historic character, ADA
 25 authorizes a process for arriving at alternatives that
 26 can preserve historic character while maximizing
 27 disabled visitors' access to the building.

International Building Code

28 NPS policy is also guided by the International
 29 Building Code, which states:

30 3406.1 Historic Buildings. The provisions of this
 31 code related to the construction, repair, alteration,
 32 addition, restoration and movement of structures,
 33 and change of occupancy shall not be mandatory
 34 for historic buildings where such buildings are
 35 judged by the building official to not constitute a
 36 distinct life safety hazard.

37 Threats to public health and safety must be
 38 eliminated, but alternative ways to prevent them
 39 are always sought when full code compliance
 40 would needlessly compromise the integrity of a
 41 historic building.

NFPA Code 914

42 The National Fire Protection Association (NFPA)
 43 has promulgated codes for historic buildings,
 44 most notably NFPA 909, "Code for the Protection
 45 of Cultural Resources Properties - Museums,
 46 Libraries, and Places of Worship," and NFPA 914,
 47 "Code for Fire Protection of Historic Structures."
 48 As a matter of policy, NPS recommends installing
 49 fire-suppression systems in every historic building.

NPS Management Policies

50 NPS General Management Policies (2006),
 51 especially chapter 5, "Cultural Resource



Figure II-5. View of Bluffs Coffee Shop from across the Parkway taken before 1953. (BLRI Coll.)

1 Management,” guide its oversight of historic
 2 properties. Based on the authority of some
 3 nineteen Acts of Congress and many more
 4 Executive orders and regulations, these policies
 5 require planning to ensure that decision-
 6 making and priority-setting processes integrate
 7 information about cultural resources and
 8 consultation and collaboration with outside
 9 entities. They also support good stewardship
 10 to ensure that cultural resources are preserved
 11 and protected, receive appropriate treatments
 12 (including maintenance), and are made available
 13 for public understanding and enjoyment.

Section 5.3.5, Treatment of Cultural Resources

14 This section of the General Management
 15 Policies provides specific directives, including
 16 one stipulating that “the preservation of cultural
 17 resources in their existing states will always receive
 18 first consideration.” It also states:

19 ... treatments entailing greater intervention
 20 will not proceed without the consideration of
 21 interpretive alternatives.... Pending treatment
 22 decisions reached through the planning process,
 23 all resources will be protected and preserved in
 24 their existing states. Except for emergencies that
 25 threaten irreparable loss without immediate action,
 26 no treatment project will be undertaken unless

27 supported by an approved planning document
 28 appropriate to the proposed action (p. 50).

29 This HSR is the approved planning document.

Park Long-Range Interpretive Plan

30 The Blue Ridge Parkway Long-Range Interpretive
 31 Plan was prepared in 2002 and provides
 32 recommendations for enhancing the visitor
 33 experience throughout the Parkway. The plan
 34 identifies Doughton Park as an area rich in
 35 both natural and cultural resources with many
 36 opportunities for learning about the history and
 37 character of southern Appalachia. It is suggested
 38 that the NPS work closely with concessionaires
 39 at Bluffs to provide orientation information on
 40 Doughton Park to visitors (p. 95-96).

Park General Management Plan

41 In 2013, NPS developed a General Management
 42 Plan/ Environmental Impact Statement for the Blue
 43 Ridge Parkway. In *Chapter 2: Alternatives*, the NPS
 44 Preferred Plan (Alternative B) takes the following
 45 stance Cultural Resources:

46 "Seek designation of the designed parkway
 47 corridor as a national historic landmark district
 48 while continuing to manage it as an eligible
 49 resource. The principal components of this
 50 designed landscape are the parkway road with
 51 its supporting structures and constructed

1 landforms, a scenic corridor provided by a broad
 2 right-of-way, a chain of 17 original and 3 more
 3 recent recreation areas, and a variety of exhibits
 4 interpreting the natural and cultural histories of
 5 the region." (p. 46)

6 Specifically concerning buildings, the preferred
 7 alternative states:

8 "Continue to give priority for preservation to
 9 historic structures that are directly associated
 10 with the parkway's original design intent and
 11 that are listed as structures contributing to the
 12 national significance of the parkway. Structures
 13 constructed or acquired after 1955 are not
 14 considered to contribute to the significance of
 15 the parkway and as such, their merits for listing
 16 on the National Register of Historic Places and
 17 preservation activities would be determined
 18 individually." (p. 46)

19 The preferred alternative for interpretation and
 20 visitor services states:

21 "Continue to maintain 20 recreation areas along
 22 the length of the parkway with traditional visitor
 23 services that support a recreational and scenic
 24 driving experience, including camping, lodging,
 25 restaurants, camp stores, and picnic sites. Ensure
 26 that in the future these traditional recreation
 27 services remain a high priority and are enhanced,
 28 as needed, to respond to increases in visitor
 29 demand." (p. 47)

30 The NPS preferred alternative for concessions
 31 states:

32 "Continue to find ways to provide viable
 33 concession services at all existing locations to
 34 ensure the long-term availability of in-parkway
 35 lodging, food, and other services. Strategies
 36 might include making upgrades to existing
 37 infrastructure and/or adding new facilities where
 38 appropriate." (p. 47)

Park Foundation Document

39 In October 2016, a foundation document was
 40 prepared which serves primarily as an update
 41 to the GMP. The document notes the Parkway's
 42 lack of resources to adequately maintain
 43 historic structures, as well as the closure and
 44 deterioration of historic structures as a result.
 45 The document presents the opportunity to,
 46 "Pursue uses of historic structures that are
 47 consistent with their historic context, including
 48 use by concessioners." (p. 25)

49 The foundation document also presents planning
 50 considerations, such as a need for a preservation
 51 and maintenance plan, which would,

52 "...provide guidance for preservation and
 53 maintenance of both historic and nonhistoric
 54 structures and assets, including historic buildings,
 55 the designed landscape, ditches and culverts, etc. It
 56 would help set minimum objectives and priorities
 57 for preservation and maintenance." (p. 29)

II.C Alternatives for Treatment and Use

1	In accordance with NPS policy, an alternative	24
2	for both treatment and use has been considered	25
3	in addition to the Ultimate Treatment and Use	26
4	described in Section II.A. While not recommended	27
5	under the current circumstances, these alternative	28
6	approaches fulfill the basic park mandate to protect	29
7	historic resources on the Blue Ridge Parkway.	30
8	<i>There is no Alternative Treatment provided</i>	31
9	<i>for the exterior, as the exterior exhibits a high</i>	32
10	<i>level of integrity and should be preserved to the</i>	33
11	<i>greatest extent possible.</i>	34
12	<i>The Alternative Treatment for the Interior is the</i>	35
13	<i>preservation of identified character-defining</i>	36
14	<i>elements while adapting the interior to a use</i>	
15	<i>other than a full-service restaurant.</i>	
16	<i>The Alternative Use is a reduced-scale quick</i>	37
17	<i>service cafe serving ready-made offerings such</i>	38
18	<i>as sandwiches and drinks. This use could evolve</i>	39
19	<i>after financial viability of the original full-service</i>	40
20	<i>restaurant model is proven.</i>	41
21	This approach has the following advantages:	42
22	• Is consistent with the intent of the General	44
23	Management Plan (GMP) to preserve	45

historic structures directly associated with the Parkway's original design intent.

- It maintains the building's historic role as a concession offering meals.
- Simplified food offerings could reduce risk faced by a potential concessionaire by lowering initial start-up costs.
- It would not require a full commercial kitchen or large staff to operate.
- It could provide short or mid-term occupancy until Bluffs Lodge is restored to provide a consistent customer base and a larger restaurant is warranted.

However, it has the following disadvantages:

- While consistent with the intent of the GMP to protect the Parkway's historic structures, this alternative would be a notable departure from the original visitor experience enjoyed for over sixty years.
- It may fail to meet the expectations of patrons who have shown support for the shop's reopening, leaving NPS open to criticism.
- Interior spaces would likely be underutilized.

II.D Recommendations for Treatment and Use



Figure II-6. Bluffs Coffee Shop and service station viewed from the edge of the Parkway, looking northwest. All photos in this section were taken by JKOA in 2018.

1 The following Ultimate Treatment and Use
2 recommendations for Bluffs Coffee Shop reflect
3 the Blue Ridge Parkway's desire to protect and
4 maintain its architectural resources and the
5 intent to return the coffee shop to active use as a
6 restaurant. All plans focus on retaining character-
7 defining features as outlined at the end of section
8 I.C of this report, while presenting opportunities
9 to modify the interior to fit the needs of a
10 concessionaire.

11 The actions recommended below are intended to
12 provide a conceptual framework for achieving the
13 treatment and use recommended. They do not
14 provide and are not intended to provide the level
15 of specific guidance that architectural/engineering
16 plans and specifications present.

The Site

17 Though this HSR focuses on the coffee shop
18 building, the character of the site is also important
19 in providing the proper historic setting as
20 advocated in the 2006 Cultural Landscape Report
21 for Doughton Park.

22 The site retains the vast majority of its historic
23 elements, including the configuration of the loop
24 road, parking areas, and flagstone walkways. The
25 immediate area includes many examples of early
26 rustic landscape elements such as stone walls, water
27 fountains, and picnic tables.

28 The paved service area between the coffee shop and
29 service station is bordered by a poured-in-place
30 concrete retaining wall with an extending stone knee

1 wall. Improper groundwater management behind
 2 the retaining wall has resulted in the extensive
 3 deterioration of the concrete, including heavy
 4 spalling, staining, and cracking (*Figs. II-7-8*).

5 Work completed in 2017 replaced much of
 6 the rainwater collection system on the south
 7 elevation. Although the north elevation does not
 8 have a complete gutter system, the steep grade
 9 behind the building generally allows for natural
 10 runoff to prevent water from pooling at the
 11 building's base.

Recommendations for the Site

- 12 • Retain the early landscape elements
 13 surrounding the coffee shop complex as
 14 outlined in the 2006 CLR for Doughton park.
 15 Use this document to guide site treatment.
- 16 • Evaluate deterioration of concrete retaining
 17 wall west of the coffee shop and plan for
 18 repair or replacement. The original stone of
 19 the upper portion should be retained and
 20 reused in the reconstruction.

Bluffs Coffee Shop - Exterior

21 The coffee shop has been vacant since late fall
 22 of 2010, the end of the operating season. Since
 23 its closure, NPS has provided basic maintenance

24 to preserve and stabilize the building, including
 25 recent roof repairs and drainage work. NPS also
 26 maintains the surrounding site.

27 The exterior of the coffee shop has received few
 28 modifications since initial construction. The
 29 interior retains the vast majority of its original
 30 features, including trim, doors, casings, flooring,
 31 and casework, including the main serving counter.

Recommendations for Achieving Accessibility & Universal Design Standards

- The existing ramp leading to the east doorway provides a good solution for universal accessibility. The existing flagstone walkway in front of the building has curb cuts at its center, east, and west ends, making the ramp easily accessed from all parking areas. A new door jamb design without center post would provide a greater ease of access for wheelchairs.
- ADA compliant bathrooms should be designed within the footprint of the existing main level bathrooms, west of the main entrance. To accommodate the additional space required for accessibility, consider replacing the existing public bathroom designs with two, single-fixture bathrooms which would not require additional space for



Figure II-7. Concrete retaining wall between coffee shop and service station. Note extensive deterioration.



Figure II-8. Example of severe spalling at far east end of retaining wall, adjacent to exterior staircase.

1 entry vestibules and could accommodate the
2 turning radius of a wheelchair.

Recommendations for Historic Paints and Finishes

- 3 • Prepare an analysis of historic paints and
4 finishes of the interior and exterior for the
5 historic period. Include paint type and color,
6 as well as varnishes. Interior analysis should
7 focus on noted locations of early finishes
8 identified in the dining room and entryway
9 (Rooms 101A and 101B). The results of this
10 analysis should inform the treatment of
11 original trim, exposed structural members,
12 and wood paneling in key public areas.



Figure II-9. Example popped fasteners and warped board on west wall of south bay.

Recommendation for Exterior Siding

- 13 • Inspect underlying sheathing of areas with
14 failed fasteners, particularly those on the east
15 and west walls of the projecting south bay
16 (*Fig. II-9*).
- 17 • Replace in-kind heavily-warped or split
18 boards that represent a threat to the
19 weathertightness of the building envelope.
- 20 • Monitor gaps in vertical plank board siding
21 for insect entry through exposed sheathing
22 boards.
- 23 • Maintain natural weathered appearance of
24 exterior cladding as part of future repair or
25 finishing campaigns.

Recommendations for Roofing:

- 26 • Continue planned semi-long-term solution
27 of installing composite roofing to replace
28 failing cement shingles and temporary 3-ply
29 composition roofing.
- 30 • Plan for eventual replacement of composite
31 roofing with combed cement shingle
32 matching the size and coloration of the
33 original cement roofing material.

Recommendations for Gutters and Downspouts

- 34 • Install /reinstall gutters and downspouts
35 on north elevation to effectively collect
36 rainwater runoff from all roof slopes,
37 including the rear porch.

Recommendation for Protecting Historic Windows

- 38 • After conducting a comprehensive paint
39 analysis, prepare and paint all elements
40 of window sash and exterior casings. As
41 part of the preparation, remove exfoliating
42 surface rust on steel-sash windows and

prime with a rust-inhibiting primer.

- Restore operation of windows in key areas,
such as the dining room, by repairing or
replacing in-kind missing or damaged
awning sash operators.
- Fabricate interior screen sash to allow
window operation. Remaining screen
sash hardware can serve as a model for
replacements.
- Consider fabricating interior thermal sash that
could be installed during colder months and
in the off-season to reduce drafts.

Recommendations for Exterior Doors

- Restore functionality of locking mechanisms
on all exterior doors. Original locksets
should be retained, re-keyed, repaired, and
reused.
- Replace deteriorated two-panel paired
screen doors on west elevation based on the
design shown in original drawings.
- Replace three non-original screen doors on
the north elevation with doors and hardware
modeled after extant early examples.
- Replace deteriorated east doors and door
frame with a design sized appropriately for
the rough opening (*Fig. II-10*). Model the
replacement doors according to existing
original door designs.

Recommendations for Chimney

- Clean the outside of the chimney with mild,
non-ionic detergent to reduce excessive soiling
and biocide to address biological growth.

Recommendations for Exterior Lighting

- Remove existing surface-mounted electrical
boxes, fixtures, and conduit on the exterior



Figure II-10. Deteriorated, poorly-detailed replacement doors in east doorway.

Recommendations for Counter and Stools

- Repair and reuse existing serving counter and use as a model to reconstruct missing sections, matching the original in appearance and materials.
- Repair and reuse existing counter stools. Use existing stools as a model for fabricating missing stools. If any original stools cannot be repaired, retain in the Park's archive.
- Restore original serving counter length and number of stools as shown in early photographs.

Recommendations for Mechanical Systems

- Install new heating and cooling systems to cover all major interior spaces. The designed system should have minimal visual impact on the character of the coffee shop's historic dining room and entryway, especially.

Recommendations for Electrical System

- Replace entirety of electrical system, including wiring, receptacles, switches and panels. Provide necessary service to support a commercial kitchen.
- Clean, repair, and rewire existing original and early light fixtures in the dining room. Replace missing glass chimneys based on those in historic photographs.

Recommendation for Plumbing System

- Remove remnants of existing plumbing system and install new system.

Fire Protection and Life Safety System

- Remove remnants of existing fire protection system and install new system.

1 and replace with a more aesthetically- 40
 2 sensitive solution. Rewire original recessed 41
 3 fixture boxes still present above most 42
 4 exterior doorways. 43

- Replace exterior lighting fixtures with an 44
 6 appropriate design considering both the 45
 7 rustic architectural styling as well as the era 46
 8 in which the building was constructed. 47

Bluffs Coffee Shop - Interior

9 The majority of original interior elements remain 47
 10 intact. Care should be taken to preserve the
 11 character-defining features as indicated at the end
 12 of section I.C of this report.

Recommendations for Historic Flooring

- Replace existing asphalt tile floor in the 13
 14 dining room and entryway, which in addition
 15 to be worn an incomplete, has tested positive
 16 for asbestos content. Care should be taken
 17 to match the coloration, texture, pattern,
 18 and dimension of the original flooring, all of
 19 which relate to the character of the space.

Bibliography

- Crouch, Carlisle J. "Acting Superintendent Memorandum for the Regional Director". Region 1, February 17, 1948, BLRI Archives Series 16, Box 90, Folder 53.
- Emerson, Ralph W., *Regional Landscape Architect, Memorandum to the Superintendent*, January 24, 1947, BLRI Archives Series 16, Box 90, Folder 45.
- Forbis, Dennis. "Report of Asbestos Survey and Lead Paint Sampling, Gift Shop and Coffee Shops Renovation Areas". Unpublished, September 16, 2016.
- Forbis, Dennis. "Mold Remediation at the Bluffs Coffee Shop and Gift Shop – Post Remediation Assessment Results – Coffee Shop Building". Unpublished, December 12, 2016.
- Hellman, Robert. *Archeological Investigations Conducted at the Blue Ridge Parkway: Doughton Park, North Carolina*. (Southeast Archeological Center, 2002)
- Henderson, Matt (District Facility Manager, Highlands District, BLRI), email correspondence with the author, July 9, 2018
- Heating Plan, Coffee Shop Bldg. No. 106, Drawing BL-5323A, August 1948.
- The Jaeger Company. *Cultural Landscape Report, Doughton Park and Sections 2A, B, and C, Blue Ridge Parkway* (Atlanta: National Park Service Southeast Regional Office, 2006).
- Jolley, Harley. *Painting with a Comet's Tail: The Touch of the Landscape Architect on the Blue Ridge Parkway*. (Boone, NC: Appalachian Consortium Press, 1987), 12. (As cited in CLR).
- Lee Wan and Associates, Inc. "Comprehensive study and Recommendations for Unsafe Electrical System Life Safety Corrections, Doughton Park Lodge, Coffee Shop/Dining Facilities, Blue Ridge Parkway". Unpublished, May 1981.
- Lee Wan and Associates, Inc. "Doughton Park Lodge, Coffee Shop & Service Station, Blue Ridge Parkway, N.C., Electrical and Life Safety Renovations". Unpublished, June 1981.
- Lee Wan and Associates, Inc. "Renovation Study, Bluffs Lodge and Bluffs Coffee Shop". Unpublished, February 1980.
- National Park Service. *Final General Management Plan /Environmental Impact Statement, Blue Ridge Parkway, Virginia and North Carolina*. Southeast Regional Office, 2013
- National Park Service. *Long-term Interpretive Plan, Blue Ridge Parkway*. Blue Ridge Parkway Branch of Interpretation, Harpers Ferry Center Interpretive Planning, 2002.
- National Park Service. *Foundation Document, Blue Ridge Parkway, North Carolina /Virginia*. Southeast Regional Office, 2016.

National Park Service. *Draft: National Historic Landmark Nomination, Blue Ridge Parkway Historic District*. Unpublished, 2016.

Peaslee, Horace “Report to the National Park Service and National Park Concessions, Inc. on the Bluff Park Coffee Shop and Service Station”, June 22, 1946, BLRI Archives Series 16, Box 89, Folder 35.

Quin, Richard and Christopher Marston. *Blue Ridge Parkway Historic American Engineering Record, HAER No. NC-42*. 1996-1997.

Sanborn, H.S., Memorandum to the superintendent, December 7, 1947, BLRI Archives Series 16, Box 90, Folder 52.

Sturgill, Bridgette “Blue Ridge Parkway opens Doughton Park Visitor Center and Park Store” Mountaintimes.com, June 29, 2017.

Weems, Sam P. “Superintendents Memorandum for the Regional Director”. Region One, September 28, 1946., BLRI Archives Series 16, Box 89, Folder 41.

Superintendent’s Annual Report to the Director, 1949.

Superintendent’s Annual Report, 2003.

Superintendent’s Annual Report, 2006

Superintendent’s Annual Report, 2010

Interviews



Bill Harrison, former General Manager, Bluffs Coffee Shop and Bluffs Lodge, July 2018.

Selected Websites

“Digital Blue Ridge Parkway” <https://docsouth.unc.edu/blueridgeparkway/>.

Appendix A:



1948 Construction Drawings



BASEMENT PLAN
SCALE 1/8" = 1'-0"

HALF-SIZE REPRODUCTION

RECOMMENDED H.S. SANBORN DATE 3/27/48
 RECOMMENDED O.C. HOPKINS DATE 3/3/48
 SANITARY ENGINEER, USPHS



ROOM & SPACE	SUB-FLOOR	FIN FLOOR	BASE	WALLS	CEILING	REMARKS
Living Quarters No 1	Concrete	Asphalt Tile	Asphalt Tile	Cement Plumb	Cement Wash	
" " No 2	"	"	"	"	"	
" " No 3	"	"	"	"	"	
Womens Locker Room	"	Concrete	Concrete	"	"	
Mens "	"	"	"	"	"	
Refuse Room	"	"	"	"	"	
Boiler "	"	"	None	None	None	
Stairs	"	"	Concrete	Cement Plumb	Cement Point	
Compressor Room	"	"	None	None	None	
Coal Bunker No 1	"	"	"	"	"	
" " No 2	"	"	"	"	"	
Storage	"	"	"	"	"	
Porch	"	"	"	Cement Point	Stained	

RECOMMENDED Charles F. Peterson DATE 3/22/48
 SUPERINTENDENT

RECOMMENDED Charles F. Peterson DATE 3/22/48
 DESIGNER ARCHITECT

APPROVED Thomas J. Allen DATE 3/23/48
 REGIONAL DIRECTOR

UNITS STATES
 DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE
 PLANS AND DESIGN DIVISION


COFFEE SHOP - BLDG. NO 106

REGION ONE

DRAWING NO. 106-106-106

DESIGNED BY: W. H. HARRIS
 DRAWN BY: W. H. HARRIS
 CHECKED BY: W. H. HARRIS
 REVIEWED BY: W. H. HARRIS
 APPROVED BY: W. H. HARRIS

BASIC DATA
 PLY. BT. BL. 3526 - GARDING
 PLY. BT. BL. 3527 - MECHANICAL
 PLY. BT. BL. 3528 - ELECTRICAL
 PLY. BT. BL. 3529 - PLUMBING
 PLY. BT. BL. 3530 - SANITARY PIPING LAYOUT



LEGEND



SCALE	DETAIL
Concrete	[Pattern]
Cinder Block	[Pattern]
Stone Masonry	[Pattern]
Tile	[Pattern]
Wood	[Pattern]

FIRST FLOOR PLAN
SCALE 1/4" = 1'-0"

SECTION I-I
SCALE 1/2" = 1'-0"

SECTION GARAGE CHUTE
SCALE 1/2" = 1'-0"

DESIGNED BY: [Name]
 CHECKED BY: [Name]
 DRAWN BY: [Name]
 REVISIONS:
 1. [Description]
 2. [Description]
 3. [Description]
 4. [Description]
 5. [Description]



NOTES
 For Sec. Q-Q see Det. W-W, Sheet No. 6
 For Sec. P-P see Det. V-V, Sheet No. 6
 For Sec. T-T see Det. U-U, Sheet No. 6

FIRST FLOOR FINISH SCHEDULE

ROOM & SPACE	SUB-FLOOR	FIN. FLOOR	BASE	WAINSCOT	WALLS	CEILING	REMARKS
Restroom	Concrete	Flag Stone	Wood (S)	None	Wood (S)	Wood (S)	
Lobby & Gifts	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P), Dry Wall (D)	Dry Wall (D)	
Dining Room	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	
Men's Toilet	Concrete	Asphalt Tile	Concrete	None	Wood (S)	Wood (S)	
Women's Toilet	Concrete	Asphalt Tile	Concrete	None	Wood (S)	Wood (S)	
Kitchen	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	
Stair Hall	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	
Men's Toilet	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	
Close	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	
Stair Room	Concrete	Asphalt Tile	Concrete	None	Wood (S), Plaster (P)	Wood (S)	


NOTE #1: Cinder block walls to receive rubber cement wash.
 (S) Stained
 (P) Painted
 (D) Dry Wall

SCALE: AS NOTED


RECOMMENDED	DATE	
CONCURRED	DATE	
APPROVED	DATE	

UNITED STATES DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE
 PLANS AND DESIGN DIVISION
 PROJECT NO. 106
 COFFEE SHOP - BLDG. NO. 106
 BLVD. BRIDGE PARKWAY
 STATE OF MONTANA



REGION ONE
 SHEET 2 OF 11
 DRAWING NO. 106-2-52
 DATE 11-1-52



SOUTH ELEVATION



NORTH ELEVATION




SCALE 1/4" = 1'-0"

RECOMMENDED	DATE	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PLANS AND DESIGN DIVISION PREPARED BY D. S. MOORE OFFICE COFFEE SHOP - BLDG. NO. 106 NAME OF JOB TIDE MILLIFES LOCATION BLUE RIDGE PARKWAY TOWN OF PARK, MISSOURI	DESIGN ONE
CONCURRED	DATE		DRAWING NO. 106-106
APPROVED	DATE		DATE 4-17-34

DESIGNED BY
 GEORGE W. COLEMAN
 CIVIL ENGINEER
 ST. LOUIS, MO.
 ENGINEERING
 PLANS AND DESIGN
 FORESTRY
 RESEARCH AND EDUCATION
 SANITATION
 REVIEWED
 RESEARCH AND EDUCATION
 SANITATION
 PLANNING AND STATE COORDINATOR
 MEDICAL DIRECTOR
 CLEARED

BASIC DATA See sheet No. 1



DESIGNED BY
 CHECKED BY
 DRAWN BY
 ENGINEERING
 REVISIONS
 RESEARCH AND EDUCATION
 PLANNING AND STATE COORDINATION
 REGIONAL DIRECTOR
 CLEARED
 TRAIL LINE

BASIC DATA SEE SHEET NO. 1

RECOMMENDED _____ DATE _____	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PLANS AND DESIGN DIVISION PREPARED BY EDWARD A. GILES	REGION ONE
CONCURRED _____ DATE _____		SCALE 1/2"=1'-0"
APPROVED _____ DATE _____		SHEET NO. 1 DRAWING NO. 2273-78 DATE 11-20-27-28 DRAWN BY G. W. C.
COFFEE SHOP - BLDG. NO. 106 NAME OF BLDG. THE BLDG. NO. 106 LOCATION BLUE RIDGE PARKWAY NAME OF PARK OR MONUMENT		

TRIM LINE

CLEARED

REVIEWED

DESIGNED BY

ST. CLAYTON

CHAS. E. ST. CLAYTON

PLANS AND DESIGN

FORESTRY

RESEARCH AND EDUCATION

PLANNING AND STATE COOPERATION

PERSONAL DIRECTOR

DESIGNED BY

ST. CLAYTON

CHAS. E. ST. CLAYTON




PLANS AND DESIGN

FORESTRY

RESEARCH AND EDUCATION

PLANNING AND STATE COOPERATION

PERSONAL DIRECTOR



SECTION C-C

SECTION B-B

SECTION A-A

Plaster beyond this line by others

BASIC DATA

PLAN

H PLAN THRU CABINETS

SCALE 1/2" = 1'-0"


RECOMMENDED	DATE
CONCURRED	DATE
APPROVED	DATE

UNITED STATES
DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE
PLANS AND DESIGN DIVISION
FOUNDED BY
ROCKWELL
OFFICE

COFFEE SHOP - BLDG. NO 106

NAME OF JOB
THE CLIFFS
LOCATION
BLUE RIDGE PARKWAY
NAME OF PARK OR MONUMENT

REGION	ONE
PROJECT NO.	106
SHEET NO. OF 14	10
DRAWING NO.	106-10
DATE	11-27-38




DESIGNED BY
 C. P. 133 (M.A.)
 DRAWING AND DESIGN
 CONSULTING ENGINEER
 REVIEWED
 RECREATIONAL
 DRAWING AND DESIGN
 CONSULTING ENGINEER
 CLEARED
 NATIONAL ARCHITECTURE
 BOARD OF EXAMINERS
 ARCHITECTURE
 HISTORY
 CONSTRUCTION
 BASIC DATA


NOTE: For location of sections see plan sheet No. 5

RECOMMENDED	DATE	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PLANS AND DESIGN DIVISION PREPARED BY R. B. ARNOLD DRAWING NO. 6-2077-1 SHEET 1-11-A
CONCURRED	DATE	
APPROVED	DATE	
COFFEE SHOP - BLDG. NO. 106 THE BLUFFS BLUE RIDGE PARKWAY GREAT SMOKING HILLS NATIONAL MONUMENT		REGION ONE SHEET 1 OF 11 DRAWING NO. 6-2077-1 SHEET 1-11-A


DESIGNED BY GROSSMAN	REVIEWED	CLEARED
PLANS AND DESIGN	RESEARCH AND EDUCATION	RECREATIONAL PLANNING AND STATE COOPERATION
CHECKED BY ENGINEERING	HISTORY	REGIONAL DIRECTOR




SECTION THRU CORNICE - N. WALL OF DINING ROOM




SECTION THRU MAIN CORNICE SOUTH ELEV.




HEAD SECTION - WINDOWS




HEAD JAMB SIMILAR




HEAD SECTION WINDOWS




JAMB SECTION - WINDOWS




MULLION




JAMB SECTION WINDOW




SILL SECTION - WINDOWS




SILL WINDOWS




MULLION BETWEEN WINDOWS




SECTION THRU CORNICE - NORTH WALL OF KITCHEN




HEAD HANGERS




MULLION WINDOWS




HEAD SECTION - WINDOWS




PLAN




JAMB SECTION WINDOW




JAMB SECTION - WINDOWS




DOWNSPOUT DETAILS



SILL SECTION WINDOWS



EXTERIOR ELEVATION WINDOWS POST









SECTION AT FLOOR WINDOWS

APPROVED	CONCURRED	RECOMMENDED
DATE	DATE	DATE
UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PLANS AND DESIGN DIVISION WASHINGTON, D. C.		
ONE REGION DIVISION NO. 4 PROJECT NO. 102 SHEET NO. 102		




SCALE 3/16" = FEET UNLESS NOTED

DESIGNED BY GEORGE J. SHAW
 CHECKED BY []
 DRAWING NO. BI-2047-B
 DATE 4-21-34
 REGION ONE
 SHEET 12 OF 14
 COFFEE SHOP - BLDG. NO. 106
 THE BLUFFS
 BLUE RIDGE PARKWAY
 STATE OF MISSOURI



RECOMMENDED _____ DATE _____	DATE _____	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PLANS AND DESIGN DIVISION PREPARED BY GEORGE J. SHAW COFFEE SHOP - BLDG. NO. 106 THE BLUFFS BLUE RIDGE PARKWAY STATE OF MISSOURI	REGION ONE SHEET 12 OF 14 DRAWING NO. BI-2047-B DATE 4-21-34
CONCURRED _____ DATE _____	DATE _____		
APPROVED _____ DATE _____	DATE _____		

DESIGNED BY: G. C. ...
 CHECKED BY: ...
 DRAWING NO.: ...
 DATE: ...
 REGION: ONE
 SHEET # OF 14
 DRAWING NO.: PLY-BP
 DATE: 4-24-58




BASIC DATA

RECOMMENDED _____ DATE _____
 CONCURRED _____ DATE _____
 APPROVED _____ DATE _____

SCALE 1/4" = 1'-0"
 UNITED STATES DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE
 PLANS AND DESIGN DIVISION
 PREPARED BY BOARDMAN OFFICE
COFFEE SHOP - BLDG. N^o 106
 NAME OF JOB THE SLUFFS
 LOCATION BLUE RIDGE PARKWAY
 NAME OF PARK OR MONUMENT

REGION ONE
 PCD 2-73-12
 SHEET # OF 14
 DRAWING NO. PLY-BP
 DATE 4-24-58

DESIGNED BY: [Blank]
 FORESTRY: [Blank]
 ENGINEERING: [Blank]
 PLANS AND DESIGN: [Blank]
 REVIEWED BY: [Blank]
 RESEARCH AND DEVELOPMENT: [Blank]
 SANITATION: [Blank]
 PLANNING AND STATE COORDINATION: [Blank]
 REGIONAL DIRECTOR: [Blank]
 CLEARED: [Blank]



POST #21
POST #11 SIMILAR, OPPOSITE HAND

POST #27
POST #17 SIMILAR OPPOSITE HAND

POST #28
POST #18 EXCEPT AS NOTED & OPPOSITE HAND

POSTS # 22, 23, 24, 25
POSTS # 12, 13, 14, 15 SIMILAR OPPOSITE HAND

POST #16

POST #26

POST #26
POST #16 SIMILAR OPPOSITE HAND

SCALE 3/4" = 1'-0"

RECOMMENDED	DATE
CONCURRED	DATE
APPROVED	DATE

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE
 PLANS AND DESIGN DIVISION
 PREPARED BY
 ROANOKE OFFICE
COFFEY SHOP - BLDG. No 106
 NAME OF JOB
 THE COFFEYS.
 LOCATION
 BLUE RIDGE PARKWAY
 STATE OF MISSOURI


REGION
ONE
 PCP-8-13-7
 SHEET 13 OF 14
 DRAWING NO.
PL-2047-B
 DATE
 4-21-48

BASIC DATA

ELEVATION

REAR PORCH

SECTION



FIRST FLOOR PLAN

EQUIPMENT LAYOUT

SCALE 1/8" = 1'-0"

DESIGNED BY
 DRAWN BY
 CHECKED BY
 REVIEWED
 CLEARED

BASIC DATA

RECOMMENDED
 CONCURRED
 APPROVED

RECOMMENDED _____ DATE _____
 CONCURRED _____ DATE _____
 APPROVED _____ DATE _____

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE
 PLANNING DIVISION
 PREPARED BY
ROLAND E. SMITH
 NAME OF JOB
COFFEE SHOP BLDG. N. 1016
 LOCATION
BLUE RIDGE PARKWAY

PROJECT NO.
 SHEET NO. 1 OF 1
 DRAWN BY
 CHECKED BY

Appendix B:

Documentation Drawings


Sheet 1: Site Plan

Sheet 2: Basement & Foundation Plan

Sheet 3: Main-Level Floor Plan

Sheet 4: Roof Plan

Sheet 5: Detail Drawings



1 SITE PLAN
SCALE: 1/16" = 1'-0"



JOSEPH K. OPPERMANN - ARCHITECT, P.A.
WINSTON-SALEM, NORTH CAROLINA

BLUFFS COFFEE SHOP
DOUGHTON PARK - LAUREL SPRINGS, NORTH CAROLINA
UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, SOUTHEAST REGION

RECORDATION DATE:
06.06.2018

RECORDED BY:
JKO+JPA

SCALE:
1/16" = 1'-0"


HSR
APPENDIX B:
SHEET

RECORDATION
DATE:
04.17.2018


RECORDED BY:
JKO+JPA

SCALE:
3/32" = 1'-0"

HSR
APPENDIX B:
SHEET



1 BASEMENT / FOUNDATION PLAN
SCALE: 3/32" = 1'-0"




RECORDATION
DATE:
04.17.2018


RECORDED BY:
JKO+JPA


SCALE:
3/32" = 1'-0"

HSR
APPENDIX B:
SHEET




1 MAIN-LEVEL FLOOR PLAN
SCALE: 3/32" = 1'-0"





1 ROOF PLAN
SCALE: 3/32" = 1'-0"



JOSEPH K. OPPERMANN - ARCHITECT, P.A.
WINSTON-SALEM, NORTH CAROLINA

BLUFFS COFFEE SHOP
DOUGHTON PARK - LAUREL SPRINGS, NORTH CAROLINA
UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, SOUTHEAST REGION


RECORDATION
DATE:
04.17.2018

RECORDED BY:
JKO+JPA


SCALE:
3/32" = 1'-0"

HSR
APPENDIX B:
SHEET

4



1 WOOD GUTTER - SECTION
SCALE: 3" = 1'-0"



2 DECORATIVE WALL SPINDLES -
SECTION & ELEVATION
SCALE: 3" = 1'-0"



JOSEPH K. OPPERMANN - ARCHITECT, P.A.
WINSTON-SALEM, NORTH CAROLINA

BLUFFS COFFEE SHOP
DOUGHTON PARK - LAUREL SPRINGS, NORTH CAROLINA
UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, SOUTHEAST REGION

RECORDATION
DATE:
06.06.2018

RECORDED BY:
JKO+JPA

SCALE:
3" = 1'-0"

HSR
APPENDIX B:
SHEET