PHO503975

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES **INVENTORY -- NOMINATION FORM**

FOR NPS USE ONLY

SEP 1 5 1977

DATE ENTERED

MAR 2 9 1978

FOR FEDER	AL PROPERTIES			
		O COMPLETE NATIONA COMPLETE APPLICABL		
1 NAME		on (HS-4A, HS-4Al,		(-4D)
AND/OR COMMON		Cape Hatteras Lic		
2 LOCATION				
STREET & NUMBER On access road one	•	anction with N.C.12		
CITY, TOWN		·	CONGRESSIONAL DISTR	ICT
Buxton,		VICINITY OF	First	
STATE North Carolina		CODE 37	COUNTY Dare	CODE 055
3 CLASSIFICATION	ON			
CATEGORY O	WNERSHIP	STATUS	PRES	ENT USE
X_DISTRICT X_PUBUILDING(S)PRSTRUCTUREBOSITE PIOBJECTIN	BLIC IVATE	XOCCUPIED UNOCCUPIED WORK IN PROGRESS ACCESSIBLE XYES: RESTRICTED YES: UNRESTRICTED NO	AGRICULTURECOMMERCIALEDUCATIONALENTERTAINMENT X_GOVERNMENTINDUSTRIALMILITARY	XMUSEUM XPARK —PRIVATE RESIDENC
REGIONAL HEADQUARTERS: National Park Sestimates & NUMBER Route 1, Box 67	ervice, cape Hatt	<u> </u>	Office hose	
CITY, TOWN			30349 STATE	
Manteo, FIT ant	<u>a</u>	VICINITY OF GA		na 27 954
5 LOCATION OF COURTHOUSE, REGISTRY OF DEEDS, ETC.				
STREET & NUMBER	Dare County Cou	rthouse, Register	of Deeds	
Courthouse Buil	ldina			
CITY, TOWN			STATE	
Manteo,			North Caroli	na 27954
6 REPRESENTAT	ION IN EXISTI	NG SURVEYS		
DATE		FEDERALST	TATECOUNTYLOCAL	
DEPOSITORY FOR SURVEY RECORDS				
CITY, TOWN			STATE	



CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT __DETERIORATED

___UNALTERED

XORIGINAL SITE

__GOOD _X_{FAIR}

Builtin 1810

__RUINS
__UNEXPOSED

__MOVED DATE_____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Cape Hatteras Light Station consists of 10 acres of an L-shaped configuration of five structures bounded on the east by barrier dunes and the Atlantic Ocean, on the east by Buxton Woods, on the north by the Hatteras Naval Facility, and on the south by dunes and open beach. The original site consisted on 4 acres and then 48 acres by the mid-19th Century. The present boundaries are arbitrarily drawn based upon modern instrusions and a changing shoreline. The complex consists of the Cape Hatteras Lighthouse (HS-4A), brick oil house (HS-4Al), ruins of the Cape Hatteras Lighthouse (HS-4B), frame double keepers quarters (HS-4C), and brick principal keepers quarters (HS-4D).

Cape Hatteras Lighthouse (HS-4A) towers 208 feet from its base, making it the tallest lighthouse in the United States. The conical brick shaft is painted in a distinctive black and white striped spiral pattern. The shaft stands upon a floating foundation of cross laid layers of yellow pine timbers. Above the timbered courses rest, /fhe cut stone foundation laid in an octagonal pattern with granite groins. At the top of the shaft occurs an iron nicking with a wide corbel cornice, which supports a balustraded balcony. Above that, a second catwalk encircles the cupola which houses the light. The circular roof is crowned by metal spike atop a spherical finial.

Th shaft contains nine openings (seven windows and two doors). The lintels and sills are of stone. A spiral staircase of 268 steps winds from the base to the light which has a focal plane of 191 feet above mean high water. The staircase has seven semi-circular landings.

The present lighting device, installed in 1972, consists of a rotating beacon with two 1000 watt lamps, visible in clear weather for around 20 miles.

The tower has changed little over the years, but the light mechanism has changed several times. A fresent lens with oil lamps lighted the tower in 1870. To rotate the lens, a weight descended slowly form the top of the tower, engaging a series of gears which turned the beacon. In 1913, an incandescent oil vapor lamp replaced the old lamps. In 1934 electricity replaced the rotating power and an astronomic time switch turned the light on and off. A new lighting device was installed in 1950. Although the mechanism has changed, the light has remained white.

In 1870 the tower stood 1500 feet from the ocean. By 1935 erosion had progressed to the point where waves washed around the base of ten tower. The tower was abandoned and replaced with a skeleton steel tower a mile to the northwest. The erosion trend reversed in the late 1930's and erosion control work by the Civilian Conservation Corps and NPS permitted the return of the light to the lighthouse on January 23, 1950.

An iron picket fence built upon the base survives today.

The brick oil house (HS-4Al) stands 65 feet to the north of the lighthouse tower. Built in 1892 of red brick it is 15 feet 6 inches by 13 feet 6 inches in plan; with walls 8 feet 6 inches high; and a gable roof four feet high, covered by a turned beam metal sheathing. Originally intended to house oil drums for the light, it now houses an auxiliary generator for the beacon.

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW			
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
1600-1699	ARCHITECTURE	EDUCATION	MILITARY	XSOCIAL/HUMANITARIAN
1700-1799	ART	X_ENGINEERING	MUSIC	THEATER
X_1800-1899	X _COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	*TRANSPORTATION
<u>X</u> _1900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
		INVENTION		

Lighthouse Board,

SPECIFIC DATES

1803. 1854, 1870, 1871,1892 Henry Dearborn, Dexter Stetson

STATEMENT OF SIGNIFICANCE

Cape Hatteras Light Station contains the tallest brick lighthouse in America. light station was one of the first (conceived in 1794 and placed in operation in 1803, it was the first light station south of Cape Henry) and one of the most important links in the lighthouse chain. The Cape Hatteras Lighthouse is the primary navigational aid for mariners rounding the treacherous Diamond Shoals.

Cape Hateras Light Station stands on a spot of eastern North America most dreaded by sailors since the 16th Century when European ships began regularly coasting the Atlantic Seaboard. Clashing air and water currents causing frequently tempestuous waters and weather, extensive shoals, lack of landmarks on the low-lying, sandy Outer Banks, and other environmental factors all combine to make the seas off Cape Hatteras some of the most naturally hazardous in the world. Yet, paradoxically, some of these same factors (winds and currents) made the Carolina coast a major maritime tranportation route.

A warm offshore current, the Gulf Stream, flows north at about 4 knots and veers eastward north of Cape Hatteras. Spanish treasure fleets made good use of this current on their voyages to Spain. Southbound vessels followed an inshore counter current of colder water, the Virginia Coastal Drift. These currents became busy coastal highways, but at Cape Hatteras the Gulf Stream pinches down on the inshore current and forces southbound ships into a narrow passage around Diamond Shoals, shallow sand bars that jut more than 10 miles out from Cape Hatteras. Several hundred ships, trying to find their way around or through the shoals, have foundered near Cape Hatteras earning for the area its reputation as the "Graveyard of the Atlantic". The absence of natural landmarks along the Carolina coast added to the mariners' risks as they were drawn dangerously close to shore to get a bearing.

Recognizing the real/danger to coastal shipping, the Congress in 1797 authorized the construction of a permanent lighthouse at Cape Hatteras. On October 26, 1798, the Federal Government purchased 4 acres of land at Cape Hatteras from Christian Jennett, Thomas Farrow, and Joseph Farrow for a price of \$50.00. A problem arose over a proper contractor to build the lighthouse. Henry Dearborn, Congressman from Massachusetts, submitted the low bid for construction. Dearborn received a contract for \$38,450.00 to build both the Cape Hatteras Light Station and the Shell Castle Beacon in Ocracoke Inlet. He did not complete the Cape Hatteras light until October 1803.

Adam Gaskin was appointed first keeper of the Cape Hatteras Light on December 29, 1802, and received a yearly salary of \$333.00.

	1						
9	M	Α	IOR	RIRLIOGR	APHICAL	REFERENC	TES.
	***		101	DIDHIOOM			

Washington, D.C	., 1968.	ory or the	cape Hatte	eras Light Sta	tion", U.S.N.P.S.,
Holland, F. Ross,	Jr., "Keeper	s Dwelling	; Cape Hat	tteras Light S	tation", NPS Structur
Report, Part I,	Washington,	D.C., 196	58.		
Stick, David, "Qut	er banks or i	North Card	olina", Univ	ersity of N.C	. Press, 1958.
10 GEOGRAPHIC	CAL DATA				
ACREAGE OF NOMINATE	. 10			•	
UTM REFERENCES			Andreador .		,
A 1, 8 4 5,2 6	koo alla blo	aloco of	в 1 1 8	45,25,8,0	13 9 9019,6,01
ZONE EASTING	<u> NORTHII</u>	13.0.0.	ZONE R T C	EASTING	NORTHING
C 718 115,21		1 21910	D		
VERBAL BOUNDARY	DESCRIPTION TH	ne station	consists	of an I-chanod	zone bounded on the
east by barrier	dunes and the	Atlantic	Ocean. on	the north by t	the Hatteras Naval
Facility, on the	west by Buxt	ton Woods,	and on the	south by dune	es and open beach.
The zone lies on	e mile southe	east of th	e junction	of the park ac	ccess road with
North Carolina S	tate Route 12	2 in Buxto	n, North Ca	rolina.	w ^r
LIST ALL STATE	S AND COUNTIES	FOR PROPER	TIES OVERI APPI	NG STATE OR COUN	TY ROUNDARIES
	10,71110 0001111120		TEO OVERLEAT T		TO BOOKDAMES
STATE		CODE	COUNTY		CODE
CTATE		CODE	COLINITY		
STATE	•	CODE	COUNTY	•	CODE
TEODA DDEDA	DED DV				
11 FORM PREPA	KED B I			,	
Ronald G. Warfie	ld District	Intorprot	0.76	ï	•
ORGANIZATION	id, District	THEFT	er	DATE	
National Park Ser	rvice/Cape Ha	tteras Na	tional Seas	hore 03/1	0/77
Route 1, Box 675				TELEPHO	ONE
CITY OR TOWN				STATE	
Manteo,				North Carolin	
12 CEPTIEICATI	ON OF NO	ATRI À TRI) N.T.		
12 CERTIFICATI	STATE HISTORIC	VIIIVA III	JN ON OFFICER RE	COMMENDATION	A
,	YES	NO.		NONE AM	:['
				NONE TANN C	/ //
				STATE HISTORIC PRES	
					er, certifying that the State
evaluate its significance. T					State Review Board and to
FEDERAL REPRESENTAT		Aluk	alles	A_StateLocal.	
		1		DATE	SEP 6 1977
mer populy A	·		· ·		
The control of the co	ssistant Se	cretary		DATE	OCI 0 1011
OR NPS USE ONLY			IN THE NATION		3L1 0 1971
OR NPS USE ONLY I HEREBY CERTIFY THA			IN THE NATION		3L1 0 1377
OR NPS USE ONLY			IN THE NATION	AL REGISTER DATE	32978
OR NPS USE ONLY			IN THE NATION	AL REGISTER	72978

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS U	SE ONLY				
RECEIVED	SEP	1519	377		
	14				
DATE ENTE	RED	,	88 NO 2	9 1978	\

CONTINUATION SHEET

ITEM NUMBER

PAGE 2

Ruins of the original 1803 Cape Hatteras Lighthouse (HS-4B) sit atop a sand hill 600 feet south of the present tower. The ruins consists of a semi-circular remainder of masonry wall about four feet high. This original tower was blown up in 1870 upon completion of the new tower.

The tower constructed in 1799-1803 by Henry Dearborn was stone octagonal and brick structure 90 feet high plus a 12 foot lantern. In 1854 a brick addition realised the tower so that the focal plane of the light was 150 feet above sea level. A first order Fresnel lens was installed in the lantern. The tower was whitewashed for the first 70 feet and the remainder painted red. The light was removed by the Confederates in 1861 and replaced in 1862 by Union forces. A new Fresnel lens was installed in 1863. Erosion and time plagued the tower until Congress authorized its replacement in 1867.

A Frame Double Keepers Quarters (HS-4C) was rected in 1854. The original structure rested upon masonry piers and was of frame construction, whitewashed. A one story porch faced the south side. Two brick chimneys pierced the wood shingled gable roof. In 1892 one of the kitchens forming the wings of the dwelling was moved to the rear and it was adapted for use of two families. The main building was extended on its front and back lines about 16 feet east, the enclosure constituted an addition 16x20 feet in plane and two stories in height. Thus the structure housed three families. In 1954 the structure's interior was converted for use as a museum with exhibits and office and modern lavatory facilities replacing the old rear kitchen. German siding and metal and lexan storm windows are the only exterior changes to the 1892 structure. Brick cisterns remain at each end of the building. Five outbuildings present in 1893 do not survive. They were: a summer kitchen; three store houses; and a privy. All were frame construction on wood foundations. Two store houses had canvas roofs, the others had shingle roofs. A board fence enclosed the dwelling in 1893, but it does not survive. A brick walkway ran from the porch to the light tower.

A short distance east of the Double Keepers Quarters the Brick Principal Keepers Quarters was constructed in 1871. Originally the structure was a story and a half brick structure with a one story kitchen ell to the east. The kitchen opened off the living room located at the south end of the structure. A bedroom on the north end was separated from the living room by a central stair hall running east and west. Two bedrooms were located on the second floor.

Water from the roof was collected in a brick cistern on the north end of the structure. There were two wood porches, one at the south entrance door and the other off the stair hall on the east.

The structure has been altered and enlarged to function as a guest house. A small one story frame extension was added to the east end of the kitchen. A two stroy frame addition was built in the ell of the old structure to provide a larger living room on the first floor and a large bedroom on the second floor. To the east of this addition a one story

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY

RECEIVED SEP 1 5 1977

DATE ENTERED

MAR 2 9 1978

CONTINUATION SHEET

ITEM NUMBER

PAGE

3

porch was constructed to line up with the kitchen addition. An exterior stairway leads to a landing and a doorway cut in the wall leading into the interior main stair. The walls and ceilings have been lined with beaded pine panelling so little of the original interior can be seen. The roof is covered by wood shingles. The entire exterior is painted white. The four outbuildings present in 1893 were of wood, two were store houses, one a summer kitchen and a privy. They do not survive. The structure and its outbuildings were within the eastern half of a half acre compound surrounded by a board fence (now gone). A brick walk runs from the dwelling to the light tower.

Currently, a large visitor center parking lot intrudes on the old lightstation. Originally this area was sandy, flat, periodically flooded. The old quarters area was surrounded by a white wooden fence, now gone. While the station was originally bordered on the north by woods, dunes and open beach, today a naval facility intrudes upon the scene. Where now the station is separated from the ocean by barrier dunes built in the 1930's, the original station sat on a gently sloping, wide beach. The second floor of the Double Keepers Quarters (Museum of the Sea) houses offices for the District Ranger and Maintenance personnel.

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY
BECEIVED SEP 1 5 1977

DATE ENTERED

8

MAR 2 9 1978

CONTINUATION SHEET

ITEM NUMBER

PAGE 2


From the start, a major problem was illumination; the small lamp fueled by sperm whale oil and porpoise oil did not penetrate the darkness beyond the shoals. Storms and flocks of geese shattered the windows and broke the lamps, putting the light out for days at a time. Complaints were numerous and vocal. In effect, complaints were saying that what should have been the best light on the coast was indeed the worst.

Problems of poor lighting and erosion continued. Finally the Lighthouse Board made a decided improvement in the conduct of all U.S. lighthouse operations. Their first corrections included raising the tower from 90 to 150 feet and installing a new lighting device—a first order revolving Fresnel lens. The improvements made Cape Hatteras light one of the most dependable on the coast.

The Civil War caused the light to be extinguished in 1861. Confederate forces tried to destroy the lighthouse to deprive Federal vessels of the beacon. Union forces managed to save the tower, but retreating Confederates took the Fresnel lens with them. The light was re-exhibited around June 1, 1862, but the tower needed extensive repairs. Congress appropriated \$75,000 to reconstruct the Cape Hatteras Lighthouse in 1867. The new tower was constructed in 1869-70 by the Lighthouse Board with Dexter Stetson as foreman. The new tower was erected on a site 600 feet north of the original because of erosion threats at the old site. The land for the station, acquired in 1828, from Pharoah Farrow, consisted of a parcel of 40 acres more or less for which a sum of \$200.00 was paid. The new light was exhibited for the first time on December 16, 1870. In 1873 the Lighthouse Board recognized that the lighthouse should be a practical daymark, so it authorized the spiral black and white striping, which turned the structure into the most striking structure on the Outer Banks.

The National Park Service acquired ownership of the Light Station when it was abandoned in 1935. In 1950 when the structure was again found safe for use, new lighting equipment was installed. The U.S. Coast Guard continues to operate the lighting equipment while the National Park Service keeps the tower open to the public. Time has eroded the iron balcony so it is now inaccessible.

The Museum of the Sea, located in the old Double Keepers Quarters, elaborates on the Cape Hatteras story: Cape Hatteras Light Station has played a pivotal role in the development of aids to navigation on one of the most dreaded shores of the Atlantic Coast. The lighthouse stands as a symbol of the humanitarian efforts of a young nation, and still serves as a functional warning device.



United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Secti	tion number Page _				
	Cape Hatteras Light Sta	ation, Dare Cou	unty. NORTH	CAROLINA	
	PROPOSED MOVE APPROVED				
	Mo M. M. M. L. C. Keeper of the Nat	onal Register		6/23/98 Date	

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number Page	
Cape Hatteras Light Station	Dare County, NORTH CAROLINA
PROPOSED MOVE APPROVAL	Keeper any Federman 1/10/90