			# <u>CH 202</u>		
State of North					
Division of Archives and History			Chatham	COUNTY	
NDIVIDUAL	PROPERTY FORM	FOR	Merry Oa	ks QUAD	
X MUL	TIPLE RESOURCE OR	THEMAT	TIC NOMINATION		
1 NAME	n til til men men han kvir men til med protesser, styllet som til fregjeringsgad men men kvir fre til seg en men som				
HISTORIC		,			
Ebenezer Me AND/OR COMMON	thodist Church				
2 LOCATION					
STREET & NUMBER	West side SR 1008 near New Hope Tow	, .5 miles nort inship, near Bel	15_NOT FOR PUBLICATION		
CITY, TOWN	. 11 - V	VICINITY OF	congressional distr Fourth	RICT	
STATE BO	ells <u>X</u>	CODE	COUNTY	CODE	
North Caroli		037	Chatham	037	
3 CLASSIFIC	ATION				
CATEGORY	OWNERSHIP	STATUS	PRES	ENT USE	
DISTRICT	PUBLIC X_PRIVATE	XOCCUPIED	AGRICULTURE	MUSEUM	
_XBUILDING(S) STRUCTURE	#PRIVATE BOTH	UNOCCUPIEDWORK IN PROGRESS	COMMERCIAL EDUCATIONAL	PARKPRIVATE RESIDENCE	
_SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	37	
OBJECT	IN PROCESS	YES RESTRICTED	GOVERNMENT	SCIENTIFIC	
	n/ageing considered	X YES UNRESTRICTED	INDUSTRIAL MILITARY	TRANSPORTATIONOTHER	
4 OWNER OF	PROPERTY				
NAME					
Ebenezer M	ethodist Church	c/o Mrs. Ros	coe Wilson		
STREET & NUMBER	202				
Rt. 2, Box	203		STATE		
Apex		VICINITY OF	N. C.		
5 LOCATION	OF LEGAL DESCR	IPTION			
COURTHOUSE. REGISTRY OF DEEDS, E	TTC Chatham County	Courthouse			
STREET & NUMBER					
city.town Pitts	city.town Pittsboro,		STATE N. C.		
6 FORM PREI				minimiero contrate estantan men ^o • elempinggen procuremen-	
NAME/TITLE Ray Manieri			July 1, 1983		
ORGANIZATION			DATE DATE		
Urban Reseat	rch Associates	anna Plan aith i ann a tha ann an agus agus an thiú taire ann an m <u>heann agus agus a</u> gus a	TELEPHONE		
1301 Cornwa	llis Drive		ICLEFHONE		
CITY OR TOWN	<u> </u>		STATE		
Greensboro			N.C.		

CONDITION

CHECK ONE

CHECK ONE

XEXCELLENT

__DETERIORATED

__UNALTERED

_ORIGINAL SITE

__GOOD __FAIR __RUINS
__UNEXPOSED

MOVED DATE 1973

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Ebenezer Methodist Church is a simple rural Gothic Revival chapel probably constructed during the late nineteenth century. It is a one-story, one by four bay weatherboard structure set in a small grove of pine trees on S.R. 1008. The church has a steeply pitched gable roof of tin and lancet windows with modest tracery. The church's cemetery is located just to the north of the chapel.

Its most dominant feature is a single-stage entrance tower which projects from its gable front. This tower features a double-leaf entrance topped by a Gothic arch containing an interesting quatrefoil design. A small pent roof shelters the entrance. Lancet windows with Gothic hood molds appear on each side of the tower at the first story. Louvered lancet window openings occur on each side at a higher level. A steep, bellcast, pyramid roof caps the steeple. This roof contains dormered vents, decorated with louvers and trefoil designs. A heavy, turned, wooden finial sits atop the pyramid roof. Large lancet windows illuminate the chapel's remaining sides. A small, gabled, weatherboard addition extends from the Chapel's rear and a modern cement block ell extends northward from the chapel's rear.

The interior of the Ebenezer Methodist Church maintains much of its original character. Original multi-paneled doors survive, as does the original wainscoting and chair rail. All interior doors and windows have plain surrounds. The interior walls have interesting horizontal, grooved paneling. Seating for the church's congregation is provided by heavy wooden pews. A heavy, paneled wooden railing creates a chancel area by separating the pulpit, piano, and choir pews from the rest of the congregation.

OCAL

4 - 4 - 5	COMMUNICATIONS:	INDUSTRY ;	POLITICS/GOVERNMENT	_OTHER (SPECIFY)				
	COMMUNICATIONS	INDUSTRY ;	POLITICS/GOVERNMENT	_OTHER (SPECIFY)				
1900-								
_X1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION				
_1700-1799	ART	ENGINEERING	MUSIC	_THEATER				
1600-1699	XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN				
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE				
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE				
PREHISTORIC	ARCHEULUGY-PREHISTORIC	_COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	X RELIGION				
PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW							

STATEMENT OF SIGNIFICANCE

The Ebenezer Methodist Church, one of the oldest Methodist congregations in the New Hope Creek area, was established in 1827. It has occupied several different structures since its establishment. The present church building dates from about 1890 and allegedly incorporates part of the previous church building constructed in 1867. As a result of the construction of the B. Everett Jordan Dam, the church was moved two miles north of its original site to its present location in the late 1970s. The present church structure is particularly interesting as a well-preserved example of Gothic Revival motifs on a simple frame chapel. In this respect it is unusual for Chatham County, where most rural chapels do not reach its level of expression of the Gothic Revival style.

and the second of the second o

1. The state of th

CRITERIA ASSESSMENT

A. Associated with the development of Methodism in North Carolina during the late nineteenth century.

1

en en la región de la companya de l Companya de la compa La companya de la co

C. Embodies the distinctive characteristics of vernacular Gothic Revival, ecclesiastical architecture, as that style developed in the rural areas of central North Carolina during the late nineteenth century.

Although the Ebenezer Methodist Church was established as early as 1827, the present church structure dates from about 1890. The church's worship services were first held in a small log chapel, which was listed in the National Register of Historic Places. This structure has now fallen into ruin.

The original log church was used by both black and white members of the congregation for many years, but because of the growth of the congregation and the desire for more modern facilities, other church buildings were constructed. The second church structure, located across SR 1008 from the previous site of the present church structure, was constructed between 1830 and 1840 and given to the congregation's black members, which left benezer Church to establish their own congregation after the Civil War.

Although the establishment of the Ebenezer African Methodist Episcopal Church, reduced the membership of Ebenezer Church by almost one-half, a new church building was constructed in 1867. Church tradition states that this third structure was used for several decades and then incorporated into the construction of the present chapel about 1890.

It is not known why a new structure was built about 1890, but it may have been necessitated by the growth of the congregation or the desire for more modern facilities as the rural congregation became more prosperous. Church oral tradition claims that local craftsmen were used to create the Gothic Revival motif of this small frame chapel. Timber for construction of the new building, which incorporated the 1867 chapel, was cut from nearby forests and floated down local rivers to the site of the church.

Ebenezer Methodist Church has experienced several physical changes during the twentieth century. A rear addition, forming two Synday School rooms was added in 1914 and a cement block ell added in 1948. During the late 1970s, construction of the B. Everett Jordan Dam threatened the church and it was moved to its present location on SR 1008 two miles north of its former site. After its relocation, a new masonry block addition was added to the church and a frame and block shelter constructed to its rear. The church cemetery was also relocated to the new site.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Adams, W. H., et al. Archaeological Investigations of Ebenezer Log Church and Vicinity. Sumbitted to the Army Corps of engineers, August 15, 1979.

Clegg, Mrs. Bynum. Interviewed February 14, 1983. Mrs. Clegg is Church Historian.

continued on attached sheet ...

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY Approx. 1 acre

A[1,7] [6]8,0] 3, 1, 0	3,915,513,1,0	в		
ZONE EASTING	NORTHING	ZONE	EASTING	NORTHING
		D		

VERBAL BOUNDARY DESCRIPTION

The nominated property is located on the west side of SR 1008, .5 of a mile north of its junction with SR 1975 and consists of the area upon which the church is located. See sketch map.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number 8

Page

NOTES

- 1. "Ebenezer Church, County Landmark", The Pittsboro Herald, August 9, 1972, p. 2.
- 2. Mrs. Bynum Clegg, Interviewed February 14, 1983. Mrs. Clegg is church historian.
- 3. W. H. Adams, et al, <u>Archaeological Investigations of Ebenezer Log Church and Vicinity</u>, submitted to the United States Army Corps of Engineers, August 15, 1979.
- 4. "Ebenezer Church County Landmark", The Pittsboro Herald, August 9, 1972, p. 2.
- 5. Ibid.
- 6. Ibid.
- 7. "The History of Ebenezer Church", Pittsboro Herald, January 31, 1973 p. 10.
- 8. Ibid.
- 9. Ibid.
- 10. Mrs. Bynum Clegg, February 14, 1983.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

Continuation sheet

Item number 9

Page

"Ebenezer Church, County Landmark." Pittsboro Herald, August 9, 1972.

Hadley, Wade H. Jr., et al. Chatham County, 1771-1971. Durham: Moore Printing Company, 1971.

"The History of Ebenezer Methodist Church." Pittsboro Herald, January 31, 1973, p. 10.





