Historic Architectural Resources Survey Report

Phase II (Abridged)

Oak Street Extension from Young Street to US 221A (Broadway Street) Forest City, Rutherford County, North Carolina

TIP No. U-2711B State Project No. 8.2890403 Federal Aid Project No. STP-1310(2)

Prepared for:

Project Development and Environmental Analysis Branch North Carolina Department of Transportation P. O. Box 25201 Raleigh, North Carolina 27611

Prepared by:

Scott C. Owen Architectural Historian 7200 Almeda Rd. # 915 Houston, Texas 77054

August 1999

Historic Architectural Resources Survey Report

Phase II (Abridged)

Oak Street Extension from Young Street to US 221A (Broadway Street) Forest City, Rutherford County, North Carolina

TIP No. U-2711B State Project No. 8.2890403 Federal Aid Project No. STP-1310(2)

Prepared for:

Project Development and Environmental Analysis Branch North Carolina Department of Transportation P. O. Box 25201 Raleigh, North Carolina 27611

Prepared by:

Scott C. Owen Architectural Historian 7200 Almeda Rd. # 915 Houston, Texas 77054

Principa Investigator Scott C. Owen, Architectural Historian

Supervisor, Historic Architectural Resources Section North Carolina Department of Transportation

10 m)] Date

Date

Management Summary

The North Carolina Department of Transportation (NCDOT) proposes to extend Oak Street in Forest City on new location from Young Street to US 221A (Broadway Street). NCDOT plans to construct the Oak Street extension as either a four-lane facility with a sixteen-foot grassed median, or a five-lane, sixty-four-foot curb and gutter facility. The length of this project is approximately 2.22 miles. Additional right of way will be required.

In July, 1999, NCDOT hired Scott C. Owen as principal investigator to conduct and prepare a Phase II (Abridged) survey and report of historic architectural resources for the subject project. The principal investigator conducted this survey to determine the area of potential effects (APE), and to identify and evaluate all properties over fifty years of age within the APE according to the Criteria of Evaluation for the National Register of Historic Places. He consulted the Rutherford County survey maps and files at the State Historic Preservation Offices (SHPO) in Raleigh and Asheville, as well as the listings of the National Register of Historic Places and the North Carolina Study List, to find information on historic properties in the project area. Based on information found in these files, as well as the results of a field survey, the principal investigator established a boundary for the APE to include all properties roughly within 300-1000 feet of the proposed Oak Street extension. The APE is bounded on the north and east by the Norfolk and Southern railroad tracks, and on the west by Church Street. Thick stands of trees line the railroad tracks. These trees, along with the raised berm on which the tracks lay on the east side of Broadway Street, will shield properties outside the APE from construction of the extension, as well as the effects of the completed roadway. The southern APE boundary parallels the proposed extension through an adjacent neighborhood to the south, and includes all properties with approximately 750-1000 feet of the extension. The principal investigator conducted an intensive survey by car and on foot on July 21, 1999, covering one hundred percent of the APE, to identify those properties over fifty years of age that appeared to be eligible for the National Register.

The principal investigator identified fifty-nine (59) properties in this survey. No properties are listed on the National Register or the North Carolina Study List. In a meeting on August 6, 1999, NCDOT and SHPO concurred with the principal investigator's opinion that none of the properties are eligible for the National Register, and that none are worthy of further evaluation. An inventory of these properties and photographs of each follow in Appendix A.

Properties Not Eligible for the National Register and Not Worthy of Further Evaluation

1.	New Bethel Independent Church	VIII-8
2.	House	VIII-9
3.	House	VIII-9
4.	House	VIII-10
5.	House	VIII-10
6.	House	VIII-11
7.	House	VIII-11
8.	House	VIII-12

9.	House	VIII-12
10		VIII-13
11		VIII-13
12		VIII-14
13		VIII-14
14		VIII-15
15		VIII-15
16		VIII-16
17		VIII-16
18		VIII-17
19		VIII-17
20		VIII-18
21		VIII-18
22		VIII-19
23.		VIII-19
24.		VIII-20
25.		VIII-20
26.		VIII-21
27.		VIII-21
28.		VIII-22
29.		VIII-22
30.		VIII-23
31.		VIII-23
32.		VIII-24
33.		VIII-24
34.		VIII-25
35.		VIII-25
36.		VIII-26
37.	House	VIII-26
38.		VIII-27
39.	House	VIII-27
40.	House	VIII-28
41.	House	VIII-28
42.	House	VIII-29
43.	House	VIII-29
44.	House	VIII-30
45.	House	VIII-30
46.	House	VIII-31
47.	House	VIII-31
48.	House	VIII-32
49.	House	VIII-32
50.	House	VIII-33
51.	House	VIII-33
52.		VIII-34
53.	House	VIII-34

54.	House	VIII-35
55.	House	VIII-35
56.	House	VIII-36
57.	ABC Seamless Siding and Gutters	VIII-36
58.	House	VIII-37
59.	Little Red School	VIII-37

Table of Contents

I.	Signatory Page	I-1
п.	Management Summary	П-1
Ш.	Table of Contents	Ш-1
IV.	List of Maps, Plans, and Photographs	IV-1
v.	Purpose of Survey and Report	V-1
VI.	Methodology	VI-1
VII.	Summary Results and Findings	VII-1
	A. Properties Under Fifty Years of Age	VII-1
	B. List of Properties on the National Register	VII-1
	C. List of Properties Eligible for the National Register	VII-1
	D. List of Properties Not Eligible for the National Register and Not Worthy of Further Evaluation	VII-1
VIII.	Appendix A – Concurrence Letter, Inventory, and Photographs of Properties Not Eligible for the National Register and Not Worthy of Further Evaluation (August 6, 1999)	VIII-1

List of Maps, Plans, and Photographs

Maps

Fig. 1	Project Area Map	V-2
Fig. 2	Area of Potential Effects Map	V-3

Photographs

1.	New Bethel Independent Church	VIII-8
1.	New Bethel Independent Church (Parsonage)	VIII-8
2.	House	VIII-9
3.	House	VIII-9
4.	House	VIII-10
5.	House	VIII-10
6.	House	VIII-11
7.	House	VIII-11
8.	House	VIII-12
9.	House	VIII-12
10.	House	VIII-13
11.	House	VIII-13
12.	House	VIII-14
13.	House	VIII-14
14.	House	VIII-15
15.	House	VIII-15
16.	House	VIII-16
17.	House	VIII-16
18.	House	VIII-17
19.	House	VIII-17
20.	House	VIII-18
21.	House	VIII-18
22.	House	VIII-19
23.	House	VIII-19
24.	House	VIII-20
25.	House	VIII-20
26.	House	VIII-21
27.	House	VIII-21
28.	House	VIII-22
29.	House	VIII-22
30.	Swafford Auto Sales	VIII-23
31.	House	VIII-23
32.	House	VIII-24
33.	House	VIII-24
34.	House	VIII-25
35.	House	VIII-25

36.	House	VIII-26
37.	House	VIII-26
38.	Store	VIII-27
39.	House	VIII-27
40.	House	VIII-28
41.	House	VIII-28
42.	House	VIII-29
43.	House	VIII-29
44.	House	VIII-30
45.	House	VIII-30
46.	House	VIII-31
47.	House	VIII-31
48.	House	VIII-32
49.	House	VIII-32
50.	House	VIII-33
51.	House	VIII-33
52.	House	VIII-34
53.	House	VIII-34
54.	House	VIII-35
55.	House	VIII-35
56.	House	VIII-36
57.	ABC Seamless Siding and Gutters	VIII-36
58.	House	VIII-37
59.	Little Red School	VIII-37

Purpose of Survey and Report

This survey was conducted and report prepared in order to identify historic architectural resources located within the APE as part of the environmental studies conducted by NCDOT and documented by an Environmental Assessment (EA). This report is prepared as a technical addendum to the EA and as part of the documentation of compliance with the National Environmental Policy Act (NEPA) and the National Historic Preservation Act of 1966, as amended. This report is on file at NCDOT and is available for review by the general public. Section 106 of the National Historic Preservation Act of 1966, as amended, 16 U.S.C. § 470f, requires Federal agencies to take into account the effect of their undertakings on properties included in or eligible for inclusion in the National Register of Historic Places and to afford the Advisory Council on Historic Preservation a reasonable opportunity to comment on such undertakings.




Fig. 1 Project Area Map Approximate Scale: 1" = 1800 Feet




Fig. 2 Area of Potential Effects Map Approximate Scale: 1" = 525 Feet

Methodology

This Phase II (Abridged) survey was conducted and report compiled by the principal investigator in accordance with the provisions of FHWA Technical Advisory T 6640.8A (Guidance for Preparing and Processing Environmental and Section 4(f) Documents); the Secretary of the Interior's Standards and Guidelines for Archaeological and Historic Preservation (48 FR 44716); 36 CFR Part 800; 36 CFR Part 60; and Phase II (Abridged) Survey Procedures for Historic Architectural Resources by NCDOT dated June 15, 1994, as amended. This survey report meets the guidelines of NCDOT and the National Park Service.

The principal investigator conducted a Phase II (Abridged) survey with the following goals: 1) to determine the APE, defined as the geographic area or areas within which a project may cause changes in the character or use of historic properties, if any such properties exist; 2) to identify all significant historic architectural resources within the APE; and 3) to evaluate these resources according to the National Register of Historic Places criteria.

The survey methodology consisted of a field survey and historical background research of the project area. The principal investigator conducted the field survey by car and on foot. He photographed, investigated, and evaluated all structures over fifty years of age in the APE, and keyed all of those structures to U.S.G.S. quadrangle maps.

A search of SHPO's survey files for the project area showed that some properties in the vicinity of the APE have been previously surveyed. However, the one property that had been surveyed in the APE no longer stands. No properties in the APE are listed on the National Register or the North Carolina Study List. Kim Merkel conducted a comprehensive architectural survey of Rutherford County in 1979, and published her findings in <u>The Historic Architecture of Rutherford County</u> (1983).

Summary Results and Findings

Properties Under Fifty Years of Age

Criterion Consideration G, for properties that have achieved significance within the last fifty years, states that properties less than fifty years of age may be listed in the National Register only if they are of exceptional importance or if they are integral parts of districts eligible for the National Register. There are no properties in the APE that qualify for the National Register under Criterion Consideration G.

List of Properties on the National Register

none

List of Properties Eligible for the National Register

none

List of Properties Not Eligible for the National Register and Not Worthy of Further Evaluation

- 1. New Bethel Independent Church
- 2. House
- 3. House
- 4. House
- 5. House
- 6. House
- 7. House
- 8. House
- 9. House
- 10. House
- 11. House
- 12. House
- 13. House
- 14. House
- 15. House
- 16. House
- 17. House
- 18. House
- 19. House
- 20. House
- 21. House
- 22. House
- 23. House
- 24. House

26. House

27. House

28. House

29. House

30. Swafford Auto Sales

31. House

32. House

33. House

34. House

35. House

36. House

37. House

38. Store

39. House

40. House

41. House

42. House

43. House

44. House

45. House

46. House

47. House

48. House

49. House

50. House

51. House

52. House

53. House

54. House

55. House

56. House

57. ABC Seamless Siding and Gutters

58. House

59. Little Red School

Appendix A

Concurrence Letter, Inventory, and Photographs of Properties Not Eligible for the National Register and Not Worthy of Further Evaluation (August 6, 1999)

TIP # U.2711 B Federal Aid # STP-1310(2) County RUtherford

I

CONCURRENCE FORM FOR

PROPERTIES NOT ELIGIBLE FOR THE NATIONAL REGISTER OF HISTORIC PLACES

Cons	wchion of Oak St. extension on Youngst. is US ZZIA, Forest City	new location
on Au	Q. 6, 1999, representatives of the	
	North Carolina Department of Transportation (NCDOT) Federal Highway Administration (FHwA) North Carolina State Historic Preservation Office (SHPO) Other	
reviewed	the subject project at	
	A scoping meeting Historic architectural resources photograph review session/cons Other	ultation.
All partie	s present agreed	
	there are no properties over fifty years old within the project's	area of potential effect.
	there are no properties less than fifty years old which are consideration G within the project's area of potential effect.	lered to meet Criterion
K	there are properties over fifty years old (list attached) within the but based on the historical information available and the photog identified as $\frac{Properhies}{1-59}$ considered not eligible for the National Register and no further	raphs of each property, propertie
	there are no National Register-listed properties within the project	et's area of potential effect.
Signed:		
Ma	uppetun	Aug 6 1999
,	ative) NCDDT	J D'ate
FHwA, fo	r the Division Administrator, or other Federal Agency	Date
Represent	1 f. Mat Au	9.6, 1999
in the second	······	i Date
state Histo	oric Preservation Officer	Date

If a survey report is prepared, a final copy of this form and the attached list will be included.

Inventory of Identified Properties Phase II (Intensive) Survey of Historic Architectural Resources for Oak Street Extension, from Young Street to US 221A (Broadway Street), Forest City Rutherford County, North Carolina TIP No. U-2711B July 26, 1999

Properties Listed on the National Register

none

Properties to be Evaluated in Final Report

none

Properties Not Worthy of Further Evaluation

- New Bethel Independent Church Early-twentieth-century, brick-veneered church. Tower covered in artificial siding. Modern wing, with same brick veneer, added before 1979. Interior has sheetrock walls and beaded board, tongue-and-groove ceiling. Church accompanied by brick-veneered parsonage and garage, and concrete block recreation building. Lacks integrity and architectural significance.
- 2. House

Pyramidal-roof cottage, with German siding and 6/1 windows. Lacks historical or architectural significance.

- 3. House
 - Gable front house. Lacks historical or architectural significance.
- House Gable front house. Lacks historical or architectural significance.
- 5. House

Gable front house. Lacks historical or architectural significance.

6. House

Gable front house. Lacks historical or architectural significance.

7. House

Side gable house with engaged porch. Artificial siding. Lacks historical or architectural significance.

8. House

Cross gable house. Lacks historical or architectural significance.

9. House

Side gable house with screened engaged porch and rear ell. Lacks historical or architectural significance.

Cross gable house. Lacks historical or architectural significance.

11. House

Hipped-roof, brick house. Lacks historical or architectural significance.

12. House

Cross gable house with asphalt shingle siding. Lacks historical or architectural significance.

13. House

Side gable frame house. Lacks historical or architectural significance.

14. House

Side gable bungalow with engaged porch and knee brackets in eaves. Lacks historical or architectural significance.

15. House

Side gable frame house with aluminum siding. Lacks historical or architectural significance.

16. House

Side gable house. Lacks historical or architectural significance.

17. House

Side gable house with rear ell. Sheathed in plywood siding, which covers all doors and windows. Lacks integrity, as well as historical or architectural significance.

18. House

Cross gable frame house with attached porch and shed addition on side. Lacks historical or architectural significance.

19. House

Side gable frame house with attached porch and rear ell. Lacks historical or architectural significance.

20. House

Gable front bungalow with engaged porch. Lacks historical or architectural significance.

21. House

Side gable house with projecting pedimented porch and rear ell. Lacks historical or architectural significance.

22. House

Side gable house with center pediment gable. Attached porch, rear ell, and shingle siding in end gables. Lacks historical or architectural significance.

23. House

Side gable brick house with center gable, rear ell, and pedimented porch extending to one side. Lacks historical or architectural significance.

Side gable house with artificial siding. Lacks historical or architectural significance.

(panishi sub-inter piper and pining third, period and provided and the property of the prop

25. House

Side gable house with attached porch and rear ell. Lacks historical or architectural significance.

26. House

Side gable house with attached porch and rear ell. Lacks historical or architectural significance.

27. House

Shed roof house attached to gable front garage. Lacks historical or architectural significance.

28. House

Side gable house. Lacks historical or architectural significance.

29. House

Side gable house. Lacks historical or architectural significance.

30. Swafford Auto Sales

Clipped gable, brick building with twin dormers overlooking frame addition in front. Lacks integrity, as well as historical or architectural significance.

31. House

Cross gable house with mix of frame and artificial siding. Lacks historical or architectural significance.

32. House

Side gable brick house with gable addition and engaged porch at front. Lacks historical or architectural significance.

33. House

Side gable house with gable extension at front. Covered in artificial siding. Lacks historical or architectural significance.

34. House

Ranch-style duplex with hipped roof. Lacks historical or architectural significance.

35. House

Gable front bungalow with exposed rafters in eaves. Lacks historical or architectural significance.

36. House

Side gable house with projecting gable in front. Covered in artificial siding. Lacks historical or architectural significance.

37. House

Gable front house. Lacks historical or architectural significance.

38. Store

One-room, gable front, frame building with attached porch. Lacks historical or architectural significance.

Pyramidal roof house with artificial siding. Lacks historical or architectural significance.

40. House

Side gable house with small porch overhang. Lacks historical or architectural significance.

41. House

Side gable house with attached porch. Lacks historical or architectural significance.

42. House

Cross gable house with attached porch. Lacks historical or architectural significance.

43. House

Side gable house with pedimented porch. Covered in artificial siding. Lacks historical or architectural significance.

44. House

Gable front bungalow with artificial siding. Lacks historical or architectural significance.

45. House

Gable front bungalow with artificial siding. Lacks historical or architectural significance.

46. House

Gable front house with gable addition to side. Lacks historical or architectural significance.

47. House

Two-story gable front house with artificial siding. Lacks historical or architectural significance.

48. House

Side gable house with front gable addition and engaged porch. Lacks historical or architectural significance.

49. House

Gable front house with attached porch and artificial siding. Lacks historical or architectural significance.

50. House

Gable front house with attached porch. Lacks historical or architectural significance.

51. House

Cross gable bungalow with engaged porch on two sides. Lacks historical or architectural significance.

52. House

Gable front house with artificial siding. Lacks historical or architectural significance.

53. House

Side gable house with German siding. Lacks historical or architectural significance.

Side gable house with artificial siding. Lacks historical or architectural significance.

55. House

Gable front bungalow with artificial siding. Lacks historical or architectural significance.

56. House

Cross gable frame house with rear ell and shingled gables. Some original 2/2 windows survive; the rest are modern 1/1 replacements. Modern front door with side lights. Lacks historical or architectural significance.

57. ABC Seamless Siding and Gutters

Side gable bungalow with knee brackets in eaves, an engaged porch, and stone veneer porch columns. Lacks historical or architectural significance.

58. House

Side gable bungalow with shingled exterior and knee brackets in eaves. Original engaged porch now enclosed with modern storm windows. Lacks historical or architectural significance.

59. Little Red School

Hipped roof house with twin cross gables on front and attached porch. Projecting cross gable on one side, and large wing addition on the other. Lacks integrity, as well as historical or architectural significance.



1. New Bethel Independent Church




1. New Bethel Independent Church (Parsonage)



































16. House






























30. Swafford Auto Sales



















38. Store









































57. ABC Seamless Siding and Gutters





59. Little Red School